



LAND ROVER

LAND ROVER

 Code 

**0-9**

12 L ..... 786

14TCIE ..... 782

17 H ..... 786

18K16 ..... 782

200TDi ..... 786

204PT ..... 782



21 L ..... 788

224DT ..... 782

23 L ..... 786

244DT ..... 784

25 K4F ..... 788

 Code 

276DT ..... 788

3.9V8EFI ..... 790-792

300TDi ..... 788

306DT ..... 790

30DDTX ..... 790

35 D ..... 790

36 D ..... 790-792



37 D ..... 792

38 D ..... 792

4.2V8EFI ..... 792

40 D ..... 792

42 D ..... 790

 Code 

46 D ..... 792

**D**

DW12BTED4 ..... 782

**I**



i6 ..... 790

**M**

M 47 ..... 782

M 47 R ..... 782

MGRV8 ..... 792

 Code 

**S**

SEV8 ..... 790

**T**

Td5 ..... 784

**V**

V06VEI ..... 790

 Code 

 Code 

 Code 

 Code 

LAND ROVER						
Ltr.						
1,8 18K16	86-88 kW (117-120 PS)	FREELANDER 16V	02/98-10/06	<b>D37245-00</b> ⑫ <b>B37246-00</b> ⑬	<b>H50497-10</b> LVB500190 82,5 Ø	<b>T50497-00</b> WAN2293L (10x)
2,0 M 47 M 47 R	80-85 kW (109-116 PS)	FREELANDER Td4	11/01→	<b>D82500-00</b> ⑫  <b>B54786-00</b> ⑬ LVQ101240L	<b>H01312-00</b> LVB101820L 1,45 mm 1 MLS <b>H11312-10</b> LVB101830L 1,55 mm 2 MLS <b>H21312-20</b> LVB000100L 1,65 mm 3 MLS	
2,0 14TCIE	72 kW (98 PS)	FREELANDER DI	02/98-11/00	<b>S36055-00</b> ⑫ ⑬ <b>D36055-00</b> ⑫ 	<b>H03732-00</b> LVB100910 1,05 mm 1 MLS <b>H13732-10</b> LVB100920 1,2 mm 2 MLS <b>H23732-20</b> LVB100930 85,5 Ø 1,35 mm 3	
2,0 204PT <b>[NEW]</b>	177 kW (241 PS)	FREELANDER 2 RANGE ROVER EVOQUE	06/11→	<b>S38576-00</b> ⑫ ⑬ <b>D38576-00</b> ⑫	<b>H40547-00</b> LR024975 MLS	<b>T80478-00</b> LR025253 (10x)
2,2 DW12BTED4 224DT <b>[NEW]</b>	110-140 kW (150-190 PS)	FREELANDER 2 RANGE ROVER EVOQUE	10/06→	<b>D38112-02</b> ⑫  <b>B38113-00</b> ⑬	<b>H01901-00</b> LR017303 1,25 mm MLS <b>H11901-10</b> LR017304 1,3 mm MLS <b>H21901-20</b> LR017305 1,35 mm MLS <b>H31901-30</b> LR017307 85,9 Ø 1,37 mm MLS	<b>T05133-00</b> LR001222 (10x)

<b>X53289-01</b> LVP100630L 		<b>X89969-01</b> LKJ101110L 	<b>X82388-01</b> LKG100551 		<b>P77395-01 N</b> ← 30x40x7 A SL LD FPM <b>P77697-01 N</b> → LUC100220L 30x40x7 A SL LD FPM
<b>X82500-01</b> LVP100620L 	<b>N92634-00</b> LGP100310L	<b>X58955-01</b> 4x 8510218 	<b>X52316-01</b> 2x LR020102 	<b>X54786-01</b> LVF100420L NBR  <b>X82501-01</b> LVF100430L 	<b>P77396-01 K</b> ← LVF100530L 55x68x8 AB RD PTFE <b>P77003-01 K</b> → LUF100540L 90x110x12 AB SL LD PTFE
<b>X53700-01</b> LVP100400 		<b>X81655-01</b> WCM100480  <b>X52283-01</b> ⑦ LKJ100790 		<b>X54457-01</b> ERR7029 NBR 	<b>P77126-01 K</b> ← WZX1915 35x45x7 A SL RD FPM <b>P77397-01 K</b> → LUF100420 FPM
<b>V38568-00</b> LR025664 	<b>N92984-00</b> LR025006 (8x) +LR025018 (8x)	<b>M59388-00</b> LR024991 (4x) 	<b>X59389-01</b> LR025852 	<b>70-31414-10</b> 	<b>P77835-01 K</b> ← LR043291 37x50x6 A SL RD FPM <b>P77365-01 K</b> → LR041995 PTFE
<b>V38102-00</b> LR009411 +LR009412 (2x) +LR002834 	<b>N93131-00</b> LR001242 (16x) <b>P76842-00</b> LR001242	<b>M38101-00</b> LR005364 	<b>X59834-01</b> LR022333 	<b>70-31414-10</b> 	<b>P77464-01 K</b> ← LR000673 42x62x7 A SL RD PTFE <b>P77465-01 K</b> → LR000674 90x110x7 A SL LD PTFE <b>P77142-01 N</b> LR000659 27x47x7 A SL RD FPM

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



LAND ROVER						
Ltr.						
2,4 244DT	90 kW (122 PS) DEFENDER TD	05/07→	<b>S37080-00</b> <sup>(12)</sup> <sup>(13)</sup>  <b>D37080-00</b> <sup>(12)</sup> 	<b>H07770-00</b> LR004418 1,1 mm 1 MLS <b>H17770-10</b> LR004419 1,15 mm 2 MLS <b>H27770-20</b> LR004420 91 Ø 1,2 mm 3 MLS 	<b>T05555-00</b> LR004369 (10x) +LR004370 (8x) 	
2,5 Td5	102 kW (139 PS) DISCOVERY Td5	01/99-06/04	<b>D36884-00</b> <sup>(12)</sup> → 1A736339 <b>D36885-00</b> <sup>(12)</sup> → 2A736340 → <b>B36884-00</b> <sup>(13)</sup> 	<b>H08014-00</b> LVB000240 86 Ø 1,2 mm 2 MLS <b>H18014-10</b> LVB000250 86 Ø 1,27 mm 1 MLS <b>H28014-20</b> LVB000260 86 Ø 1,35 mm 3 MLS 	<b>T08014-00</b> ERR5384 (12x) 	

<b>X83024-01</b> LR004440 NBR 	<b>N92986-00</b> LR005901 (16x) <b>P76777-00</b> LR005901 16x	<b>X88198-01</b> LR018370 8x 	<b>X81992-01</b> LR004393 	<b>E36738-00</b> LR006957  <b>70-31414-10</b> 	<b>P77367-01 K</b> ← LR029318 PTFE <b>P77338-01 K</b> → LR020609 PTFE
<b>X83088-01</b> ERR7094 → 1A736339 <b>X83089-01</b> LVP000020 → 2A736340 →	<b>N92743-00</b> LJQ100940 (10x) <b>P76839-00</b> LJQ100940 10x	<b>X89134-01</b> LKJ000010 	<b>X81515-01</b> LKG100470  <b>X82370-01</b> ESR3737 	<b>X54795-01</b> LVF500040 	<b>P77399-01 K</b> ← ERR5992 50x65x8 AB SL RD FPM



LAND ROVER						
Ltr.						
2,5 12 L 200TDi	83 kW (113 PS) DEFENDER TDI DISCOVERY TDI	10/89→	<b>D36117-00</b> STC362 	<b>H01826-00</b> LVB500200 1,3 mm MLS <b>H11826-10</b> LVB500210 1,4 mm MLS <b>H21826-20</b> LVB500220 1,5 mm MLS <b>H31826-30</b> LVB500230 92 Ø 1,6 mm MLS  <b>H07879-00</b> ERR5261 1,42 mm 1 <b>H17879-10</b> ERR5262 1,52 mm 2 <b>H27879-20</b> ERR5263 92 Ø 1,62 mm 3 <b>H37879-30</b> ERR7154 1,7 mm 	<b>T07879-00</b> ETC8808 (4x) +ETC8809 (10x) +ETC8810 (4x) 	
2,5 17 H 23 L	61-86 kW (83-117 PS) DEFENDER 90/110	09/85→	<b>S30103-00</b> ⑫ ⑬ 501677 <b>D30103-00</b> ⑫ <b>B30103-00</b> ⑬ RTC809	<b>H02281-00</b> GEG338 95,2 Ø 		

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>X53646-01</b> NBR 	<b>N90700-00</b> ETC8663 (x8) <b>P76636-00</b> ETC8663 8x	<b>X52550-01</b> ⑦ ERR1208 	<b>70-31414-10</b> 	<b>P76175-01 K</b> ← ADU8891 48,6x63,65x8/9 RD NBR <b>P76400-01 K</b> → ERR2532 100x120x12 LD <b>P76111-01 N</b> 13510-V7200 40x52x7 RD FPM	
<b>X03838-01</b> GEG431 Kork 	<b>N90790-00</b> 554727(x4)+ <b>P76509-00</b> 554728 4x <b>P76510-00</b> 554727 4x	<b>X02284-01</b> ⑦ 274171 	<b>X02266-01</b> GEG723	<b>X03755-01</b> GEG537 	<b>P76175-01 K</b> ← ADU8891 48,6x63,65x8/9 RD NBR <b>P76272-01 K</b> → 523240 63,5x82,5x7,9 LD FPM



LAND ROVER						
Ltr.						
2,5 21 L 300TDi	83 kW (113 PS) DEFENDER TDI DISCOVERY TDI	10/89-12/98	<b>S32149-00</b>  <b>D32149-00</b> STC2802  <b>B32149-00</b> STC2801	⑫ ⑬ ⑳	<b>H01826-00</b> LVB500200 1,3 mm MLS <b>H11826-10</b> LVB500210 1,4 mm MLS <b>H21826-20</b> LVB500220 1,5 mm MLS <b>H31826-30</b> LVB500230 92 Ø 1,6 mm MLS  <b>H07879-00</b> ERR5261 1,42 mm 1 <b>H17879-10</b> ERR5262 1,52 mm 2 <b>H27879-20</b> ERR5263 92 Ø 1,62 mm 3 	<b>T01826-00</b> ERR1939 (10x) +ETC8808 (4x)
2,5 25 K4F	130 kW (177 PS) FREELANDER V6	11/00-10/06	<b>D36106-00</b> <b>B36106-00</b>	⑫ ⑬ ⑳	<b>H80102-00</b> LVB101630L 82,5 Ø 	2x <b>T40360-00</b> 2x 
2,7 276DT <b>[NEW]</b>	140 kW (190 PS) DISCOVERY TD RANGE ROVER TDVM	07/04→	<b>D38757-00</b>  <b>B38756-00</b>	⑫ ⑬ ⑳	<b>H01902-00</b> LR009719 82,5 Ø 1,17 mm 2 MLS <b>H01902-10</b> 2x LR009721 82,5 Ø 1,22 mm 3 MLS <b>H01902-20</b> 2x LR009722 82,5 Ø 1,27 mm 4 MLS <b>H11902-30</b> 2x LR009723 82,5 Ø 1,32 mm 5 	2x <b>T01902-00</b> 2x 1331316 (8x) 

⑫ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена

⑬ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>X53207-01</b> ERR2409 NBR 	<b>N90700-00</b> ETC8663 (x8) <b>P76636-00</b> ETC8663 8x	<b>X51509-01</b> ERR3785 	<b>X54675-01</b>  <b>70-31414-10</b> 	<b>P76458-01 K ←</b> 47x62x9 RD FPM <b>P77400-01 K →</b> LUF100430 FPM <b>P76117-01 N</b> 40x56x7 A SL RD MVQ		
<b>X83157-01</b> 2x LVP100470L 	<b>N95980-00</b> LUB100350L <b>P76632-00</b> LUB100350L 24x	<b>X85000-01</b> 2x LKJ100680L 	<b>X52551-01</b> 2x LKG100290L 	<b>P77461-01 K ←</b> LQX100070L 32x45x6,8 A RD <b>P77462-01 K →</b> LUF100300L		
<b>X83359-01</b> 2x LR029132 	<b>N93132-00</b> 1311285 (24x) <b>P76843-00</b> 1311285 24x	<b>X82334-01</b> 2x 1336543 	<b>X54926-01</b> LR005994  <b>X59640-01</b> 1365260 	<b>P77681-01 K ←</b> 1102415 35x50x7 A SL RD PTFE ACM <b>P77677-01 K →</b> LR036542 <b>P77624-01 N</b> 3x 1311318 26x45x8 A SL WD FPM		

⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



LAND ROVER						
Ltr.						
3,0 30DDTX 306DT <b>[NEW]</b>	155-200 kW (211-272 PS) DISCOVERY SDV6 DISCOVERY TD RANGE ROVER SPORT TD RANGE ROVER TD	09/09→	<b>D38339-01</b> (12)  <b>B38339-01</b> (13)	<b>H40636-00</b> 2x LR013063 85 Ø 1,17 mm 2 MLS <b>H40636-10</b> 2x LR013066 85 Ø 1,22 mm 3 MLS <b>H40636-20</b> 2x LR013070 85 Ø 1,27 mm 4 MLS <b>H40636-30</b> 2x LR013073 85 Ø 1,32 mm 5	<b>T01902-00</b> 2x 1331316 (8x) 	
3,2 i6	170 kW (231 PS)		<b>D38089-00</b> (12) <b>B38133-00</b> (13)	<b>H40376-00</b> LR006664 84,85 Ø MLS 	<b>T50037-00</b> LR002553 (14x) 	
3,9 SEV8 V06VEI 3.9V8EFI 42 D	136-140 kW (185-190 PS) RANGE ROVER	07/94→	<b>D36122-00</b> (12) STC2822 <b>B36122-00</b> (13) STC2823			
3,9 35 D	134 kW (182 PS) DISCOVERY V8	09/93-10/98	<b>D36121-00</b> (12) STC1641 → <b>35D08927B</b> <b>D36122-00</b> (12) STC2822 <b>35D08928B</b> → <b>B36122-00</b> (13) STC2823 <b>35D08928B</b> →			
3,9 35 D	134 kW (182 PS) RANGE ROVER	11/88-07/94	<b>D36121-00</b> (12) STC1641 → <b>35D08927B</b> <b>D36122-00</b> (12) STC2822 <b>35D08928B</b> → <b>B36122-00</b> (13) STC2823 <b>35D08928B</b> →			
3,9 36 D	134 kW (182 PS) DISCOVERY V8	09/93-10/98	<b>D36121-00</b> (12) STC1641 → <b>36D25154B</b> <b>D36122-00</b> (12) STC2822 <b>36D25155B</b> → <b>B36122-00</b> (13) STC2823 <b>36D25155B</b> →			

<b>X83359-01</b> 2x LR029132 	<b>N93132-00</b> 1311285 (24x) <b>P76843-00</b> 24x 1311285		<b>X82334-01</b> 2x 1336543 	<b>X54926-01</b> LR005994 	<b>P77681-01 K</b> ← 1102415 35x50x7 A SL RD PTFE ACM <b>P77677-01 K</b> → LR036542 <b>P77624-01 N</b> 3x 1311318 26x45x8 A SL WD FPM
<b>V38118-00</b> LR001808 (6x) +LR001978 		<b>X89889-01</b> 6x LR001454 	<b>X82354-01</b> 2x LR001455 		<b>P77815-01 K</b> ← 19x38,5x8 A SL RD PTFE <b>P77353-01 K</b> → LR001418 98x118x10 A SL LD PTFE ACM
	<b>N92744-00</b> ERR1782 (16x)				
	<b>N92744-00</b> ERR1782 (16x) <b>35D08928B</b> →				



LAND ROVER						
Ltr.						
3,9 36 D	134 kW (182 PS) RANGE ROVER	11/88-07/94	<b>D36121-00</b> (12) STC1641 → 36D25154B <b>D36122-00</b> (12) STC2822 → 36D25155B→ <b>B36122-00</b> (13) STC2823 → 36D25155B→			
3,9 37 D	127 kW (173 PS) RANGE ROVER	11/88-07/94	<b>D36121-00</b> (12) STC1641 → 37D02931B <b>D36122-00</b> (12) STC2822 → 37D02932B→ <b>B36122-00</b> (13) STC2823 → 37D02932B→			
3,9 38 D	127 kW (173 PS) RANGE ROVER	11/88-07/94	<b>D36121-00</b> (12) STC1641 → 38D27237B <b>D36122-00</b> (12) STC2822 → 38D27238B→ <b>B36122-00</b> (13) STC2823 → 38D27238B→			
3,9 3.9V8EFI	127 kW (173 PS) RANGE ROVER	11/88-07/94	<b>D36121-00</b> (12) STC1641 → 12/93 <b>D36122-00</b> (12) STC2822 → 01/94→ <b>B36122-00</b> (13) STC2823 → 01/94→			
4,0 MGRV8	136 kW (185 PS) DISCOVERY V8	11/98-06/04	<b>D36122-00</b> (12) STC2822 <b>B36122-00</b> (13) STC2823			
4,3 40 D	149 kW (203 PS) RANGE ROVER	09/92-07/94	<b>D36122-00</b> (12) STC2822 <b>B36122-00</b> (13) STC2823			
4,3 4.2V8EFI	149 kW (203 PS) RANGE ROVER	09/92-07/94	<b>D36122-00</b> (12) STC2822 <b>B36122-00</b> (13) STC2823			
4,6 46 D	165 kW (224 PS) RANGE ROVER	07/94-03/02	<b>D36122-00</b> (12) STC2822 <b>B36122-00</b> (13) STC2823			

	<b>N92744-00</b> ERR1782 (16x) → 36D25155B→				
	<b>N92744-00</b> ERR1782 (16x) → 37D02932B→				
	<b>N92744-00</b> ERR1782 (16x) → 38D37238B→				
	<b>N92744-00</b> ERR1782 (16x)				
	<b>N92744-00</b> ERR1782 (16x)			<b>X54928-01</b> LVF100400 Gummi 	
	<b>N92744-00</b> ERR1782 (16x)				

