









PEUGEOT

 Code	
<b>0-9</b>	
1580 SPI (222A2) .....	386
8140.43S (F28DTCR) .....	404
<b>C</b>	
CRD93 .....	400
CRD93L .....	402
CRD93LS .....	402
<b>D</b>	
DJ5 (T9A) .....	402
DJ5T (T8A) .....	402
DJ5TED (THX) .....	402
DW10ATED (RHZ) .....	394
DW10ATED4 (RHW) .....	394
DW10BTED (RHX) .....	394

 Code	
DW10TD (RHY) .....	394
DW10UTD (RHV) .....	394
DW10UTED4 (RHK) .....	396
DW12UTED (4HY) .....	400
DW8 (WJZ) .....	390
DW8B (WJY) .....	390
<b>E</b>	
EW10 (RFH) .....	396
EW10J4 (RFN) .....	396
<b>T</b>	
TU1JP (HFX) .....	382
TU1M (HDZ) .....	382
TU3JP (KFW) .....	382
TU3JP (KFX) .....	382

 Code	
TU5JP4 (NFU) .....	384
<b>X</b>	
XB5 .....	382
XB5P .....	382
XC5P .....	384
XC7P .....	384-386
XD2P94 .....	400
XD2PX94 .....	400
XD3P .....	402
XDP88 .....	390
XDP90 .....	400
XD PX90 .....	398
XM7P .....	386
XM7T (169B) .....	386-388
XN1P .....	396-398

 Code	
XN1T .....	398
XN1T (170) .....	396
XN1T (170B) .....	396
XU10J2 (RFL) .....	398
XU10J2U (RFL) .....	398
XU7JB (LFX) .....	388
XUD7 (A9A) .....	388
XUD9A (D9B) .....	392
XUD9A (DJY) .....	392
XUD9AU (D8C) .....	392
XUD9TE .....	392
XUD9TE (D8B) .....	392
XUD9TE (DHX) .....	392
XUD9TE (DHY) .....	392
XUD9UTF (D8C) .....	392

PEUGEOT

 Code	
--	---

 Code	
--	---

 Code	
--	---

 Code	
--	---

PEUGEOT						
Ltr.						
1,1 TU1JP (HFX)	44 kW (60 PS)	PARTNER	06/96→	<b>D36677-00</b> (12) <b>B37002-00</b> (13)	<b>H80370-00</b> 0209.Y0 73,5 Ø 1,25 mm 	<b>T01004-00</b> 0204.83 (10x) 
1,1 TU1M (HDZ)	44 kW (60 PS)	PARTNER	06/96→	<b>S31062-00</b> (12) (13) (51) 95619476+97520616 <b>D31062-00</b> (12) (51) 0197.A7 <b>B31062-00</b> (13) (51) <b>R30712-00</b> (3) 7701348178 (x4)	<b>H01004-10</b> (51) 0209.CJ 76,3 Ø 1,3 mm <b>H11004-20</b> (51) 0209.CK 76,3 Ø 1,5 mm 	<b>T01004-00</b> 0204.83 (10x) 
1,4 TU3JP (KFW) TU3JP (KFX)	54-55 kW (73-75 PS)	PARTNER	06/96→	<b>S32984-00</b> (12) (13) <b>D32984-00</b> (12) 0197.H8+0209.CJ <b>B31600-00</b> (13)  <b>R30712-00</b> (3) 7701348178 (x4)	<b>H01004-10</b> (51) 0209.CJ 76,3 Ø 1,3 mm <b>H11004-20</b> (51) 0209.CK 76,3 Ø 1,5 mm 	<b>T01004-00</b> 0204.83 (10x) 
1,5 XB5 XB5P	39-61 kW (53-83 PS)	J7	08/68→	<b>A30791-00</b> (12) (14) 0198.35 <b>D30791-00</b> (12) 0199.36 <b>R30553-00</b> (3) 0112.17(4)	<b>H03545-00</b> 0203.26 82,5 Ø 	

(12) juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра  
 (14) sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



<b>X06304-01</b> 0249.54 	<b>N91190-00</b> 0956.19 (8x) <b>P76532-00</b> 0956.19 8x	<b>X87172-01</b> 0342.E0 4x 	<b>X82381-01</b> X 0349.J6 Emission reduction FL5 <b>X82382-01</b> 0349.J3 Exhaust norm L4 <b>X81500-01</b> Δ 1709.25 	<b>X54035-01</b> (51) 	<b>P76154-01</b> K ← 0514.38 42x66x6 A SL RD MVQ <b>P76353-01</b> K → 0514.74 85x105x8 A SL LD FPM <b>P76133-01</b> N 0236.21 36x50x7 A RD FPM
<b>X06304-01</b> 0249.54 	<b>N91190-00</b> 0956.19 (8x) <b>P76532-00</b> 0956.19 8x	<b>X56780-01</b> 2x 	<b>X06306-01</b> 2x 0349.A6 <b>X06310-01</b> Δ 1709.10 	<b>X54035-01</b> (51) 	<b>P76154-01</b> K ← 0514.38 42x66x6 A SL RD MVQ <b>P76353-01</b> K → 0514.74 85x105x8 A SL LD FPM <b>P76133-01</b> N 0236.21 36x50x7 A RD FPM
<b>X06304-01</b> 0249.54 	<b>N91190-00</b> 0956.19 (8x) <b>P76532-00</b> 0956.19 8x	<b>X87172-01</b> 0342.E0 4x 	<b>X06306-01</b> 2x 0349.A6 <b>X82381-01</b> X 0349.J6 Emission reduction FL5 <b>X82382-01</b> X 0349.J3 Exhaust norm L4 <b>X06310-01</b> Δ 1709.10 	<b>X54035-01</b> (51) 	<b>P76154-01</b> K ← 0514.38 42x66x6 A SL RD MVQ <b>P76353-01</b> K → 0514.74 85x105x8 A SL LD FPM <b>P76133-01</b> N 0236.21 36x50x7 A RD FPM
<b>X04835-01</b> 0249.14 NBR 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x	<b>X04834-01</b> 0348.06 	<b>X04833-01</b> 0349.03 <b>X03013-01</b> Δ 1721.01 <b>X05087-01</b> Δ 1710.15 	<b>X04838-01</b> 0304.03 Kork 	

(51) material bloque motor Aluminio / Motorblockmaterial Aluminium / engine Block Material Aluminium / matériel pour bloc-moteur aluminium / materiale blocco motore Alluminio / материал блока двигателя алюминий



PEUGEOT						
Ltr.						
1,6 TU5JP4 (NFU)	80 kW (109 PS) PARTNER PARTNER 16V	09/00→	<b>D36693-00</b> ⑫ <b>B36693-00</b> ⑬	<b>H80497-00</b> 0209.1E 78,5 Ø MLS 	<b>T04220-00</b> 0204.81 (10x) 	
1,6 XC5P	50 kW (68 PS) J7 J7 Bus	08/68-03/80	<b>A30548-00</b> ⑫ ⑭ 0199.40 <b>D30548-00</b> ⑫ 0199.84 <b>R30553-00</b> ③ 0112.17(4)	<b>H04608-00</b> 0203.24 86,8 Ø 		
1,6 XC7P	44 kW (60 PS) J7 J7 Bus	08/68-03/80	<b>A30547-00</b> ⑫ ⑭ <b>D30547-00</b> ⑫ <b>R30547-00</b> ③	<b>H02666-00</b> 86,7 Ø 	<b>T02666-00</b> 0204.21 (10x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



<b>X83028-01</b> 0249.A9 NBR → 2336722  <b>X59782-01</b> X → 2336723→ 2x	<b>N92004-00</b> 0956.40 (16x) <b>P76809-00</b> 0956.40 16x	<b>M74443-00</b> 0348.05 	<b>X81664-01</b> 0349.J4  <b>X81500-01</b> 1709.25 	<b>X54807-01</b> 0304.55 NBR 	<b>P76154-01</b> K ← 0514.38 42x66x6 A SL RD MVQ <b>P76353-01</b> K → 0514.74 85x105x8 A SL LD FPM <b>P77141-01</b> N 0807.24 38x50x6 A SL RD FPM 2x
<b>X04835-01</b> 0249.14 NBR 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x	<b>X04834-01</b> 0348.06 4x 	<b>X04833-01</b> 0349.03  <b>X03013-01</b> Δ 1721.01  <b>X04201-01</b> Δ 1710.09  <b>X05087-01</b> Δ 1710.15 	<b>X04838-01</b> 0304.03 Kork 	
<b>X04835-01</b> 0249.14 NBR 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x		<b>X04833-01</b> 0349.03  <b>X03013-01</b> Δ 1721.01  <b>X04201-01</b> Δ 1710.09  <b>X05087-01</b> Δ 1710.15 	<b>X54253-01</b> Kork 	

⑭ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



PEUGEOT						
Ltr.						
1,6 XC7P	03/80-06/87	44 kW (60 PS) J9	<b>A30547-00</b> ⑫ ⑭ <b>D30547-00</b> ⑫ <b>R30547-00</b> ③	<b>H02666-00</b> 86,7 Ø 	<b>T02666-00</b> 0204.21 (10x) ① →06/85  <b>T02760-00</b> 0204.51 (10x) ① 07/85→ 	
1,6 1580 SPI (222A2)	02/96→	58 kW (79 PS) EXPERT	<b>S32919-00</b> ⑫ ⑬ <b>D32919-00</b> ⑫ <b>B32919-00</b> ⑬	<b>H00593-10</b> 0209.P9 87 Ø 	<b>T05082-00</b> 	
1,8 XM7P	07/70-03/80	48 kW (65 PS) J7 J7 Bus	<b>A30547-00</b> ⑫ ⑭ <b>D30547-00</b> ⑫ <b>R30547-00</b> ③	<b>H02666-00</b> 86,7 Ø 	<b>T02666-00</b> 0204.21 (10x) 	
1,8 XM7T (169B)	01/83-11/88	51 kW (69 PS) J5	<b>S30778-00</b> ⑫ ⑬ <b>D30778-00</b> ⑫	<b>H02666-00</b> 86,7 Ø 	<b>T02666-00</b> 0204.21 (10x) ① →06/85  <b>T02760-00</b> 0204.51 (10x) ① 07/85→ 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра  
 ⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>X04835-01</b> 0249.14 NBR 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x		<b>X04833-01</b> 0349.03  <b>X03013-01</b> △ 1721.01  <b>X04201-01</b> △ 1710.09  <b>X05087-01</b> △ 1710.15 	<b>X54253-01</b> Kork 	
<b>X01619-01</b> U  <b>X53175-01</b> O  <b>X53734-01</b> 0249.84 Kork 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x	<b>X51425-01</b> ⑦ 		<b>X00688-01</b> 0304.49 Gummi 	<b>P76117-01</b> K ← 40x56x7 A SL RD MVQ <b>P76273-01</b> K → 64x80x8 A SL LD MVQ <b>P76060-01</b> N 30x52x7 AB SL RD FPM
<b>X04835-01</b> 0249.14 NBR 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x		<b>X04833-01</b> 0349.03  <b>X03013-01</b> △ 1721.01  <b>X04201-01</b> △ 1710.09  <b>X05087-01</b> △ 1710.15 	<b>X54253-01</b> Kork 	
<b>X04835-01</b> 0249.14 NBR 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x	<b>X07480-01</b> 0348.33 	<b>X04833-01</b> 0349.03 	<b>X04848-01</b> 2x 0127.05 NBR  <b>X54253-01</b> Kork 	<b>P76151-01</b> K ← 0326.12 42x62x7 A RD FPM <b>P76005-01</b> N 16x21x4,5 NBR

⑭ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала  
 O arriba / oben / top / haut / superiore / сверху  
 U debajo / unten / bottom / bas / inferiore / снизу



PEUGEOT						
Ltr.						
1,8 XM7T (169B)	51 kW (69 PS) J5	09/90-01/94	<b>S30778-00</b> ⑫ ⑬ <b>D30778-00</b> ⑫	<b>H02666-00</b> 86,7 Ø 	<b>T01025-00</b> 0204.57 (10x) 	
1,8 XUD7 (A9A)	43-44 kW (58-60 PS) PARTNER D	06/96→	<b>S30527-00</b> ⑫ ⑬ 0197.H5  <b>D30527-00</b> ⑫ 0197.37 +0956.22 (8x)  <b>B30527-00</b> ⑬	<b>H08280-00</b> 0209.F9 1,57 mm 2 <b>H18280-10</b> 1,7 mm 3  <b>H05875-00</b> 0209.S0 1,36 mm 1 <b>H05875-10</b> 0209.S1 1,4 mm 2 <b>H05875-20</b> 0209.S2 1,44 mm 3 <b>H15875-30</b> 0209.S3 1,48 mm 4 <b>H15875-40</b> 0209.S4 82 Ø 1,53 mm 5 	<b>T08280-00</b> 0204.65 (10x) 	
1,8 XU7JB (LFX)	66 kW (90 PS) PARTNER	05/97→	<b>S36241-00</b> ⑫ <b>D36241-00</b> ⑫ <b>B31580-00</b> ⑬ <b>R31124-00</b> ③	<b>H01025-00</b> 0209.E1 84,3 Ø 1,2 mm <b>H11025-10</b> 0209.L3 84,3 Ø 1,5 mm 		

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



<b>X04835-01</b> 0249.14 NBR 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x	<b>X07480-01</b> 0348.33 	<b>X04833-01</b> 0349.03 	<b>X04848-01</b> 2x 0127.05 NBR <b>X54253-01</b> Kork 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76005-01 N</b> 16x21x4,5 NBR
<b>X07796-01</b> 0249.46 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x	<b>X55498-01</b> 2x 0348.99  <b>X55499-01</b> 0348.98 	<b>X07782-01</b> 2x 0349.47  <b>X03013-01</b> 1721.01 	<b>X07793-01</b> 0304.34 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76386-01 K →</b> 0127.28 90x110x7 A SL LD FPM <b>P76099-11 N</b> 0236.14 35x50x8 A SL WD FPM
<b>X53101-01</b> 0249.71 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x	<b>X85532-01</b> 4x 0348.L7 	<b>X52670-01</b> 1723.63 	<b>X07793-01</b> 0304.34 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76386-01 K →</b> 0127.28 90x110x7 A SL LD FPM <b>P76133-01 N</b> 0236.21 36x50x7 A RD FPM



PEUGEOT						
Ltr.						
1,9 DW8 (WJZ) DW8B (WJY)	51 kW (69 PS) EXPERT D PARTNER D	06/96→	<b>S32985-00</b> ⑫ ⑬ 0197.X6 +0127.28 +0326.22 +0807.14  <b>D32985-00</b> ⑫ 0197.X5 +0807.14  <b>B32989-00</b> ⑬	<b>H05616-00</b> 0209.X0 84 Ø 1,26 mm 3 <b>H05616-10</b> 0209.X1 1,3 mm 4 <b>H05616-20</b> 0209.X2 1,34 mm 5 <b>H15616-30</b> 0209.X3 1,38 mm 6 <b>H15616-40</b> 0209.X4 1,42 mm 7 <b>H15616-50</b> 0209.1C 84 Ø 1,47 mm 4 	<b>T08280-00</b> 0204.65 (10x) → 08469  <b>T05616-00</b> 0204.97 (10x) → 08470→ 	
1,9 XDP88	40 kW (55 PS) J7 Bus D J7 D	08/68-07/78	<b>S30226-00</b> ⑬ 0198.14 → 2053776 <b>S30794-00</b> ⑫ ⑬ 0198.40 → 2053777→ <b>D30226-00</b> 0197.08 → 2053776 <b>D30794-00</b> ⑫ 0197.09 → 2053777→ <b>B30756-00</b> ⑬ ⑯ → 4586484→ <b>R30794-00</b> ③	<b>H02668-00</b> 0209.L2 94 Ø → 2053776  <b>H07635-00</b> 0203.70 1,6 mm → 2053777→ <b>H17635-10</b> 94 Ø 1,7 mm → 2053777→ 		

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра  
 ⑯ con anillos para camisa de cilindro / mit Zylinderlaufbuchsenringe / with cylinder liner rings / avec joints de chemises de cylindre / con anelli tenuta canna cilindro / с прокладками гильз цилиндров



<b>X53733-01</b> U 0249.97  <b>X53780-01</b> O 0249.95 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48	<b>X58969-01</b> 2x 0348.N2  <b>X58970-01</b> 0348.N1 	<b>X52327-01</b> 2x 0349.H7 	<b>X07793-01</b> 0304.34 	<b>P76151-01</b> K ← 0326.12 42x62x7 A RD FPM <b>P76386-01</b> K → 0127.28 90x110x7 A SL LD FPM <b>P76099-11</b> N 0236.14 35x50x8 A SL WD FPM
<b>X06833-01</b> 0249.25 NBR 	<b>N90270-00</b> 0956.01 (8x)	<b>X06855-01</b> 3x 0348.52 	<b>X07092-01</b> 2x 0349.08  <b>X05087-01</b> 1710.15  <b>X07094-01</b> 1710.07  <b>X07489-01</b> 1710.19 	<b>X03048-01</b> 0313.19  <b>X07098-01</b> 0304.12 	<b>P76150-01</b> K ← 0514.11 42x60x8 A RD FPM <b>P76005-01</b> N 16x21x4,5 NBR

O arriba / oben / top / haut / superiore / сверху  
 U debajo / unten / bottom / bas / inferiore / снизу



PEUGEOT						
Ltr.						
1,9 XUD9A (DJY) XUD9A (D9B) XUD9AU (D8C)	50-51 kW (68-70 PS)	BOXER Bus D BOXER D EXPERT D J5 Bus D J5 D PARTNER D	10/90→	<b>S31582-00</b> 0197.H5  <b>D31582-00</b> 0197.37  <b>B31582-00</b> 	<b>H02359-00</b> 0209.K0 84 Ø 1,6 mm 2 <b>H12359-10</b> 84 Ø 1,7 mm 3 <b>H05876-00</b> 0209.S5 1,36 mm 1 <b>H05876-10</b> 0209.S6 1,4 mm 2 <b>H05876-20</b> 0209.S7 1,44 mm 3 <b>H15876-30</b> 0209.S8 1,48 mm 4 <b>H15876-40</b> 0209.S9 84 Ø 1,53 mm 5	<b>T08280-00</b> 0204.65 (10x) 
1,9 XUD9TE XUD9TE (DHX) XUD9TE (DHY) XUD9TE (D8B) XUD9UTF (D8C)	66-68 kW (90-92 PS)	BOXER BOXER Bus TD BOXER TD EXPERT TD	03/94→	<b>S31582-00</b> 0197.H5  <b>D31582-00</b> 0197.37  <b>B31582-00</b> 	<b>H02360-00</b> 0209.Q5 1,65 mm <b>H12360-10</b> 0209.Q6 1,75 mm <b>H05877-00</b> 0209.Q8 1,36 mm 1 MLS <b>H05877-10</b> 0209.Q9 1,4 mm 2 MLS <b>H05877-20</b> 0209.R0 1,44 mm 3 MLS <b>H15877-30</b> 0209.R1 1,48 mm 4 MLS <b>H15877-40</b> 0209.R2 84 Ø 1,53 mm 5 MLS	<b>T02360-00</b> 0204.73 (10x) 

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>X07796-01</b> 0249.46 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x	<b>X07796-01</b> 0249.46 	<b>X03013-01</b> 1721.01 	<b>X07793-01</b> 0304.34 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76386-01 K →</b> 0127.28 90x110x7 A SL LD FPM <b>P76099-11 N</b> 0236.14 35x50x8 A SL WD FPM 2x
<b>X07796-01</b> 0249.46 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x 2x	<b>X07796-01</b> 0249.46 	<b>X03013-01</b> 1721.01 	<b>X07793-01</b> 0304.34 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76386-01 K →</b> 0127.28 90x110x7 A SL LD FPM <b>P76099-11 N</b> 0236.14 35x50x8 A SL WD FPM 2x





PEUGEOT					
Ltr.					
2,0 DW10ATED (RHZ) DW10BTED (RHX) DW10TD (RHY)	66-80 kW (90-109 PS) EXPERT HDI PARTNER HDI	02/00→			
			<b>S36550-00</b> (12) (13) 0197.X4 +0249.99 	<b>H05133-00</b> 0209.X5 1,3 mm 1 MLS <b>H05133-10</b> 0209.X6 1,35 mm 2 MLS <b>H05133-20</b> 0209.X7 1,4 mm 3 MLS <b>H15133-30</b> 0209.X8 1,45 mm 4 MLS <b>H15133-40</b> 0209.X9 86 Ø 1,5 mm 5 MLS 	<b>T05133-00</b> 0204.A6 (10x) 
2,0 DW10ATED4 (RHV)	80 kW (109 PS) EXPERT EXPERT HDI	07/00→	<b>S36517-00</b> (12) (13) 0197.Y6 	<b>H01900-00</b> 0209.AV 86 Ø 1,25 mm 2 MLS <b>H11900-10</b> 0209.AW 86 Ø 1,3 mm 3 MLS <b>H21900-20</b> 0209.AX 86 Ø 1,35 mm 4 MLS <b>H31900-30</b> 0209.AY 86 Ø 1,4 mm 5 MLS 	<b>T17586-00</b> 0204.A6 (10x) 
2,0 DW10UTD (RHV)	62 kW (84 PS) BOXER Bus HDI BOXER HDI	08/01→	<b>S36550-00</b> (12) (13) 0197.X4 +0249.99 	<b>H05133-00</b> 0209.X5 1,3 mm 1 MLS <b>H05133-10</b> 0209.X6 1,35 mm 2 MLS <b>H05133-20</b> 0209.X7 1,4 mm 3 MLS <b>H15133-30</b> 0209.X8 1,45 mm 4 MLS <b>H15133-40</b> 0209.X9 86 Ø 1,5 mm 5 MLS 	<b>T05133-00</b> 0204.A6 (10x) 



<b>X53885-01</b> 0249.99 	<b>N92991-00</b> 0956.38 (8x) → 08331 <b>N92635-00</b> 0956.48 (8x) → 08332→ <b>P76662-00</b> 0956.38 → 08331 <b>P76698-00</b> 0956.48 → 08332→	<b>X58968-01</b> 0348.N4 	<b>X52326-01</b> 0349.H4 	<b>70-31414-10</b> 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76386-01 K →</b> 0127.28 90x110x7 A SL LD FPM <b>P77142-01 N</b> 0807.28 27x47x7 A SL RD FPM
<b>X53953-01</b> 0249.A6 	<b>N92635-00</b> 2x 0956.48 (8x) <b>P76698-00</b> 16x 0956.48	<b>X81070-01</b> 0349.J2 	<b>70-31414-10</b> 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76386-01 K →</b> 0127.28 90x110x7 A SL LD FPM <b>P77142-01 N</b> 0807.28 27x47x7 A SL RD FPM	
<b>X53885-01</b> 0249.99 	<b>N92635-00</b> 8x 0956.48 (8x) <b>P76698-00</b> 0956.48	<b>X58968-01</b> 0348.N4 	<b>X52326-01</b> 0349.H4 	<b>70-31414-10</b> 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76386-01 K →</b> 0127.28 90x110x7 A SL LD FPM <b>P77142-01 N</b> 0807.28 27x47x7 A SL RD FPM





PEUGEOT						
Ltr.						
2,0 DW10UTED4 (RHK)	88 kW (120 PS)	EXPERT HDI EXPERT TEPEE HDI	01/07→		<b>H01900-00</b> 0209.AV 86 Ø 1,25 mm 2	<b>T05133-00</b> 0204.A6 (10x) 
					<b>H11900-10</b> 0209.AW 86 Ø 1,3 mm 3	
					<b>H21900-20</b> 0209.AX 86 Ø 1,35 mm 4	
					<b>H31900-30</b> 0209.AY 86 Ø 1,4 mm 5	
2,0 EW10 (RFH)	103 kW (140 PS)	EXPERT	01/07→	<b>S80781-00</b> <b>D80781-00</b> <b>B38333-00</b>	<b>H80781-00</b> 0209.FS MLS 	<b>T80768-00</b> 0204.A3 (10x) 
2,0 EW10J4 (RFN)	100 kW (136 PS)	EXPERT	07/00→	<b>S36504-00</b> 0197.Y1 +0209.Z3 +0249.A4 +0249.A5 <b>D36504-00</b> <b>B36503-00</b>	<b>H80351-00</b> 0209.Z3 85,5 Ø MLS 	<b>T07586-00</b> 0204.A7 (10x) 
2,0 XN1P XN1T (170) XN1T (170B)	55-58 kW (75-79 PS)	J5 J5 Bus	09/81-09/90	<b>S30777-00</b> 9400197139 <b>D30777-00</b> <b>B30777-00</b> <b>R30547-00</b>	<b>H02760-00</b> 0209.46 90,2 Ø 1,2 mm <b>H12760-10</b> 0209.49 90,2 Ø 1,6 mm 	<b>T02666-00</b> 0204.21 (10x)  i →06/85 <b>T02760-00</b> 0204.51 (10x)  i 07/85-04/89 <b>T01025-00</b> 0204.57 (10x)  i 05/89→ 

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



<b>V37090-00</b> 0348.S3 	<b>N92635-00</b> 0956.48 (8x) 2x <b>P76698-00</b> 0956.48 16x		<b>X82339-01</b> 0349.L9 	<b>70-31414-10</b> 	<b>P77464-01 K ←</b> 0127.47 42x62x7 A SL RD PTFE <b>P77465-01 K →</b> 0127.45 90x110x7 A SL LD PTFE <b>P77142-01 N</b> 0807.28 27x47x7 A SL RD FPM
	<b>N92657-00</b> 0956.45 (16x) 16x <b>P76657-00</b> 0956.45	<b>X89881-01</b> 0348.S2 4x 	<b>X82335-01</b> 0349.L4 	<b>70-31414-10</b> 	<b>P77304-01 K ←</b> 0326.27 40x55x6,5 A SL RD FPM <b>P76386-01 K →</b> 0127.28 90x110x7 A SL LD FPM <b>P76133-01 N</b> 0236.21 36x50x7 A RD FPM <b>P77626-01 N</b> 0236.74 39x50x7 A SL RD
<b>X53933-01 L</b> 0249.A4  <b>X53934-01 R</b> 0249.A5 	<b>N92657-00</b> 0956.45 (16x) 16x <b>P76657-00</b> 0956.45	<b>X86822-01</b> 0348.P1 4x 	<b>X81109-01</b> 0349.H8 	<b>70-31414-10</b> 	<b>P77304-01 K ←</b> 0326.27 40x55x6,5 A SL RD FPM <b>P76386-01 K →</b> 0127.28 90x110x7 A SL LD FPM <b>P76133-01 N</b> 2x 0236.21 36x50x7 A RD FPM
<b>X04835-01</b> 0249.14 NBR 	<b>N90300-00</b> 0249.48 (8x) 8x <b>P76531-00</b> 0249.48	<b>X07480-01</b> 0348.33 	<b>X04833-01</b> 0349.03 	<b>X04848-01</b> 2x 0127.05 NBR  <b>X54253-01</b> Kork 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76005-01 N</b> 16x21x4,5 NBR

③ con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



PEUGEOT						
Ltr.						
2,0 XN1P	57 kW (78 PS)	J9 J9 Bus	03/80-06/87	<b>S30777-00</b> ⑫ ⑬ 9400197139 <b>D30777-00</b> ⑫ <b>B30777-00</b> <b>R30547-00</b> ③	<b>H02760-00</b> 0209.46 90,2 Ø 1,2 mm <b>H12760-10</b> 0209.49 90,2 Ø 1,6 mm 	<b>T02666-00</b> 0204.21 (10x) ① →06/85  <b>T02760-00</b> 0204.51 (10x) ① 07/85→ 
2,0 XN1T	55 kW (75 PS)	J5	09/87-08/90	<b>S30777-00</b> ⑫ ⑬ 9400197139 <b>D30777-00</b> ⑫ <b>B30777-00</b> <b>R30547-00</b> ③	<b>H02760-00</b> 0209.46 90,2 Ø 1,2 mm <b>H12760-10</b> 0209.49 90,2 Ø 1,6 mm 	<b>T02760-00</b> 0204.51 (10x) ① →04/89  <b>T01025-00</b> 0204.57 (10x) ① 05/89→ 
2,0 XU10J2 (RFW) XU10J2U (RFL)	80-81 kW (109-110 PS)	BOXER BOXER Bus	03/94→	<b>S31581-00</b> ⑫ ⑬ 95688993 <b>D31581-00</b> ⑫ 0197.G6 +0209.J8 <b>B31581-00</b> ⑬	<b>H50161-00</b> 0209.J8 87 Ø 1,2 mm 	<b>T08280-00</b> 0204.65 (10x) 
2,1 XDPX90	41 kW (56 PS)	J9 D	03/80-06/87	<b>S30226-00</b> ⑬ 0198.14 →4586483 <b>S30794-00</b> ⑫ ⑬ 0198.40 4586484→ <b>D30226-00</b> 0197.08 →4586483 <b>D30794-00</b> ⑫ 0197.09 4586484→ <b>B30756-00</b> ⑬ ⑯ 4572282→ <b>R30794-00</b> ③	<b>H02668-00</b> 0209.L2 94 Ø →4586483  <b>H07635-00</b> 0203.70 1,6 mm 4586484→ <b>H17635-10</b> 94 Ø 1,7 mm 4586484→ 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



<b>X04835-01</b> 0249.14 NBR 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x 	<b>X07480-01</b> 0348.33 	<b>X04833-01</b> 0349.03 	<b>X04848-01</b> 2x 0127.05 NBR  <b>X54253-01</b> Kork 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76005-01 N</b> 16x21x4,5 NBR
<b>X04835-01</b> 0249.14 NBR 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x 	<b>X07480-01</b> 0348.33 	<b>X04833-01</b> 0349.03 	<b>X04848-01</b> 2x 0127.05 NBR  <b>X54253-01</b> Kork 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76005-01 N</b> 16x21x4,5 NBR
<b>X01021-01</b> 0249.48 	<b>N90300-00</b> 0249.48 (8x) <b>P76531-00</b> 0249.48 8x 	<b>X56171-01</b> 2x 0348.F6  <b>X56170-01</b> ⑩ 2x 0348.E6 	<b>X01022-01</b> 4x 0349.70 	<b>70-31414-10</b> 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76386-01 K →</b> 0127.28 90x110x7 A SL LD FPM <b>P76133-01 N</b> 0236.21 36x50x7 A RD FPM
<b>X06833-01</b> 0249.25 NBR 	<b>N90270-00</b> 0956.01 (8x) 	<b>X06855-01</b> 3x 0348.52 	<b>X07092-01</b> 2x 0349.08  <b>X05087-01</b> ⑩ 1710.15  <b>X07094-01</b> ⑩ 1710.07  <b>X07489-01</b> ⑩ 1710.19 	<b>X03048-01</b> 0313.19  <b>X07098-01</b> 0304.12 	<b>P76150-01 K ←</b> 0514.11 42x60x8 A RD FPM <b>P76005-01 N</b> 16x21x4,5 NBR

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

⑯ con anillos para camisa de cilindro / mit Zylinderlaufbuchsenringe / with cylinder liner rings / avec joints de chemises de cylindre / con anelli tenuta canna cilindro / с прокладками гильзы цилиндров



PEUGEOT						
Ltr.						
2,1 XDP90	42 kW (57 PS) J7 Bus D J7 D	08/68-07/77	<b>S30226-00</b> ⑬ 0198.14 → 4586483 <b>S30794-00</b> ⑫ ⑬ 0198.40 → 4586484 → <b>D30226-00</b> 0197.08 → 4586483 <b>D30794-00</b> ⑫ 0197.09 → 4586484 → <b>B30756-00</b> ⑬ ⑯ <b>R30794-00</b> ③	<b>H02668-00</b> 0209.L2 94 Ø → 4586483  <b>H07635-00</b> 0203.70 1,6 mm → 4586484 → <b>H17635-10</b> 94 Ø 1,7 mm → 4586484 → 		
2,2 DW12UTED (4HY)	74 kW (101 PS) BOXER Bus HDI BOXER HDI	04/02 →	<b>S36550-00</b> ⑫ ⑬ 0197.X4 +0249.99   <b>D36550-00</b> ⑫ 0197.X3 +0249.99 	<b>H06254-00</b> 0209.AQ 1,25 mm 1 <b>H06254-10</b> 0209.AR 1,3 mm 2 <b>H06254-20</b> 0209.AS 1,35 mm 3 <b>H16254-30</b> 0209.AT 86 Ø 1,4 mm 4 	<b>T17586-00</b> 0204.96 (10x) 	
2,3 XD2PX94 XD2P94	49 kW (67 PS) J7 Bus D J9 Bus D J9 D	07/77-07/82	<b>A30243-00</b> ⑫ ⑭ 0197.25  <b>S30243-00</b> ⑬ <b>D30243-00</b> ⑫ 0197.08 	<b>H06656-00</b> 0209.C2 1,58 mm 2 <b>H16656-10</b> 0209.C4 96 Ø 1,7 mm 3 		
2,5 CRD93	54 kW (73 PS) J5 J5 Bus D J5 D	09/81-03/94	<b>S30253-00</b> ⑫ ⑬ 75513625 <b>D30253-00</b> ⑫ <b>B30253-00</b> ⑬	<b>H00666-00</b> 0209.75 96,3 Ø 	<b>T06345-00</b> 0204.41 (8x) +0204.42 (9x) 	

③ juego de juntas para camisa de cilindro / Dichtsatz Zylinderlaufbüchse / gasket set cylinder liner / ensemble de joints chemise de cylindre / guarnizioni camicia cilindro / комплект прокладок гильзы цилиндра



<b>X06833-01</b> 0249.25 NBR 	<b>N90270-00</b> 0956.01 (8x)	<b>X06855-01</b> 0348.52 3x 	<b>X07092-01</b> 2x 0349.08  <b>X05087-01</b> 1710.15  <b>X07094-01</b> 1710.07  <b>X07489-01</b> 1710.19 	<b>X03048-01</b> 0313.19  <b>X07098-01</b> 0304.12 	<b>P76150-01 K ←</b> 0514.11 42x60x8 A RD FPM <b>P76005-01 N</b> 16x21x4,5 NBR
<b>X53885-01</b> 0249.99 	<b>N92635-00</b> 0956.48 (8x) <b>P76698-00</b> 0956.48 8x	<b>X58968-01</b> 0348.N4 	<b>X81070-01</b> 0349.J2 	<b>70-31414-10</b> 	<b>P76151-01 K ←</b> 0326.12 42x62x7 A RD FPM <b>P76386-01 K →</b> 0127.28 90x110x7 A SL LD FPM <b>P77142-01 N</b> 0807.28 27x47x7 A SL RD FPM
<b>X06833-01</b> 0249.25 NBR 		<b>X08241-01</b> 2x 0349.44 	<b>X07092-01</b> 2x 0349.08  <b>X08240-01</b> 1710.34  <b>X08245-01</b> 1710.15 	<b>X08253-01</b> 	<b>P76150-01 K ←</b> 0514.11 42x60x8 A RD FPM <b>X08246-01 K →</b> 2x 1227968610
<b>X00742-01</b> 5 450 155 NBR  <b>X01015-01</b> 0249.45 	<b>N91300-00</b> 5469955 <b>P76531-00</b> 0249.48 <b>P76543-00</b> 0956.05 4x 4x	<b>X00837-01</b> 4x 	<b>X00881-01</b> 4x 0349.F0  <b>X07493-01</b> 5 434 181 	<b>X07498-01</b> 7543388080B 	<b>P76178-11 K ←</b> 48x65x10 A NBR <b>P76368-11 K →</b> 26126699J 95x112x12,5 LD FPM <b>P76051-01 N</b> 95550398 29x46x10 LD MVQ

⑭ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала  
 ⑯ con anillos para camisa de cilindro / mit Zylinderlaufbuchsenringe / with cylinder liner rings / avec joints de chemises de cylindre / con anelli tenuta canna cilindro / с прокладками гильз цилиндров



PEUGEOT						
Ltr.						
2,5 CRD93L CRD93LS	09/81-03/94	70 kW (95 PS)	J5 Bus TD J5 DT J5 TD	<b>S31052-00</b> 95593755 <b>D31052-00</b> <b>B31052-00</b>	<b>H06345-00</b> 0209.L6 95,6 Ø	<b>T06345-00</b> 0204.41 (8x) +0204.42 (9x)
2,5 DJ5 (T9A) DJ5T (T8A)	03/94-04/02	63-76 kW (86-103 PS)	BOXER Bus D BOXER Bus TD BOXER D BOXER TD	<b>S32148-00</b> 0197.T7 +0209.R3 <b>D32148-00</b> 0197.T6 +0209.R3 <b>B32148-00</b>	<b>H50390-00</b> 0209.R3 93 Ø	<b>T50390-00</b> 0204.74 (14x) +0204.75 (8x)
2,5 DJ5TED (THX)	01/97-04/02	79 kW (107 PS)	BOXER Bus TDI BOXER TDI	<b>S32990-00</b> 0197.W4 +0209.T5  <b>D32990-00</b> 0197.W3 +0209.T5  <b>B32148-00</b>	<b>H80034-00</b> 0209.T5 93 Ø	<b>T80034-00</b> 0204.87 (14x) +0204.88 (8x)
2,5 XD3P	07/82-06/87	53 kW (72 PS)	J9 Bus D J9 D	<b>S30241-00</b> 0197.P0  <b>D30241-00</b> 0197.N9 	<b>H07986-00</b> 1,53 mm 2 <b>H17986-10</b> 1,63 mm 3 <b>H27986-20</b> 0209.C6 96 Ø 1,73 mm 4	<b>T16656-00</b> 0204.55 (15x) +0204.56 (7x) cyl.head height 83mm  <b>T17986-00</b> 0204.54 (8x) +0204.55 (7x) +0204.56 (7x) cyl.head height 73mm 

⑫ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

⑬ para vehículos con aire acondicionado / für Fahrzeuge mit Klimaanlage / for vehicles with air conditioning / pour véhicules avec système de climatisation / per veicoli con aria condizionata / оснащение / оборудование для автомобилей с кондиционером



<b>X01015-01</b> 0249.45 	<b>N91300-00</b> 5469955 <b>P76531-00</b> 0249.48 <b>P76543-00</b> 0956.05	4x 4x	<b>X00837-01</b> 	4x	<b>X00881-01</b> 0349.F0 	4x	<b>X07498-01</b> 7543388080B 	<b>P76314-01 K ←</b> 0514.32 75x90x11,5 A SL RD FPM <b>P76368-11 K →</b> 26126699J 95x112x12,5 LD FPM <b>P76183-01 N</b> 48x72x10 RD FPM
<b>X53585-01</b> 0249.79 	<b>N92450-00</b> 0956.19 (12x) <b>P76532-00</b> 0956.19	12x	<b>X56189-01</b> 0348.K1 <b>X57008-01</b> 0348.F9 	⑩	<b>X51508-01</b> 0349.E7 	<b>70-31414-10</b> 	<b>P76053-01 K ←</b> 0326.25 64x88x6 A SL RD ACM FPM <b>P76065-01 K →</b> 0119.14 98x120x7 A SL LD FPM <b>P76098-01 N ←</b> 0807.14 35x50x7 A SL RD FPM <b>P76034-01 N →</b> 0807.15 40x62x7 A SL LD ACM FPM <b>P76047-01 N →</b> 0807.21 47,5x62x7 A SL LD ACM FPM	
<b>X53585-01</b> 0249.79 	<b>N91190-00</b> 0956.19 (8x) <b>P76532-00</b> 0956.19	8x	<b>X58971-01</b> 0348.K4 	2x	<b>X52328-01</b> 0349.G4 	<b>70-31414-10</b> 	<b>P76053-01 K ←</b> 0326.25 64x88x6 A SL RD ACM FPM <b>P76065-01 K →</b> 0119.14 98x120x7 A SL LD FPM <b>P76098-01 N V</b> 0807.14 35x50x7 A SL RD FPM <b>P77143-01 N H</b> 0807.26 32x52x7 A SL LD FPM	
<b>X06833-01</b> 0249.25 NBR 	<b>N92637-00</b> 0956.01 (8x)		<b>X08241-01</b> 0349.44 	2x	<b>X08240-01</b> 1710.34  <b>X08245-01</b> 1710.15 	<b>X08253-01</b> 	<b>P76150-01 K ←</b> 0514.11 42x60x8 A RD FPM <b>X08246-01 K →</b> 1227968610	

Ⓐ para vehículos sin aire acondicionado / für Fahrzeuge ohne Klimaanlage / for vehicles without air conditioning / pour véhicules sans système de climatisation / per veicoli senza aria condizionata / оснащение / оборудование для автомобилей без кондиционера

H posterior / hinten / rear / arrière / posteriore / сзади

V delante / vorne / front / avant / anteriore / спереди



PEUGEOT						
Ltr.						
2,8 8140.43S (F28DTCR)	93-94 kW (126-128 PS)	BOXER Bus HDI BOXER HDI	10/00→	<b>S38249-02</b> <sup>(12) (14)</sup> 0197.Y2  <b>D38249-02</b> <sup>(12)</sup> 0197.Y3 	<b>H08023-01</b> 0209.0C 1,3 mm <b>H18023-11</b> 0209.0E 1,4 mm <b>H28023-21</b> 0209.0F 1,5 mm 	

<b>X53812-01</b> ✗ 0249.C3  <b>X59298-01</b> 0249.A0 	<b>N93138-00</b> <b>P76804-00</b> 8x 	<b>X07692-01</b> 4x 	<b>X51326-11</b> 4x 0349.H5 	<b>X54494-01</b> ✗ NBR  <b>X59306-01</b> Gummi 	

<sup>(14)</sup> sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала

