

ASIA

| Code | |
|--------------|----|
| F | |
| F8 | 58 |
| FE | 58 |
| FE-Di | 58 |
| R | |
| R2 | 58 |
| RF-Tci | 58 |

Code



Code



Code



ASIA

Code



Code



Code



Code



| ASIA | | | | | | |
|------------|----------------------------|-------------|--------------------------------------|--|-----------------------------------|--|
| Ltr. | | | | | | |
| 1,8 FE | 57 kW (77 PS) ROCSTA | 06/93-12/99 | S80901-00 D80901-00 | ¹² ¹³ ¹² | H80901-20 88 Ø | |
| 1,8 F8 | 57 kW (77 PS) ROCSTA | 06/93-12/99 | S80972-00 D80972-00 | ¹² ¹³ ¹² | H80972-00 87,5 Ø | |
| 2,0 FE-Di | 100 kW (136 PS) RETONA 16V | 01/97→ | S80922-00 D80922-00 | ¹² ¹³ ¹² | H80922-00 87,5 Ø | |
| 2,0 RF-Tci | 60 kW (82 PS) RETONA TD | 01/97→ | S40029-00 D40029-00 | ¹² ¹³ ¹² | H40029-00 87,6 Ø MLS | |
| 2,2 R2 | 45 kW (61 PS) ROCSTA D | 06/93-12/99 | S80923-00 D80923-00 | ¹² ¹³ ¹² | H80923-10 87,5 Ø MLS | |



| | | | | | |
|----------------------|------------------|----------------------|----------------------|----------------------|---|
| | | | | | |
| X83194-01 | N93001-00 | X89631-01 | X82155-01 | X54866-01 | P77577-01 K ← 30x44x7 A SL RD NBR P77541-01 K → 83x100x9 A SL LD MVQ P77577-01 N 30x44x7 A SL RD NBR |
| X83246-01 | N93010-00 | | X82192-01 | X54866-01 | P77584-01 K ← 34x48x7 A SL RD NBR P77528-01 K → 90x110x9,5 A SL LD MVQ P77584-01 N ← 34x48x7 A SL RD NBR |
| X83212-01 | N92012-01 | | | X54866-01 | P77584-01 K ← 34x48x7 A SL RD NBR P77529-01 K → 90x110x9 A SL LD NBR P77584-01 N ← 34x48x7 A SL RD NBR |
| X83198-01 | N93001-00 | X89630-01 | X82153-01 | X54866-01 | P77584-01 K ← 34x48x7 A SL RD NBR P77529-01 K → 90x110x9 A SL LD NBR P77584-01 N ← 34x48x7 A SL RD NBR |
| X83198-01 | N93001-00 | X89630-01 | X82153-01 | X54866-01 | P77528-01 K → 90x110x9,5 A SL LD MVQ P77577-01 N 30x44x7 A SL RD NBR |

