

## SKODA

## SKODA

Code	
<b>0-9</b>	
135/8	1434
135B	1432
135 L	1432
135M	1432
136B	1434
136 L	1434
136M	1432
<b>A</b>	
ADR	1444
AEE	1438
AEF	1446
AEG	1456
AEH	1438
AEY	1446
AGN	1444
AGP	1448
AGR	1450
AGU	1446
AHF	1452
AKL	1438
ALH	1452
AME	1434
AMF	1434
AMG	1432
AMH	1432
AMJ	1432
AMX	1464
APK	1456
AQM	1454
AQV	1430
AQW	1434
AQY	1456
ARV	1430
ARX	1446
ARZ	1446
ASV	1452
ASY	1454
ASZ	1454

Code	
ATD	1454
ATZ	1434
AUA	1434
AUB	1434
AUM	1446
AUQ	1446
AVB	1454
AVF	1454
AVU	1440
AWT	1446
AWX	1454
AWY	1430-1432
AXP	1434
AXR	1454
AYM	1464
AZE	1434
AZF	1434
AZH	1456
AZJ	1458
AZL	1458
AZM	1458
AZQ	1432
AZV	1458
<b>B</b>	
BBG	1466
BBM	1432
BBY	1434
BBZ	1434
BCA	1434
BDG	1464
BFQ	1440
BGU	1440
BJB	1456
BKC	1456
BKD	1458
BKY	1434
BLF	1440
BLR	1458
BLS	1456

Code	
BLT	1454
BLX	1458
BLY	1458
BMD	1430-1432
BME	1432
BMM	1460
BMN	1460
BMP	1460
BMS	1436
BNM	1436
BNV	1436
BPZ	1454
BSE	1440
BSF	1440
BSS	1460
BSV	1454
BSW	1454
BTS	1440
BUD	1436
BVX	1458
BVY	1458
BVZ	1458
BWA	1460
BWW	1460
BXE	1456
BXW	1436
BZB	1446
BZG	1432
<b>C</b>	
CAVE	1436
CAXA	1436
CAXC	1436
CAYA	1440
CAYB	1440
CAYC	1440-1442
CBBB	1462
CBDB	1462
CBZA	1432
CBZB	1432

Code	
CCSA	1442
CCZA	1462
CDAA	1446
CDAB	1446
CDE	1442
CDF	1442
CDVA	1466
CEGA	1462
CEVA	1432
CFB	1436
CFFB	1462
CFGB	1462
CFHA	1462
CFHC	1462
CFHF	1462
CFJA	1462
CFNA	1442
CFWA	1432
CGGA	1438
CGM	1464
CGPA	1432
CGPB	1432
CGZ	1464
CHFA	1432
CHGA	1442
CHPA	1438
CHTA	1432
CHYA	1430
CHYB	1430
CLCA	1462
CLCB	1462
CLHA	1444
CLHB	1444
CLJA	1462
CLSA	1444
CMXA	1442
CPGA	1430
CRKB	1444
CTHE	1436

Code	
------	--

Code	
------	--

Code	
------	--

Code	
------	--

SKODA						
Ltr.						
1,0 AQV ARV	37 kW (50 PS) FABIA	12/99-08/02	<b>D36701-00</b> ⑫ <b>B36701-00</b> ⑬	<b>H80471-00</b> 047 103 383 B 73,5 Ø 	<b>T80471-00</b> N 907 957 01 (5x) +N 907 958 01 (4x) +N 907 956 01 (1x) 	
1,0 CHYA CHYB <b>[NEW]</b>	44-55 kW (60-75 PS) CITIGO	10/11→	<b>S40694-00</b> ⑫ ⑬ ⑳ <del></del> <b>D40694-00</b> ⑫ <del></del>	<b>H40694-00</b> 04C 103 383 H 75,5 Ø MLS 	<b>T40706-01</b> WHT 004 926 (8x) 	
1,0 CPGA <b>[NEW]</b>	50 kW (68 PS) CITIGO	11/12→	<b>S40699-00</b> ⑫ ⑬ ⑳ <del></del> <b>D40699-00</b> ⑫ <del></del>	<b>H40699-00</b> 04C 103 383 N 75,5 Ø MLS 	<b>T40706-01</b> WHT 004 926 (8x) 	
1,2 AWY BMD	40 kW (54 PS) FABIA	→6Y 5 280 000 07/01-03/08	<b>D36702-00</b> ⑫ <b>B36702-00</b> ⑬	<b>H80386-00</b> 03D 103 383 G 77,5 Ø MLS 	<b>T80386-00</b> WHT 001 808 (8x) 	

⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



<b>X53041-01</b> 047 103 483 NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X87468-01</b> 047 129 717 B 2x 	<b>X81438-01</b> L 047 253 039 H <b>X81439-01</b> 047 253 050 <b>X81682-01</b> R 047 253 039 J 	<b>X54718-01</b> 047 103 609 B 	<b>P76230-01</b> K ← 047 103 085 42x58x8 A SL RD FPM <b>P77290-01</b> K → 047 103 085 A 85x105x12 A SL LD FPM
<b>X59875-01</b> 04C 103 483 B ① →04/13 	<b>N93196-01</b> 04E 109 675 (6x) +04E 109 675 A (6x) <b>P76960-00</b> AS 6x <b>P76961-00</b> ES 6x 04E 109 675	<b>X58997-01</b> 3x 036 129 717 E 	<b>X59947-01</b> 1S0 253 115 B 	<b>70-31414-10</b> 	<b>P77841-01</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01</b> N → 04E 103 085 24x39x8 A SL LD PTFE
<b>X59875-01</b> 04C 103 483 B ① →04/13 	<b>N93197-00</b> 04E 109 675 A (12x) <b>P76960-00</b> 04E 109 675 A 12x	<b>X58997-01</b> 3x 036 129 717 E 	<b>X59947-01</b> 1S0 253 115 B 	<b>70-31414-10</b> 	<b>P77841-01</b> K ← 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01</b> N ← 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01</b> N → 04E 103 085 24x39x8 A SL LD PTFE
<b>70-31414-10</b> 	<b>N92024-00</b> 036 109 675 (6x) <b>P76662-00</b> 036 109 675 6x	<b>X88298-01</b> 3x 03D 129 717 A 	<b>X81435-01</b> 03D 253 039 B 	<b>70-31414-10</b> 	<b>P76096-11</b> K ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01</b> K → 021 103 051 C 85x105x11 A SL LD PTFE ACM

AS lado de escape / Auslaßseite / exhaust side / côté échappement / lato scarico / сторона выпуска  
ES lado de admisión / Einlaßseite / intake side / côté admission / lato aspirazione / сторона впуска



SKODA							
1,2	AWY BMD	40 kW (54 PS)	FABIA	6Y 5 280 001 → 07/01-03/08	<b>D36702-00</b> <b>B36702-00</b> 	<b>H80386-00</b> 03D 103 383 G 77,5 Ø MLS 	<b>T80386-00</b> WHT 001 808 (8x) 
1,2	AZQ BME BZG CEVA CGPA CGPB CHTA	44-51 kW (60-70 PS)	FABIA ROOMSTER	01/03 →	<b>D36703-00</b> <b>B36702-00</b> 	<b>H80385-00</b> 03E 103 383 F 77,5 Ø MLS 	<b>T80385-00</b> 036 103 384 B (8x) 
1,2	BBM CHFA	44 kW (60 PS)	FABIA	12/06 →	<b>D36702-00</b> <b>B36702-00</b> 	<b>H80386-00</b> 03D 103 383 G 77,5 Ø MLS 	<b>T80386-00</b> WHT 001 808 (8x) 
1,2	CBZA CBZB	63-77 kW (86-105 PS)	FABIA TSI OCTAVIA TSI PRAKTIK TSI RAPID ROOMSTER TSI YETI TSI	09/09 →	<del><b>D40579-00</b></del> <del><b>B38301-00</b></del> 	<b>H40579-00</b> 03F 103 383 E 72 Ø MLS 	<b>T40579-00</b> WHT 004 790 (10x) 
1,2	CFWA <b>[NEW]</b>	55 kW (75 PS)	FABIA TDI PRAKTIK TDI ROOMSTER TDI	03/10 →	<b>D38304-00</b> <b>B38298-00</b> 	<b>H40645-00</b> 03P 103 383 C 82 Ø 1,55 mm 1	<b>T50034-01</b> WHT 002 131 (8x) 
						<b>H40645-10</b> 03P 103 383 D 82 Ø 1,63 mm 2	
						<b>H40645-20</b> 03P 103 383 E 82 Ø 1,71 mm 3	
1,3	AMG AMH AMJ 135 L 135B 135M 136M	40-50 kW (54-68 PS)	FAVORIT FELICIA	12/92-04/02	<b>S32711-00</b> <b>D32711-00</b> <b>B30579-00</b> 	<b>H04125-00</b> 76,5 Ø 1,75 mm 	<b>T04132-00</b> 049 103 385 (10x) 

⑫ sin retén cigüeñal / ohne Wellendichtring-Kurbelwelle / without crankshaft oil seal / sans bague d'étanchéité - vilebrequin / senza paraolio albero motore / без уплотнительного кольца коленчатого вала



<b>70-31414-10</b> 	<b>N92024-00</b> 036 109 675 (6x) <b>P76662-00</b> 036 109 675 6x	<b>W88299-01</b> 03D 129 717 B 3x 	<b>X81435-01</b> 03D 253 039 B 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01 K →</b> 021 103 051 C 85x105x11 A SL LD PTFE ACM
<b>70-31414-10</b> 	<b>N92993-00</b> 036 109 675 (12x) <b>P76662-00</b> 036 109 675 12x	<b>W88302-01</b> 03E 129 717 B 3x 	<b>X81445-01</b> 03E 253 039 A 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01 K →</b> 021 103 051 C 85x105x11 A SL LD PTFE ACM
<b>70-31414-10</b> 	<b>N92024-00</b> 036 109 675 (6x) <b>P76662-00</b> 036 109 675 6x	<b>W88299-01</b> 03D 129 717 B 3x 	<b>X81435-01</b> 03D 253 039 B 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77354-01 K →</b> 021 103 051 C 85x105x11 A SL LD PTFE ACM
<b>X59883-01</b> ✗ 03F 103 483 A Metall 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675 8x	<b>X59475-01</b> 03F 129 717 A 1x 	<b>X82520-01</b> 03F 253 041 P 	<b>70-31414-10</b> 	<b>P77181-01 K ←</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM <b>P77479-01 K →</b> 036 103 171B PTFE
<b>70-31414-10</b> 		<b>X59480-01</b> 03F 129 717 4x 			
<b>X59485-01</b> 03P 103 483 	<b>N92993-00</b> 036 109 675 (12x) <b>P76662-00</b> 036 109 675 12x	<b>X59473-01</b> 03P 129 717 	<b>X82519-01</b> 03P 253 039 	<b>70-31414-10</b> 	<b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>X53151-01</b> Kork 	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675 8x	<b>X58344-01</b> 03D 129 717 D 	<b>X03743-01</b> 03D 253 039 A 2x 	<b>X03370-01</b> 032 103 609 B 	<b>P76087-01 K ←</b> 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K →</b> 068 103 051 P 85x105x9 A SL LD FPM <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
			<b>X51310-01</b> 861 253 115 A 		

Ⓢ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



SKODA						
Ltr.						
1,3 135/8 136 L 136B	43-50 kW (58-68 PS)	FAVORIT FAVORIT 136 FELICIA RAPID 130	09/84-04/02	<b>S31365-00</b> (12) (13) <b>D31365-00</b> (12) <b>B31365-00</b> (13)	<b>H50022-00</b> 114-092854 77 Ø	
1,4 AME AQW ATZ AZE AZF	44-50 kW (60-68 PS)	FABIA	08/99-05/03	<b>D36704-00</b> (12) <b>B36701-00</b> (13)	<b>H80582-00</b> 047 103 383 J 77 Ø	<b>T80471-00</b> N 907 957 01 (5x) +N 907 958 01 (4x) +N 907 956 01 (1x)
1,4 AMF	55 kW (75 PS)	FABIA TDI	04/03-03/08	<b>D36624-00</b> (12)  <b>B32959-00</b> (13) (38)	<b>H09198-00</b> 045 103 383 F 1,45 mm MLS <b>H19198-10</b> 045 103 383 G 1,53 mm MLS <b>H29198-20</b> 045 103 383 H 80,5 Ø 1,61 mm MLS	<b>T09198-00</b> 038 103 384 (8x)
1,4 AUA AUB BBY BBZ BCA BKY	55-74 kW (75-100 PS)	FABIA OCTAVIA	10/99-12/10	<b>D36621-00</b> (12) <b>B32957-00</b> (13) (38) 036 198 011	<b>H80140-00</b> 036 103 383 AM 77,5 Ø MLS	<b>T50943-00</b> 036 103 384 B (10x)
1,4 AXP	55 kW (75 PS)	OCTAVIA	08/00-12/10	<b>D36621-00</b> (12) <b>B32957-00</b> (13) (38) 036 198 011	<b>H80140-00</b> 036 103 383 AM 77,5 Ø MLS	<b>T50943-00</b> 036 103 384 B (10x)

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>X53041-01</b> 047 103 483 NBR	<b>N90300-00</b> 026 109 675 (8x) <b>P76531-00</b> 026 109 675	<b>X51353-01</b> 115-690840	<b>X54065-01</b> 113-090920 Kork	<b>P76230-01 K ←</b> 047 103 085 42x58x8 A SL RD FPM <b>P76355-11 K →</b> 068 103 051 P 85x105x9 A SL LD FPM
<b>X53041-01</b> 047 103 483 NBR	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X81683-01</b> 047 129 717 E	<b>X81438-01 L</b> 047 253 039 H <b>X81439-01</b> 047 253 050 <b>X81682-01 R</b> 047 253 039 J	<b>70-31414-10</b> <b>P76230-01 K ←</b> 047 103 085 42x58x8 A SL RD FPM <b>P77290-01 K →</b> 047 103 085 A 85x105x12 A SL LD FPM
<b>X83111-01</b> 045 103 483 C NBR	<b>N92001-00</b> 027 109 675 (6x) <b>P76532-00</b> 027 109 675	<b>X86491-01</b> 045 129 717	<b>X52968-01</b> 045 253 039 <b>X52970-01</b> 1H0 253 115 A	<b>70-31414-10</b> <b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b>	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X58997-01</b> 036 129 717 E	<b>X51579-01</b> 036 253 039 F	<b>70-31414-10</b> <b>P77313-01 K ←</b> 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR
<b>70-31414-10</b>	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X58997-01</b> 036 129 717 E	<b>X51579-01</b> 036 253 039 F	<b>70-31414-10</b> <b>P77313-01 K ←</b> 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77350-01 K →</b> 030 103 171 K PTFE ① 01/02→ <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR

③ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,4 BMS	59 kW (80 PS) FABIA TDI ROOMSTER	09/06→				
			<b>D37057-00</b> ⑫ 	<b>H09198-00</b> 045 103 383 F 1,45 mm MLS 1 <b>H19198-10</b> 045 103 383 G 1,53 mm MLS 2 <b>H29198-20</b> 045 103 383 H 80,5 Ø 1,61 mm MLS 3	<b>T09198-00</b> 038 103 384 (8x) 	
			<b>B32959-00</b> ⑬ ⑳			
1,4 BNM BNV	51-59 kW (70-80 PS) FABIA TDI ROOMSTER	10/05→				
			<b>D37013-00</b> ⑫ 	<b>H09198-00</b> 045 103 383 F 1,45 mm MLS 1 <b>H19198-10</b> 045 103 383 G 1,53 mm MLS 2 <b>H29198-20</b> 045 103 383 H 80,5 Ø 1,61 mm MLS 3	<b>T09198-00</b> 038 103 384 (8x) 	
			<b>B32959-00</b> ⑬ ⑳			
1,4 BUD BXW	59-63 kW (80-86 PS) FABIA OCTAVIA ROOMSTER	06/04→				
			<b>D36621-00</b> ⑫ <b>B32957-00</b> ⑬ ⑳ 036 198 011	<b>H80140-00</b> 036 103 383 AM 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	
1,4 CAVE CAXC CFB	92-132 kW (125-180 PS) FABIA TSI SUPERB TSI	07/08→				
			<b>S37091-00</b> ⑫ ⑬ ⑳	<b>H80752-00</b> 03C 103 383 R 77,5 Ø MLS 	<b>T80752-00</b> WHT 000 912 (10x) 	
1,4 CAXA CTHE	90-132 kW (122-180 PS) FABIA TSI OCTAVIA TSI RAPID YETI TSI	11/08→				
			<b>S37091-00</b> ⑫ ⑬ ⑳	<b>H80752-00</b> 03C 103 383 R 77,5 Ø MLS 	<b>T80752-00</b> WHT 000 912 (10x) 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X83126-01</b> 045 103 483 E NBR 	<b>N92001-00</b> 027 109 675 (6x) <b>P76532-00</b> 027 109 675	<b>X86491-01</b> 045 129 717 6x 	<b>X81831-01</b> 045 253 039 B 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83111-01</b> 045 103 483 C NBR 	<b>N92001-00</b> 027 109 675 (6x) <b>P76532-00</b> 027 109 675	<b>X86491-01</b> 045 129 717 6x 	<b>X52968-01</b> 045 253 039 <b>X52970-01</b> 1H0 253 115 A 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X58997-01</b> 036 129 717 E 4x 	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K ←</b> 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77376-01 K →</b> 030 103 171 S PTFE <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X87493-01</b> 03C 129 717 C 16x <b>X89175-01</b> ⑩ 4x 03C 129 717 A 	<b>X81446-01</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K →</b> 036 103 171 B PTFE
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X87493-01</b> 03C 129 717 C 16x <b>X89175-01</b> ⑩ 4x 03C 129 717 A 	<b>X81446-01</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K →</b> 036 103 171 B PTFE

⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,4 CGGA	59 kW (80 PS)	OCTAVIA	06/04→	<b>D36621-00</b> ⑫ <b>B32957-00</b> ⑬ ⑳ 036 198 011	<b>H80140-00</b> 036 103 383 AM 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 
1,4 CHPA <b>[NEW]</b>	103 kW (140 PS)	OCTAVIA TSI	11/12→	<b>D38727-00</b> ⑫ <b>B38725-00</b> ⑬ ⑳	<b>H40706-00</b> 04E 103 383 BJ 75 Ø MLS 	<b>T40706-00</b> WHT 004 926 (10x) 
1,6 AEE	55 kW (75 PS)	FELICIA OCTAVIA	08/95-09/04	<b>S32705-00</b> ⑫ ⑬ → AEE 562 757 <b>D32705-00</b> ⑫ 032 198 012 B <b>B32705-00</b> ⑬ 030 198 011 A → AEE 562 757 <b>B32949-00</b> ⑬ ⑳ → AEE 562 758→	<b>H50505-00</b> 030 103 383 AH 77,5 Ø MLS 	<b>T50505-00</b> 032 103 384 (10x) 
1,6 AEH AKL	74 kW (101 PS)	OCTAVIA	02/97-12/07	<b>S32239-00</b> ⑫ ⑬ <b>D32239-00</b> ⑫ 06A 198 012 <b>B32239-00</b> ⑬ ⑳ 06A 198 011	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 

⑫ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала  
 ⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X58997-01</b> 036 129 717 E 4x 	<b>X51579-01</b> 036 253 039 F 	<b>70-31414-10</b> 	<b>P77313-01 K ←</b> 036 103 085 H 32x42x6/7 A SL RD NBR <b>P77479-01 K →</b> 036 103 171 B PTFE <b>P77329-01 N</b> 2x 036 103 085 A 27x42x8 A SL RD NBR
<b>X59930-01</b> 04E 103 483 H 	<b>N93196-00</b> 04E 109 675 (8x) +04E 109 675 A (8x) <b>P76960-00</b> AS 8x 04E 109 675 A <b>P76961-00</b> ES 8x 04E 109 675	<b>X58997-01</b> 036 129 717 E 4x 	<b>X59925-01</b> 04E 253 039 D 	<b>70-31414-10</b> 	<b>P77841-01 K ←</b> 04C 103 085 30x40x7 A SL RD PTFE ACM <b>P77843-01 N ←</b> 2x 04E 103 085 B 36x46x7 A SL RD PTFE ACM <b>P77844-01 N →</b> 04E 103 085 24x39x8 A SL LD PTFE
<b>X53497-01</b> 030 103 483 K NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>M37167-00</b> 030 198 717 	<b>X51584-01</b> 032 253 039 E 	<b>70-31414-10</b> 	<b>P76087-01 K ←</b> 068 103 085 E 32x47x10 A SL WD FPM → AEE 562 757 <b>P77313-01 K ←</b> 036 103 085 H 32x42x6/7 A SL RD NBR → AEE 562 758→ <b>P76355-11 K →</b> 068 103 051 P 85x105x9 A SL LD FPM → AEE 562 757 <b>P77317-01 K →</b> 028 103 171 B PTFE → AEE 562 758→ <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>X53263-01</b> 051 103 483 A ACM 2 Dichtlippen 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X57666-01</b> 06A 133 398 F 4x 	<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K →</b> 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

AS lado de escape / Auslaßseite / exhaust side / côté échappement / lato scarico / сторона выпуска  
 ES lado de admisión / Einlaßseite / intake side / côté admission / lato aspirazione / сторона впуска



SKODA						
Ltr.						
1,6 AVU BFQ	75 kW (102 PS) OCTAVIA	09/00-12/10	<b>D36633-00</b> ⑫ <b>B32936-00</b> ⑬ ⑳	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	
1,6 BGU BSE BSF	75 kW (102 PS) OCTAVIA	06/04→	<b>D36633-00</b> ⑫ <b>B36706-00</b> ⑬ ⑳	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 	
1,6 BLF	85 kW (115 PS) OCTAVIA FSI	02/04-10/08	<b>S36776-00</b> ⑫ ⑬ ⑳ <b>D36776-00</b> ⑫	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	
1,6 BTS	77 kW (105 PS) FABIA ROOMSTER	09/06→	<b>S37014-00</b> ⑫ ⑬ ⑳	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 	
1,6 CAYA CAYB CAYC	55-77 kW (75-105 PS) FABIA TDI RAPID ROOMSTER TDI SUPERB TDI YETI TDI	03/10→	<b>D38310-00</b> ⑫  <b>B38300-00</b> ⑬ ⑳	<b>H40582-00</b> 03L 103 383 J 80,5 Ø 1,55 mm 1 □ MLS <b>H40582-10</b> 03L 103 383 K 80,5 Ø 1,63 mm 2 □ MLS <b>H40582-20</b> 03L 103 383 L 80,5 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	

⑫ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора  
 ⑬ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>X83001-01</b> 06B 103 483 L NBR 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675 8x	<b>X57666-01</b> 06A 133 398 F 4x 	<b>X52965-01</b> 06A 253 039 L  <b>X07867-01</b> ✕ 533 253 115 D 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K →</b> 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83001-01</b> 06B 103 483 L NBR 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675 8x	<b>X57666-01</b> 06A 133 398 F 4x  <b>X88303-01</b> ⑩ 4x 06A 133 227 B 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77352-01 K →</b> 06B 103 171 E <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X87493-01</b> 03C 129 717 C  <b>X89175-01</b> ⑩ 4x 03C 129 717 A 	<b>X81446-01</b> 03C 253 039 D  <b>X52978-01</b> 1J0 253 115 S	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77376-01 K →</b> 030 103 171 S PTFE
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X58997-01</b> 036 129 717 E 4x 	<b>X81446-01</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM
<b>V59484-01</b> 03L 103 483 H +03L 103 070 A (4x)  <b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59484-01</b> 03L 103 483 H  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59477-01</b> 03L 129 717 J 4x  <b>X59479-01</b> 03L 129 717 H 4x 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM

⑩ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,6 CAYC	06/09→	77 kW (105 PS)	OCTAVIA TDI	<b>D38310-00</b> <sup>12</sup> 10/09→  <b>B38300-00</b> <sup>13 35</sup>	<b>H40582-00</b> 03L 103 383 J 80,5 Ø 1,55 mm MLS 1 □	<b>T50034-00</b> WHT 002 131 (10x) 
1,6 CCSA CHGA CMXA	06/04→	75 kW (102 PS)	OCTAVIA	<b>D36633-00</b> <sup>12</sup> <b>B32936-00</b> <sup>13 35</sup>	<b>H50474-00</b> 06B 103 383 H 82,5 Ø 1,2 mm MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 
1,6 CDE CDF		77 kW (105 PS)		<b>S80752-00</b> <sup>12 13 38</sup>	<b>H80752-00</b> 03C 103 383 R 77,5 Ø MLS 	<b>T59457-00</b> WHT 000 675 (10x) 
1,6 CFNA <b>[NEW]</b>	09/06→	77 kW (105 PS)	FABIA RAPID ROOMSTER	<b>S37014-00</b> <sup>12 13 38</sup>	<b>H80622-00</b> 03C 103 383 D 77,5 Ø MLS 	<b>T50943-00</b> 036 103 384 B (10x) 

⑫ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>V59484-01</b> 03L 103 483 H +03L 103 070 A (4x) 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59477-01</b> 03L 129 717 J 4x 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM 10/09→ <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM 10/09→
<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x) 		<b>X59479-01</b> 03L 129 717 H 4x 			
<b>X59484-01</b> 03L 103 483 H 					
<b>X59500-01</b> 03L 103 483 C 					
<b>X83001-01</b> 06B 103 483 L NBR 	<b>N92991-00</b> 036 109 675 (8x) <b>P76662-00</b> 036 109 675 8x	<b>X57666-01</b> 06A 133 398 F 4x 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K →</b> 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X82517-01</b> 03C 253 039 E 	<b>70-31414-10</b> 		<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X58997-01</b> 036 129 717 E 4x 	<b>X81446-01</b> 03C 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K →</b> 036 103 171B PTFE

⑬ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач





SKODA						
Ltr.						
1,6 CLHA CLHB CRKB	66-81 kW (90-110 PS) OCTAVIA TDI	11/12→				
<b>[NEW]</b>			<b>D38750-00</b> (12) 	<b>H40700-00</b> 04L 103 383 C 80,5 Ø 1,55 mm MLS 1 □ <b>H40700-10</b> 04L 103 383 D 80,5 Ø 1,63 mm MLS 2 □ <b>H40700-20</b> 04L 103 383 E 80,5 Ø 1,71 mm MLS 3 □ 	<b>T40709-00</b> WHT 005 673 (10x) 	
1,6 CLSA	77 kW (105 PS)		<b>S80752-00</b> (12 13 38) 	<b>H80752-00</b> 03C 103 383 R 77,5 Ø MLS 	<b>T59457-00</b> WHT 000 675 (10x) 	
1,8 ADR	92 kW (125 PS)		<b>S32232-00</b> (12 13) <b>D32232-00</b> (12) <b>B32232-00</b> (13) <b>B37030-00</b> (13 35) 	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T10468-00</b> 058 103 385 A (10x) 	
1,8 AGN	92 kW (125 PS) OCTAVIA →1U V 040 000 09/96-07/00		<b>D32240-00</b> (12) 06A 198 012 A <b>B32934-00</b> (13 38) 06A 198 011 A <b>Z36190-00</b> (8) 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T80109-00</b> 06A 103 385 C (10x) →AGN 107 000  <b>T50468-00</b> 06A 103 385 A (10x) →AGN 107 001→ 	
1,8 AGN	92 kW (125 PS) OCTAVIA →1U W 000 001→ 09/96-07/00		<b>D36707-00</b> (12) <b>B32934-00</b> (13 38) 06A 198 011 A <b>Z36190-00</b> (8) 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T80109-00</b> 06A 103 385 C (10x) →AGN 107 000  <b>T50468-00</b> 06A 103 385 A (10x) →AGN 107 001→ 	

⑫ junta para tensor cadena de distribución / Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала

③⑤ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>V59933-00</b> 03L 103 483 S +04L 103 070 (4x) 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59929-01</b> 04L 129 717 B 	<b>X59927-01</b> 04L 253 039 B 	<b>70-31414-10</b> 	<b>P77831-01 K</b> → 04L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>X59933-01</b> 03L 103 483 S 					
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X58997-01</b> 036 129 717 E 4x 	<b>X82517-01</b> 03C 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77479-01 K</b> → 036 103 171 B PTFE
<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675 20x	<b>X57659-01</b> 058 129 717 B 		<b>X54226-01</b> Aluminium 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM <b>P77317-01 K</b> → 028 103 171 B PTFE <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM
<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675 20x	<b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L  <b>X07867-01</b> 533 253 115 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675 20x	<b>X88304-01</b> 06A 133 398 D 4x 	<b>X51632-01</b> 058 253 039 L  <b>X07867-01</b> 533 253 115 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM

③⑤ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.			<b>1</b>			
1,8 AGU ARX ARZ AUM AUQ AWT	110-132 kW (150-180 PS) OCTAVIA T SUPERB T	08/97-12/10	<b>D32240-00</b> ⑫ 06A 198 012 A <b>B32934-00</b> ⑬ ⑳ 06A 198 011 A <b>Z36190-00</b> ⑧ 058 198 217	<b>H50468-00</b> 058 103 383 Q 82,5 Ø MLS 	<b>T50468-00</b> 06A 103 385 A (10x) 	
1,8 BZB	118 kW (160 PS) OCTAVIA TSI SUPERB TSI	06/07→	<b>D40567-00</b> ⑫ <b>B38289-00</b> ⑬ ㉓	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T80727-00</b> 06D 103 385 D (10x) 	
1,8 CDA CDAB	112-118 kW (152-160 PS) OCTAVIA TSI SUPERB TSI YETI TSI	06/07→	<b>D40567-00</b> ⑫ <b>B38289-00</b> ⑬ ㉓	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x)  <b>T80727-00</b> 06D 103 385 D (10x) 	
1,9 AEF	47 kW (64 PS) FELICIA D	10/95-04/02	<b>D32719-00</b> ⑫ 028 198 012 E → AEF 007 001→  <b>B32231-00</b> ⑬ 028 198 011 D → AEF265 000  <b>B37015-00</b> ⑬ ㉓ → AEF265 001→ 	<b>H02391-00</b> 028 103 383 BH 1,53 mm 1 MLS <b>H12391-10</b> 028 103 383 BJ 1,57 mm 2 MLS <b>H22391-20</b> 028 103 383 BK 81 Ø 1,61 mm 3 MLS 	<b>T02673-00</b> 068 103 384 A (10x) 	
1,9 AEY	47 kW (64 PS)		<b>D32721-00</b> ⑫ 028 198 012 F  <b>B32231-00</b> ⑬ 028 198 011 D → AEY 050 000  <b>B37015-00</b> ⑬ ㉓ → AEY 050 001→ 	<b>H02392-00</b> 028 103 383 BL 1,45 mm 1 MLS <b>H12392-10</b> 028 103 383 BM 1,53 mm 2 MLS <b>H22392-20</b> 028 103 383 BN 81 Ø 1,61 mm 3 MLS 	<b>T02673-00</b> 068 103 384 A (10x) 	

⑫ junta para tensor cadena de distribución / Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала  
 ⑬ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>V53271-00</b> 058 198 025 A 	<b>N90298-00</b> 036 109 675 (20x) <b>P76662-00</b> 036 109 675 20x	<b>X57659-01</b> 058 129 717 B 	<b>X51632-01</b> 058 253 039 L <b>X07867-01</b> 533 253 115 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X89272-01</b> 06J 129 717 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77451-01 K</b> ← 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K</b> → 06H 103 171 F 85x132/152x15,7 PTFE
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X89272-01</b> 06J 129 717  <b>X89273-01</b> 06F 129 717 D 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77451-01 K</b> ← 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K</b> → 06H 103 171 F 85x132/152x15,7 PTFE
<b>V31598-00</b> 028 198 025 	<b>N91190-00</b> 027 109 675 (8x) → AEF 007 001→ <b>P76532-00</b> 027 109 675 → AEF 007 001→ 8x	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 4x 026 129 589 A  <b>X51947-01</b> 037 253 039 	<b>X54361-01</b> 037 115 220 B NBR  <b>X54624-01</b> 044 103 609 D ACM 	<b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM → AEF265 000 <b>P77317-01 K</b> → 028 103 171 B PTFE → AEF 265 001→ <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>V32231-00</b> 028 103 483 G +028 103 532 A (3x) +028 103 533 (3x) 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X55431-01</b> 028 129 717 D 	<b>X03747-01</b> 4x 026 129 589 A 	<b>X54624-01</b> 044 103 609 D ACM 	<b>P76087-01 K</b> ← 068 103 085 E 32x47x10 A SL WD FPM <b>P76355-11 K</b> → 068 103 051 P 85x105x9 A SL LD FPM → AEY 050 000 <b>P77317-01 K</b> → 028 103 171 B PTFE → AEY 050 001→ <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

⑳ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA										
Ltr.										
1,9 AGP	50 kW (68 PS) OCTAVIA SDI	06/97-12/03	<b>S32241-00</b> <sup>(12)</sup> <sup>(13)</sup>  <b>D32241-00</b> <sup>(12)</sup> 038 198 012  <b>B32241-00</b> <sup>(13)</sup> <sup>(38)</sup> 038 198 011 	<b>H06033-00</b> 038 103 383 G 1,45 mm 1 → AGP 028 000 <b>H16033-10</b> 038 103 383 F 1,53 mm 2 → AGP 028 000 <b>H26033-20</b> 038 103 383 E 80,5 ∅ 1,61 mm 3 → AGP 028 000  <b>H03518-00</b> 038 103 383 AL 1,47 mm 1 → AGP 028 001→ <b>H13518-10</b> 038 103 383 AM 1,57 mm 2 → AGP 028 001→ <b>H23518-20</b> 038 103 383 AN 80,5 ∅ 1,67 mm 3 → AGP 028 001→ 	<b>T02673-00</b> 068 103 384 A (10x) 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X03747-01</b> 4x 026 129 589 A  <b>X51638-01</b> 037 253 039 D  <b>X51706-01</b> 3A0 253 115  <b>X52970-01</b> 1H0 253 115 A 	<b>70-31414-10</b> 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

<sup>(38)</sup> sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA												
Ltr.	1.9 AGR	66 kW (90 PS)	OCTAVIA TDI	09/96-03/10								
					<b>S32241-00</b> <sup>12</sup> <sup>13</sup>  <b>D32241-00</b> <sup>12</sup> 038 198 012  <b>B32241-00</b> <sup>13</sup> <sup>38</sup> 038 198 011 	<b>H06033-00</b> 038 103 383 G 1,45 mm 1 MLS → AGR 151 000 <b>H16033-10</b> 038 103 383 F 1,53 mm 2 MLS → AGR 151 000 <b>H26033-20</b> 038 103 383 E 80,5 ∅ 1,61 mm 3 MLS → AGR 151 000  <b>H03518-00</b> 038 103 383 AL 1,47 mm 1 MLS → AGR 151 001→ <b>H13518-10</b> 038 103 383 AM 1,57 mm 2 MLS → AGR 151 001→ <b>H23518-20</b> 038 103 383 AN 80,5 ∅ 1,67 mm 3 MLS → AGR 151 001→ 	<b>T02673-00</b> 068 103 384 A (10x) 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X03747-01</b> 4x 026 129 589 A  <b>X51638-01</b> 037 253 039 D  <b>X51706-01</b> 3A0 253 115  <b>X52970-01</b> 1H0 253 115 A 	<b>70-31414-10</b> 	<b>P76096-01 K</b> ← 054 115 147 B 35x48x10 A SL RD FPM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM

<sup>38</sup> sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,9 AHF	81 kW (110 PS) OCTAVIA TDI	08/97-01/06	<b>S32241-00</b> 038 198 012	<b>H06033-00</b> 038 103 383 G 1,45 mm 1 MLS → AHF 140 000 <b>H16033-10</b> 038 103 383 F 1,53 mm 2 MLS → AHF 140 000 <b>H26033-20</b> 038 103 383 E 80,5 Ø 1,61 mm 3 MLS → AHF 140 000 	<b>T02673-00</b> 068 103 384 A (10x) 	
			<b>D32241-00</b> 038 198 012	<b>H03518-00</b> 038 103 383 AL 1,47 mm 1 MLS → AHF 140 001→ <b>H13518-10</b> 038 103 383 AM 1,57 mm 2 MLS → AHF 140 001→ <b>H23518-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS → AHF 140 001→ 		
			<b>B32241-00</b> 038 198 011			
1,9 ALH ASV	66-81 kW (90-110 PS) OCTAVIA TDI	09/96-03/10	<b>S32241-00</b> 038 198 012	<b>H03518-00</b> 038 103 383 AL 1,47 mm 1 MLS <b>H13518-10</b> 038 103 383 AM 1,57 mm 2 MLS <b>H23518-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS 	<b>T02673-00</b> 068 103 384 A (10x) 	
			<b>D32241-00</b> 038 198 012			
			<b>B32241-00</b> 038 198 011			

<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X03747-01</b> 026 129 589 A <b>X51638-01</b> 037 253 039 D <b>X51706-01</b> 3A0 253 115 <b>X52970-01</b> 1H0 253 115 A	4x <b>70-31414-10</b>	<b>P76096-01 K ←</b> 054 115 147 B 35x48x10 A SL RD FPM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	
<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X03747-01</b> 026 129 589 A <b>X51638-01</b> 037 253 039 D <b>X51706-01</b> 3A0 253 115 <b>X52970-01</b> 1H0 253 115 A	4x <b>70-31414-10</b>	<b>P76096-01 K ←</b> 054 115 147 B 35x48x10 A SL RD FPM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM	

Ⓢ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,9 AQM	50 kW (68 PS)	OCTAVIA SDI	06/97-12/03	<b>D37016-00</b> <sup>(12)</sup>  <b>B32241-00</b> <sup>(13) (38)</sup> 038 198 011 	<b>H03518-00</b> 038 103 383 AL 1,47 mm 1 MLS <b>H13518-10</b> 038 103 383 AM 1,57 mm 2 MLS <b>H23518-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS 	<b>T02673-00</b> 068 103 384 A (10x) 
1,9 ASY	47 kW (64 PS)	FABIA SDI	11/99-03/08	<b>D32937-00</b> <sup>(12)</sup>  <b>B32937-00</b> <sup>(13) (35)</sup> 	<b>H03518-00</b> 038 103 383 AL 1,47 mm 1 MLS <b>H13518-10</b> 038 103 383 AM 1,57 mm 2 MLS <b>H23518-20</b> 038 103 383 AN 80,5 Ø 1,67 mm 3 MLS 	<b>T02673-00</b> 068 103 384 A (10x) 
1,9 ASZ ATD AVB AVF AWX AXR BLT BPZ BSV BSW	74-96 kW (100-130 PS)	FABIA TDI OCTAVIA TDI ROOMSTER ROOMSTER TDI SUPERB TDI	01/00→	<b>D32937-00</b> <sup>(12)</sup>  <b>B32937-00</b> <sup>(13) (35)</sup> 	<b>H09538-00</b> 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS <b>H19538-10</b> 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS <b>H29538-20</b> 038 103 383 DG 80,5 Ø 1,61 mm 3 MLS 	<b>T03518-00</b> 038 103 384 (10x) 

<sup>(35)</sup> contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X51638-01</b> 037 253 039 D <b>X81385-01</b> 155 253 115 	<b>70-31414-10</b> 	<b>P76096-01 K ←</b> 054 115 147 B 35x48x10 A SL RD FPM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P76087-01 N</b> 068 103 085 E 32x47x10 A SL WD FPM
<b>X53715-01</b> 038 103 483 D ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X03747-01</b> 4x 026 129 589 A  <b>X51638-01</b> 037 253 039 D  <b>X81385-01</b> 155 253 115 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X53715-01</b> 038 103 483 D ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x	<b>X03747-01</b> 4x 026 129 589 A  <b>X51638-01</b> 037 253 039 D  <b>X51706-01</b> 3A0 253 115	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

<sup>(38)</sup> sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



SKODA						
Ltr.						
1,9 BJB BKC BXE	77 kW (105 PS) OCTAVIA TDI SUPERB TDI	06/04-12/10		<b>D32937-00</b> <sup>(12)</sup>  <b>B36708-00</b> <sup>(13) (35)</sup>	<b>H09538-00</b> 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS <b>H19538-10</b> 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS <b>H29538-20</b> 038 103 383 DG 80,5 Ø 1,61 mm 3 MLS	<b>T03518-00</b> 038 103 384 (10x) 
1,9 BLS	77 kW (105 PS) FABIA TDI OCTAVIA TDI ROOMSTER SUPERB TDI	06/04→		<b>D37051-00</b> <sup>(12)</sup>  <b>B36708-00</b> <sup>(13) (35)</sup>	<b>H09538-00</b> 038 103 383 DE 80,5 Ø 1,45 mm 1 MLS <b>H19538-10</b> 038 103 383 DF 80,5 Ø 1,53 mm 2 MLS <b>H29538-20</b> 038 103 383 DG 80,5 Ø 1,61 mm 3 MLS	<b>T03518-00</b> 038 103 384 (10x) 
2,0 AEG	85 kW (116 PS) OCTAVIA	04/99-05/07		<b>B32937-00</b> <sup>(13) (35)</sup>	<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 
2,0 APK AQY AZH	85 kW (116 PS) FABIA OCTAVIA	04/99-03/08		<b>D36646-00</b> <sup>(12)</sup> <b>B32937-00</b> <sup>(13) (35)</sup>	<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 

<sup>(12)</sup> junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



<b>X53715-01</b> 038 103 483 D ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x 	<b>X51638-01</b> 037 253 039 D <b>X51706-01</b> <sup>(10)</sup> 3A0 253 115 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K →</b> 038 103 171 S PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83120-01</b> 03G 103 483 D NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x 	<b>X81833-01</b> 03G 253 039 A 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K →</b> 038 103 171 S PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X53809-01</b> 06A 103 483 C NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X75011-01</b> 06A 129 717 D 4x 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X53809-01</b> 06A 103 483 C NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X57668-01</b> 037 129 717 C <b>X52681-01</b> <sup>(10)</sup> 06A 129 717 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

<sup>(35)</sup> contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



SKODA						
2,0 AZJ	85 kW (116 PS)	OCTAVIA	04/99-05/07	<b>B32937-00</b> <sup>13 35</sup>	<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 
2,0 AZL	85 kW (116 PS)	FABIA	12/99-03/08	<b>D36712-00</b> <sup>12</sup> <b>B32937-00</b> <sup>13 35</sup>	<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 
2,0 AZM	85 kW (115 PS)	SUPERB	12/01-03/08	<b>D37017-00</b> <sup>12</sup> <b>B32937-00</b> <sup>13 35</sup>	<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 
2,0 AZV BKD	100-103 kW (136-140 PS)	OCTAVIA TDI SUPERB TDI	02/04→	<b>D36710-00</b> <sup>12</sup>  <b>B36708-00</b> <sup>13 35</sup>	<b>H08124-00</b> 03G 103 383 1,55 mm MLS 1 <b>H18124-10</b> 03G 103 383 A 1,63 mm MLS 2 <b>H28124-20</b> 03G 103 383 B 82 Ø 1,7 mm MLS 3 	<b>T08124-00</b> 03G 103 384 (10x) 
2,0 BLR BLX BLY BVX BVY BVZ	110 kW (150 PS)	OCTAVIA FSI	11/04→	<b>D37018-00</b> <sup>12</sup> <b>B36711-00</b> <sup>13 38</sup>	<b>H80451-00</b> 06D 103 383 L 84 Ø MLS 	<b>T80450-00</b> 06D 103 385 (10x) 

<sup>12</sup> junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора

<sup>35</sup> contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>X53809-01</b> 06A 103 483 C NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X57666-01</b> 06A 133 398 F 4x <b>X88303-01</b> <sup>10</sup> 06A 133 227 B 4x 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X53809-01</b> 06A 103 483 C NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X57668-01</b> 037 129 717 C <b>X52681-01</b> <sup>10</sup> 06A 129 717 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X53263-01</b> 051 103 483 A ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675 8x	<b>X87424-01</b> 06B 129 717 A 4x 	<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K</b> → 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83030-01</b> 03G 103 483 NBR 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X87466-01</b> 03G 129 717 B <b>X89274-01</b> 03G 129 717 C 	<b>X81685-01</b> 03G 253 039 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K</b> → 038 103 171 S PTFE <b>P77181-01 N</b> 2x 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83112-01</b> 06D 103 483 E NBR 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X88306-01</b> 06D 129 717 D 	<b>X81686-01</b> 06B 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K</b> ← 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77318-01 K</b> → 06B 103 171 B 85x131/152x15,7 Aluminium PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM

<sup>38</sup> sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач





SKODA						
Ltr.						
2,0 BMM BMP	103 kW (140 PS) OCTAVIA TDI SUPERB TDI	11/05→	 <b>D37051-00</b> (12)  <b>B36708-00</b> (13 35)	<b>H08008-00</b> 038 103 383 CP 1,45 mm 1 MLS <b>H18008-10</b> 038 103 383 CQ 1,53 mm 2 MLS <b>H28008-20</b> 038 103 383 CR 82 Ø 1,61 mm 3 	<b>T03518-00</b> 038 103 384 (10x) 	
2,0 BMN	125 kW (170 PS) OCTAVIA TDI	04/06→	 <b>D37052-00</b> (12)  <b>B36708-00</b> (13 35)	<b>H08124-00</b> 03G 103 383 1,55 mm 1 MLS <b>H18124-10</b> 03G 103 383 A 1,63 mm 2 MLS <b>H28124-20</b> 03G 103 383 B 82 Ø 1,7 mm 3 	<b>T08124-00</b> 03G 103 384 (10x) 	
2,0 BSS BWW	91-103 kW (124-140 PS) SUPERB TDI	10/05→	 <b>D32937-00</b> (12)  <b>B32937-00</b> (13 35)	<b>H08008-00</b> 038 103 383 CP 1,45 mm 1 MLS <b>H18008-10</b> 038 103 383 CQ 1,53 mm 2 MLS <b>H28008-20</b> 038 103 383 CR 82 Ø 1,61 mm 3 	<b>T03518-00</b> 038 103 384 (10x) 	
2,0 BWA	147 kW (200 PS) OCTAVIA RS	10/05→	 <b>D37050-00</b> (12)  <b>B36707-00</b> (13 35)	<b>H80449-00</b> 06F 103 383 G 83,5 Ø MLS 	<b>T80727-00</b> 06D 103 385 D (10x) 	

35 contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>X83120-01</b> 03G 103 483 D NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x 	<b>X81833-01</b> 03G 253 039 A 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77353-11 K →</b> 038 103 171 S PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83121-01</b> 03G 103 483 C NBR 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X87466-01</b> 03G 129 717 B <b>X89274-01</b> 03G 129 717 C 16x 	<b>X81981-01</b> 03G 253 039 C 		<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM 2x
<b>X53715-01</b> 038 103 483 D ACM 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	<b>X55431-01</b> 028 129 717 D 8x 	<b>X51638-01</b> 037 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>X83119-01</b> 06F 103 483 D NBR 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	<b>X89273-01</b> 06F 129 717 D 16x 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM



SKODA						
Ltr.						
2,0 CBBB CBDB CEGA	103-125 kW (140-170 PS) OCTAVIA TDI SUPERB TDI YETI TDI	04/06→	 <b>D38107-00</b> ⑫  <b>B38109-00</b> ⑬ ⑮	<b>H01461-00</b> 03L 103 383 82 Ø 1,55 mm 1 □ MLS <b>H11461-10</b> 03L 103 383 A 82 Ø 1,63 mm 2 □ MLS <b>H21461-20</b> 03L 103 383 B 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	
2,0 CCZA	147 kW (200 PS) OCTAVIA RS SUPERB TSI	10/05→	<b>D40567-00</b> ⑫ <b>B38289-00</b> ⑬ ⑮	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T40708-00</b> WHT 005 305 (10x)  <b>T80727-00</b> 06D 103 385 D (10x) 	
2,0 CFFB CFHA CFHC CFHF CFJA CLCA CLCB CLJA	81-125 kW (110-170 PS) OCTAVIA TDI SUPERB TDI YETI TDI	02/04→	 <b>D38308-00</b> ⑫  <b>B38299-00</b> ⑬ ⑮	<b>H40584-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 □ MLS <b>H40584-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 □ MLS <b>H40584-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	
2,0 CFGB <b>[NEW]</b>	125 kW (170 PS) SUPERB TDI	07/08→	 <b>D38731-00</b> ⑫  <b>B38299-01</b> ⑬ ⑮	<b>H40584-00</b> 03L 103 383 BM 82 Ø 1,55 mm 1 □ MLS <b>H40584-10</b> 03L 103 383 BN 82 Ø 1,63 mm 2 □ MLS <b>H40584-20</b> 03L 103 383 BP 82 Ø 1,71 mm 3 □ MLS 	<b>T50034-00</b> WHT 002 131 (10x) 	

⑮ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>X83360-01</b> 03L 103 483 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X89884-01</b> 03L 129 717 	<b>X81685-01</b> 03G 253 039 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X89273-01</b> 06F 129 717 D 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 	<b>P77451-01 K ←</b> 06H 103 383 G 45x60x8 AB SL RD FPM <b>P77754-01 K →</b> 06H 103 171 F 85x132/152x15,7 PTFE
<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59474-01</b> 03L 129 717 E 	<b>X59496-01</b> 03L 253 039 E 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM
<b>V59500-00</b> 03L 103 483 C +03L 103 070 (4x)  <b>X59500-01</b> 03L 103 483 C 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675 16x	<b>X59474-01</b> 03L 129 717 E 	<b>X59891-01</b> 04L 253 039 D 	<b>70-31414-10</b> 	<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77689-01 K →</b> 03L 103 171 PTFE <b>P77774-01 N</b> 03L 103 085 32x47x10 A RD FPM

⑮ sin retén en el lado de la transmisión / ohne Wedi Getriebes. / without shaft seal at gearbox end / sans bague d'étanchéité côté boîte de vitesse / senza paraolio per albero trasmissione lato cambio / без уплотнения вала со стороны коробки передач



<b>SKODA</b>							
Ltr.				1			
2,0 CGM	147 kW (200 PS)				<b>D40567-00</b> <sup>(12)</sup>	<b>H40567-00</b> 06H 103 383 AC 83 Ø MLS 	<b>T80727-00</b> 06D 103 385 D (10x) 
2,0 CGZ	88 kW (120 PS)					<b>H80098-00</b> 06A 103 383 AN 83,5 Ø MLS 	<b>T50474-00</b> 06A 103 384 C (10x) 
2,5 AYM	114 kW (155 PS) SUPERB TDI	12/01-08/03			<b>D32940-00</b> <sup>(12)</sup> 	<b>H03136-00</b> 2x 059 103 383 BQ 1,1 mm MLS <b>H13136-10</b> 2x 059 103 383 BR 1,15 mm MLS <b>H23136-20</b> 2x 059 103 383 BS 79 Ø 1,2 mm MLS 	<b>T03136-00</b> 059 103 384 (16x) 
					<b>B32940-00</b> <sup>(13)</sup> 		
2,5 BDG	120 kW (163 PS) SUPERB TDI	06/03-03/08			<b>D32940-00</b> <sup>(12)</sup> 	<b>H03136-00</b> 2x 059 103 383 BQ 1,1 mm MLS <b>H13136-10</b> 2x 059 103 383 BR 1,15 mm MLS <b>H23136-20</b> 2x 059 103 383 BS 79 Ø 1,2 mm MLS 	<b>T80448-00</b> 057 103 384 A (16x) 
					<b>B32940-00</b> <sup>(13)</sup> 		
2,8 AMX	142 kW (193 PS) SUPERB	12/01-03/08			<b>D36715-00</b> 2x 078 198 012 F +068 103 085 E (2x) <b>Z36190-00</b> <sup>(8)</sup> 2x 058 198 217	<b>H80491-00</b> 2x 078 103 383 L 83,5 Ø MLS 	<b>T50999-00</b> 078 103 385 K (16x) 

Ⓢ junta para tensor cadena de distribución / Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала



<b>70-31414-10</b> 	<b>N92990-00</b> 036 109 675 (16x) <b>P76662-00</b> 036 109 675	16x 	<b>X89273-01</b> 06F 129 717 D 	<b>X81829-01</b> 06F 253 039 F 	<b>70-31414-10</b> 
<b>X53809-01</b> 06A 103 483 C NBR 	<b>N91190-00</b> 027 109 675 (8x) <b>P76532-00</b> 027 109 675	8x 	<b>X75011-01</b> 4x 06A 129 717 D 	<b>X52965-01</b> 06A 253 039 L 	<b>70-31414-10</b> 
<b>V32940-00</b> 2x 059 198 025 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	24x 	<b>X58943-01</b> 2x 059 129 717 G 	<b>X52307-01</b> 6x 059 253 039 B <b>X52930-01</b>	<b>70-31414-10</b> 
<b>V32940-00</b> 2x 059 198 025 	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	24x 	<b>X58943-01</b> 2x 059 129 717 G 	<b>X52307-01</b> 6x 059 253 039 B <b>X52930-01</b>	<b>70-31414-10</b> 
<b>V53716-00</b> 2x 078 198 025 	<b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675	30x 	<b>X58942-01</b> 2x 078 129 717 J 	<b>X52308-01</b> 2x 078 253 039 G 	<b>70-31414-10</b> 
					<b>P77451-01 K ←</b> 06H 103 383 G 45x60x8 AB SL RD FPM
					<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P77183-01 K →</b> 06A 103 171 A 85x131/152x15,7 PTFE <b>P77181-01 N</b> 038 103 085 A 32x47x10 A SL RD PTFE ACM
					<b>P76096-01 K ←</b> 054 115 147 B 35x48x10 A SL RD FPM <b>P77440-01 K →</b> 070 103 051 A 85x105x12 A SL LD PTFE <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM
					<b>P76096-01 K ←</b> 054 115 147 B 35x48x10 A SL RD FPM <b>P77440-01 K →</b> 070 103 051 A 85x105x12 A SL LD PTFE <b>P76087-01 N</b> 2x 068 103 085 E 32x47x10 A SL WD FPM
					<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P76087-01 N</b> 4x 068 103 085 E 32x47x10 A SL WD FPM



SKODA						
Ltr.						
2,8 BBG	140 kW (190 PS) SUPERB V6	06/02-03/08	<b>D36715-00</b> 078 198 012 F +068 103 085 E (2x) <b>Z36190-00</b> ⑧ 058 198 217	2x <b>H80491-00</b> 078 103 383 L 83,5 Ø MLS	2x <b>T50999-00</b> 078 103 385 K (16x)	
3,6 CDVA	191 kW (260 PS) SUPERB	11/08→	<b>D37064-01</b> ⑫	<b>H80734-00</b> 85 Ø MLS	<b>T80734-00</b>	

<b>V53716-00</b> 078 198 025	<b>N92633-00</b> 036 109 675 (30x) <b>P76662-00</b> 036 109 675	<b>X58942-01</b> 078 129 717 J	<b>X52308-01</b> 078 253 039 G		<b>P76096-11 K ←</b> 038 103 085 E 35x48x10 A SL RD PTFE ACM <b>P76087-01 N</b> 4x 068 103 085 E 32x47x10 A SL WD FPM
2x 	30x 	2x 	2x 		
<b>X83128-01</b> NBR	<b>N92830-00</b> 036 109 675 (24x) <b>P76662-00</b> 036 109 675	<b>X89886-01</b> 03H 133 237 D	<b>X82352-01</b> Zyl. 1-3 <b>X82353-01</b> Zyl. 4-6	<b>70-31414-10</b>	<b>P77354-01 K →</b> 021 103 051 C 85x105x11 A SL LD PTFE ACM
	24x 				

⑧ junta para tensor cadena de distribución / Dichtung Steuerkettenspanner / gasket timing chain tensioner / joint tendeur de chaîne / guarnizione tendicatena di distribuzione / прокладка натяжителя цепи привода распределительного вала

