



**mitsubishi**

 Code 

**0-9**

3A91 ..... 964

4A20 ..... 978

4A90 ..... 964

4A91 ..... 968

4A92 ..... 970

4B10 ..... 972

4D30 ..... 988

4D31T ..... 988

4D55 ..... 980

4D55T ..... 980

4D56 ..... 982

4D56 T ..... 982

4D56 TD ..... 982



4D65 ..... 972

4D65 T ..... 974

4D68 ..... 978

4D68 (SOHC) ..... 978

4D68 T ..... 978

 Code 

4G11 ..... 964

4G12 ..... 966

4G13 ..... 964

4G13 (12 V) ..... 964-966

4G13 (16 V) ..... 966

4G15 ..... 966

4G15 (12V) ..... 968

4G15T ..... 968

4G18 ..... 970

4G32 ..... 968-972

4G37 ..... 972-974

4G54 ..... 984

4G61 ..... 972

4G63 ..... 978-980



4G63 (DOHC 16V) ..... 980

4G63K ..... 978

4G67 ..... 974

4G69 ..... 980

4G92 ..... 972

 Code 

4G93 ..... 974

4G93 GDI ..... 976

4M40 ..... 984

4M40-2AT ..... 984

4M40-A ..... 984

4M41 ..... 986

4N13 ..... 976

6A12 ..... 980

6A13 ..... 982

6G72 ..... 986

6G73 ..... 982

**B**



BSY ..... 976

**F**

F8QT ..... 976

F9Q ..... 976

F9Q2 ..... 976

 Code 

**G**

G11B ..... 964

G12B ..... 966

G13B ..... 964

G15B ..... 966

G32B ..... 968

G32B Turbo ..... 968

G37B ..... 972

G54B T/C ..... 984

G63B ..... 978

G63B Turbo ..... 978

G6AT ..... 986

**O**

OM639 ..... 968

**mitsubishi**

 Code 

 Code 

 Code 

 Code 

MITSUBISHI						
Ltr.						
1,1 3A91	55 kW (75 PS) COLT	10/04→	<b>S38056-00</b> ⑫ 	<b>H80697-00</b> MN195371 76 Ø 		
1,2 G11B 4G11	40 kW (54-55 PS) COLT LANCER	12/78-01/84	<b>S80885-00</b> ⑫ ⑬ MD997039 <b>D80885-00</b> ⑫ MD997012	<b>H80885-10</b> MD030290 72,5 Ø 		
1,3 G13B	49-51 kW (67-70 PS) COLT LANCER	06/86-05/92	<b>S80926-00</b> ⑫ ⑬ MD997112 <b>D80926-00</b> ⑫ MD997108	<b>H80926-00</b> MD174496 72,5 Ø 	<b>T40328-00</b> MD008769 (10x) 	
1,3 4A90	70 kW (95 PS) COLT	06/04→	<b>S38055-00</b> ⑫ 	<b>H80698-00</b> MN195370 76 Ø 		
1,3 4G13	60 kW (82 PS) COLT	09/00-09/03	<b>S40041-01</b> ⑫ ⑬ MD978013 <b>D40041-01</b> ⑫ MD978012	<b>H40041-00</b> MD351292 72 Ø MLS 		
1,3 4G13 (12 V)	55 kW (75 PS) COLT	04/88-05/92	<b>S80926-01</b> ⑫ ⑬ MD974614 ① →05/90  <b>D80926-01</b> ⑫ MD974613 ① →05/90	<b>H80926-00</b> MD174496 72,5 Ø ① →05/90  <b>H80979-00</b> MD323473 76,5 Ø ① 06/90→ 	<b>T40328-00</b> MD008769 (10x) 	
1,3 4G13 (12 V)	55 kW (75 PS) COLT LANCER	04/92-12/96		<b>H80979-00</b> MD323473 76,5 Ø 	<b>T40328-00</b> MD008769 (10x) ① →04/95 	



<b>X83364-01</b> MN158378 	<b>N92114-00</b> MR984262 (12x) <b>P76707-00</b> MR984262 12x	<b>X89885-01</b> MN149030 3x 	<b>X81917-01</b> MN163442 	<b>70-31414-10</b> 	<b>P77349-01 K ←</b> MN195668 30x48x6,5 A RD
<b>X83192-01</b> MD030282 		<b>M37912-00</b> MD151902 +MD151903 	<b>X82156-01</b> MD030468 	<b>X54863-01</b> MD030133 	
<b>X83192-01</b> MD030282 	<b>N93000-02</b> MD115472 (8x)	<b>M37912-00</b> MD151902 +MD151903 	<b>X82156-01</b> MD030468 	<b>X54863-01</b> MD030133 	<b>P77485-01 K ←</b> MD372248 30x46x8 A SL RD MVQ <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>X83363-01</b> MN158200 	<b>N92115-00</b> MR984262 (16x) <b>P76707-00</b> MR984262 16x	<b>X89885-01</b> MN149030 4x 	<b>X81918-01</b> MN163441 	<b>70-31414-10</b> 	<b>P77349-01 K ←</b> MN195668 30x48x6,5 A RD
<b>V37978-00</b> 	<b>N93035-00</b> MD302172 (8x) +MD307341 (8x)	<b>X89730-01</b> MR420441 	<b>X82252-01</b> MR552763 	<b>70-31414-10</b> 	<b>P77579-01 K ←</b> 30x46x7 A SL RD NBR <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>X83192-01</b> MD030282 ① →05/90 	<b>N93000-00</b> MD307343 (12x) ① 06/90→	<b>M37912-00</b> MD151902 +MD151903 ① →05/90 	<b>X82157-01</b> MD149533 ① →05/90  <b>X82197-01</b> MD150525 ① 06/90→ 	<b>70-31414-10</b> 	<b>P77485-01 K ←</b> MD372248 30x46x8 A SL RD MVQ <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
	<b>N93000-00</b> MD307343 (12x)	<b>X89667-01</b> MD311949 	<b>X82197-01</b> MD150525 	<b>70-31414-10</b> 	<b>P77485-01 K ←</b> MD372248 30x46x8 A SL RD MVQ <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR



MITSUBISHI

MITSUBISHI						
Ltr.						
1,3 4G13 (12 V)	55 kW (75 PS)	LANCER	07/90-05/94		<b>H80979-00</b> MD323473 76,5 Ø	<b>T40328-00</b> MD008769 (10x) 
1,3 4G13 (12 V)	55 kW (75 PS)	LANCER	11/99-08/03		<b>H80979-00</b> MD323473 76,5 Ø	
1,3 4G13 (16 V)	60-63 kW (82-86 PS)	LANCER SPACE STAR	06/98→	<b>S40041-00</b> ⑫ ⑬ MD976862 <b>D40041-00</b> ⑫ MD976861	<b>H40041-00</b> MD351292 72 Ø MLS	
1,4 G12B	52-60 kW (70-82 PS)	MIRAGE TREDIA	03/79→	<b>S80887-00</b> ⑫ ⑬ MD997094 <b>D80887-00</b> ⑫ MD997013	<b>H80887-00</b> MD030293 76 Ø	
1,4 4G12	50-51 kW (68-70 PS)	COLT LANCER TREDIA	05/79-08/85	<b>S80890-00</b> ⑫ ⑬ MD997113 <b>D80890-00</b> ⑫ MD997109	<b>H80890-00</b> MD016163 76,9 Ø	
1,5 G15B 4G15	51-55 kW (70-75 PS)	COLT LANCER	11/83-08/89	<b>S80890-00</b> ⑫ ⑬ MD997113 ① →12/86 <b>S80890-01</b> ⑫ ⑬ MD997456 ① 01/87→ <b>D80890-00</b> ⑫ MD997109 ① →12/86 <b>D80890-01</b> ⑫ MD997455 ① 01/87→	<b>H80890-00</b> MD016163 76,9 Ø	



<b>N93000-00</b> MD307343 (12x)	<b>X82197-01</b> MD150525 	<b>70-31414-10</b> 	<b>P77485-01 K ←</b> MD372248 30x46x8 A SL RD MVQ <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR		
<b>N93000-00</b> MD307343 (12x)	<b>X82197-01</b> MD150525 	<b>70-31414-10</b> 	<b>P77485-01 K ←</b> MD372248 30x46x8 A SL RD MVQ <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR		
<b>V37978-00</b> 	<b>N93035-00</b> MD302172 (8x) +MD307341 (8x)	<b>X89734-01</b> MD342458 	<b>X82258-01</b> MR386209 	<b>70-31414-10</b> 	<b>P77579-01 K ←</b> 30x46x7 A SL RD NBR <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>X83192-01</b> MD030282 	<b>N93000-02</b> MD115472 (8x)	<b>M37912-00</b> MD151902 +MD151903 	<b>X82156-01</b> MD030468 	<b>X54863-01</b> MD030133 	<b>P77579-01 K ←</b> 30x46x7 A SL RD NBR <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>X83192-01</b> MD030282 	<b>N93000-02</b> MD115472 (8x)	<b>M37912-00</b> MD151902 +MD151903 	<b>X82156-01</b> MD030468 	<b>X54863-01</b> MD030133 	<b>P77579-01 K ←</b> 30x46x7 A SL RD NBR <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>X83192-01</b> MD030282 	<b>N93000-02</b> MD115472 (8x)	<b>M37912-00</b> MD151902 +MD151903 	<b>X82156-01</b> MD030468 ① →02/86  <b>X82157-01</b> MD149533 ① 01/87→ 	<b>X54863-01</b> MD030133 	<b>P77579-01 K ←</b> 30x46x7 A SL RD NBR <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR



MITSUBISHI						
Ltr.						
1,5 OM639	70 kW (95 PS)					
1,5 4A91	80 kW (109 PS)	COLT LANCER	06/04→	<b>S38055-00</b> 	<b>H80698-00</b> MN195370 76 Ø	
1,5 4G15 (12V)	63-81 kW (86-110 PS)	LANCER MIRAGE	05/89-08/99		<b>H80979-00</b> MD323473 76,5 Ø	
1,5 4G15T	110 kW (150 PS)	COLT	03/05→	<b>S40317-00</b> 1000A272  <b>D40317-00</b> 1000A271	<b>H40317-00</b> 1005A862	
1,6 G32B 4G32	48-55 kW (65-75 PS)	CORDIA GALANT L 300 TREDIA	09/81-04/94	<b>S80891-01</b> MD997043 ① →06/84 <b>S80891-02</b> MD997137 ① 07/84→ <b>D80891-01</b> MD997014 ① →06/84 <b>D80891-02</b> MD997136 ① 07/84→	<b>H80891-00</b> MD012886 78 Ø	
1,6 G32B Turbo	84-92 kW (114-125 PS)	COLT TREDIA	09/82-04/88	<b>S80891-00</b> MD997103 <b>D80891-00</b> MD997102	<b>H80891-00</b> MD012886 78 Ø	

AS lado de escape / Auslaßseite / exhaust side / côté échappement / lato scarico / сторона выпуска



<b>V38108-00</b> MN960102 +MN960103		<b>X89484-01</b> MN960219	<b>X82072-01</b> MN960209	<b>X54833-01</b> MN960405	<b>P77391-01 K ←</b> MN960033 40x62x8 RD PTFE
<b>X83363-01</b> MN158200	<b>N92115-00</b> MR984262 (16x) <b>P76707-00</b> MR984262	<b>X89885-01</b> MN149030	4x <b>X81918-01</b> MN163441	<b>70-31414-10</b> 	<b>P77349-01 K ←</b> MN195668 30x48x6,5 A RD
<b>X83192-01</b> MD030282	<b>N93000-00</b> MD307343 (12x)	<b>X89667-01</b> MD311949	<b>X82197-01</b> MD150525	<b>X54863-01</b> MD030133	<b>P77485-01 K ←</b> MD372248 30x46x8 A SL RD MVQ <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V38015-00</b> MD377811 +MD377813 (2x) +MR994294 (2x)	<b>N76829-00</b> MD307341 (8x) +MD302172 (8x) <b>P76829-00</b> MD302172 <b>P76830-00</b> MD307341	ES 8x AS 8x <b>X89806-01</b> MN143690	<b>X82252-01</b> MR552763	<b>70-31414-10</b> 	<b>P77569-01 K ←</b> MD377999 34x46x7 A SL RD FPM <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37940-00</b> MD007383 +MD020718	<b>N93011-00</b> MD197467 (8x)	<b>X89961-01</b> MD034235 ① →06/84 <b>X89632-01</b> MD192250 ① 07/84→	<b>X82158-01</b> MD302867	<b>X54864-01</b> MD008897 ① →06/84	<b>P76463-01 K ←</b> 44x60x7 RD NBR <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37940-00</b> MD007383 +MD020718	<b>N93011-00</b> MD197467 (8x)			<b>X54864-01</b> MD008897	<b>P77495-01 K ←</b> MD050606 44x60x7 A SL RD MVQ <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR

ES lado de admisión / Einlaßseite / intake side / côté admission / lato aspirazione / сторона впуска



MITSUBISHI

MITSUBISHI						
Ltr.						
1,6 4A92 <b>[NEW]</b>	85-86 kW (116-117 PS) ASX LANCER	05/10→	<b>S38055-01</b> 1000B593 	<b>H80698-00</b> MN195370 76 Ø 		
1,6 4G18	72 kW (98 PS) LANCER	09/03→	<b>S40108-00</b> MD979216 <b>D40108-00</b> MD978240 ⑫ ⑬ ⑰	<b>H40108-00</b> MD342397 MLS 		
1,6 4G18	72 kW (98 PS) SPACE STAR	01/01-12/04	<b>S40108-00</b> MD979216 <b>D40108-00</b> MD978240 ⑫ ⑬ ⑰	<b>H40108-00</b> MD342397 MLS 		
1,6 4G32	48-55 kW (65-75 PS) L 300 SAPPORO	02/80-10/86	<b>S80891-01</b> MD997043 ① →06/84 <b>S80891-02</b> MD997137 ① 07/84→ <b>D80891-01</b> MD997014 ① 09/81-06/84 <b>D80891-02</b> MD997136 ① 07/84→ ⑫ ⑬	<b>H80891-00</b> MD012886 78 Ø 		
1,6 4G32	51 kW (69 PS) L 400	06/96-10/02	<b>S80891-02</b> MD997137 <b>D80891-02</b> MD997136 ⑫	<b>H80891-00</b> MD012886 78 Ø 		

⑰ con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



<b>X71000-01</b> 1035A991 	<b>N93207-00</b> MD179175 (16x) <b>P76968-00</b> MD179175 16x	<b>M38796-00</b> 1540A387 +1540A385 (4x) 	<b>X71001-01</b> 1555A555 	<b>70-31414-10</b> 	<b>P77349-01 K ←</b> MN195668 30x48x6,5 A RD <b>P77867-01 K →</b> 1052A150 LD FPM
<b>V83326-00</b> MD342281 +MD339118 (4x)  <b>X83326-01</b> MD342281 	<b>N76829-00</b> MD307341 (8x) +MD302172 (8x) <b>P76829-00</b> MD302172 <b>P76830-00</b> MD307341 ES 8x AS 8x	<b>X89730-01</b> MR420441 	<b>X82252-01</b> MR552763 	<b>70-31414-10</b> 	<b>P77569-01 K ←</b> MD377999 34x46x7 A SL RD FPM <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V83326-00</b> MD342281 +MD339118 (4x)  <b>X83326-01</b> MD342281 	<b>N76829-00</b> MD307341 (8x) +MD302172 (8x) <b>P76829-00</b> MD302172 <b>P76830-00</b> MD307341 ES 8x AS 8x	<b>X89730-01</b> MR420441 	<b>X82252-01</b> MR552763 	<b>70-31414-10</b> 	<b>P77485-01 K ←</b> MD372248 30x46x8 A SL RD MVQ ① →08/02 <b>P77569-01 K ←</b> MD377999 34x46x7 A SL RD FPM ① 09/02→ <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37940-00</b> MD007383 +MD020718 	<b>N93011-00</b> MD197467 (8x)	<b>X89961-01</b> MD034235 ① →06/84  <b>X89632-01</b> MD192250 ① 07/84→ 	<b>X82158-01</b> MD302867 	<b>X54864-01</b> MD008897 ① 09/81-06/84 	<b>P76463-01 K ←</b> 44x60x7 RD NBR <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37940-00</b> MD007383 +MD020718 	<b>N93011-00</b> MD197467 (8x)	<b>X89632-01</b> MD192250 	<b>X82158-01</b> MD302867 		<b>P76463-01 K ←</b> 44x60x7 RD NBR <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR

AS lado de escape / Auslaßseite / exhaust side / côté échappement / lato scarico / сторона выпуска  
ES lado de admisión / Einlaßseite / intake side / côté admission / lato aspirazione / сторона впуска



MITSUBISHI



MITSUBISHI						
Ltr.						
1,6 4G32	51 kW (69-70 PS) L 300	11/84→	<b>S80891-02</b> ⑫ ⑬ MD997137 <b>D80891-02</b> ⑫ MD997136	<b>H80891-00</b> MD012886 78 Ø 		
1,6 4G61	91 kW (124 PS) COLT	04/88-05/90	<b>S80925-00</b> ⑫ ⑬ MD997472 <b>D80925-00</b> ⑫ MD997468	<b>H80925-00</b> MD113178 83,5 Ø 		
1,6 4G92	66-84 kW (90-114 PS) CARISMA COLT LANCER MIRAGE	03/92→	<b>S80980-00</b> ⑫ ⑬ MD970444  <b>D80980-00</b> ⑫ MD970441	<b>H80980-00</b> MD184399 82,5 Ø 	<b>T40330-00</b> MD164738 (10x) 	
1,8 G37B 4G37	61-71 kW (83-97 PS) GALANT LANCER SPACE WAGON	01/87-10/92	<b>S80892-01</b> ⑫ ⑬ MD997514 <b>D80892-01</b> ⑫ MD997513	<b>H80892-00</b> MD062144 82 Ø 	<b>T40328-00</b> MD008769 (10x) 	
1,8 4B10	102-105 kW (139-143 PS) ASX LANCER	02/08→	<b>S38292-00</b> ⑫ ⑬ 1000B334 	<b>H40570-00</b> 1005B450 87 Ø 0,5 mm 		
1,8 4D65	43-44 kW (58-60 PS) COLT D GALANT D LANCER D	01/84-10/92	<b>S80895-00</b> ⑫ ⑬ MD997116  <b>D80895-00</b> ⑫ MD997115	<b>H80895-00</b> MD066813 82,5 Ø 	<b>T40332-00</b> MD040514 (10x) 	

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>V37940-00</b> MD007383 +MD020718 	<b>N93011-00</b> MD197467 (8x) 	<b>X89632-01</b> MD192250 	<b>X82158-01</b> MD302867 	<b>X54864-01</b> MD008897 	<b>P76463-01 K</b> ← 44x60x7 RD NBR <b>P77509-01 K</b> → MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37949-00</b> 	<b>N93000-01</b> MD115472 (16x) 	<b>X89699-01</b> MD188995 	<b>X82161-01</b> MD124763 	<b>X54883-01</b> MD040342 	<b>P77495-01 K</b> ← MD050606 44x60x7 A SL RD MVQ <b>P77517-01 K</b> → MD343564 80x96x9 A SL LD MVQ <b>P77585-01 N</b> 2x MD372536 35x50x8 A SL RD NBR
<b>V37953-00</b> 	<b>N92012-01</b> MD184303 (16x) 	<b>X89668-01</b> MD172796 	<b>X82198-01</b> MD157084 	<b>70-31414-10</b> 	<b>P77522-01 K</b> → MD150161 85x103x8 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37940-00</b> MD007383 +MD020718 	<b>N93011-00</b> MD197467 (8x) 	<b>X89664-01</b> MD112095 	<b>X82158-01</b> MD302867 	<b>X54864-01</b> MD008897 	<b>P77495-01 K</b> ← MD050606 44x60x7 A SL RD MVQ <b>P77509-01 K</b> → MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>X59461-01</b> 1035A583 	<b>N93151-00</b> MN183952 (16x) <b>P77758-00</b> MN183952 16x 	<b>X59462-01</b> 4x 1542A133 	<b>X59463-01</b> 1555A185 	<b>70-31414-10</b> 	<b>P77756-00 K</b> ← 1052A809 A SL RD FPM <b>P77757-00 K</b> → 1052A118 85x103x8 A SL LD FPM
<b>V37943-00</b> 	<b>N93011-00</b> MD197467 (8x) 	<b>X89811-01</b> ⑦ MD070669 		<b>70-31414-10</b> 	<b>P77495-01 K</b> ← MD050606 44x60x7 A SL RD MVQ <b>P77517-01 K</b> → MD343564 80x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR



MITSUBISHI

MITSUBISHI						
Ltr.						
1,8 4D65 T	55-60 kW (75-82 PS) GALANT TD SPACE WAGON TD	06/84-10/98	<b>S80895-01</b> MD997170  <b>D80895-01</b> MD997134	<b>H80895-00</b> MD066813 82,5 Ø 	<b>T40332-00</b> MD040514 (10x) 	
1,8 4G37	66 kW (90 PS) CORDIA TREDIA	08/84-12/86	<b>S80892-00</b> MD997105 <b>D80892-00</b> MD997104	<b>H80892-00</b> MD062144 82 Ø 	<b>T40328-00</b> MD008769 (10x) 	
1,8 4G37	66 kW (90 PS) LANCER SPACE WAGON	01/84-12/88	<b>S80892-00</b> MD997105 1 → 01/87 <b>S80892-01</b> MD997514 1 02/87 → <b>D80892-00</b> MD997104 1 → 01/87 <b>D80892-01</b> MD997513 1 02/87 →	<b>H80892-00</b> MD062144 82 Ø 	<b>T40328-00</b> MD008769 (10x) 	
1,8 4G67	100 kW (136 PS) COLT LANCER	11/89-05/92	<b>S80925-00</b> MD997472 <b>D80925-00</b> MD997468	<b>H80925-00</b> MD113178 83,5 Ø 	<b>T40329-00</b> MD121887 (10x) 	
1,8 4G93	84-115 kW (114-156 PS) CARISMA COLT ECLIPSE GALANT LANCER MIRAGE PAJERO SPACE RUNNER SPACE WAGON	10/91 →	<b>S80980-00</b> MD970444  <b>D80980-00</b> MD970441	<b>H80980-00</b> MD184399 82,5 Ø 	<b>T40330-00</b> MD164738 (10x) 	
1,8 4G93	87 kW (118 PS) SPACE STAR GDI	06/98-12/04	<b>S40045-00</b> MD978095 <b>D40045-00</b> MD978094	<b>H40045-00</b> MD333279 82 Ø MLS 	<b>T40330-00</b> MD164738 (10x) 	

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>V37943-00</b> 	<b>N93011-00</b> MD197467 (8x) 	<b>X89811-01</b> MD070669 ⑦ 	<b>70-31414-10</b> 	<b>P77495-01 K ←</b> MD050606 44x60x7 A SL RD MVQ <b>P77517-01 K →</b> MD343564 80x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR	
<b>V37940-00</b> MD007383 +MD020718 	<b>N93011-00</b> MD197467 (8x) 	<b>X89664-01</b> MD112095 	<b>X82158-01</b> MD302867 	<b>X54864-01</b> MD008897 	<b>P77495-01 K ←</b> MD050606 44x60x7 A SL RD MVQ <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37940-00</b> MD007383 +MD020718 	<b>N93011-00</b> MD197467 (8x) 	<b>X89664-01</b> MD112095 	<b>X82158-01</b> MD302867 	<b>X54864-01</b> MD008897 	<b>P77495-01 K ←</b> MD050606 44x60x7 A SL RD MVQ <b>P77509-01 K →</b> MD372250 72x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37949-00</b> 	<b>N93000-01</b> MD115472 (16x) 	<b>X89699-01</b> MD188995 	<b>X82161-01</b> MD124763 	<b>X54883-01</b> MD040342 	<b>P77495-01 K ←</b> MD050606 44x60x7 A SL RD MVQ <b>P77517-01 K →</b> MD343564 80x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37953-00</b> 	<b>N92012-01</b> MD184303 (16x) 	<b>X89668-01</b> MD172796 	<b>X82198-01</b> MD157084 	<b>70-31414-10</b> 	<b>P77522-01 K →</b> MD150161 85x103x8 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>X83287-01</b> MD346750 	<b>N92012-01</b> MD184303 (16x) 	<b>X89736-01</b> MR497557 	<b>X82253-01</b> MR323599 	<b>70-31414-10</b> 	<b>P77490-01 K ←</b> MD168055 37x50x6 A SL RD MVQ <b>P77522-01 K →</b> MD150161 85x103x8 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR



MITSUBISHI						
Ltr.						
1,8 4G93 GDi	87-90 kW (118-122 PS)	SPACE STAR GDI	06/98-12/04	<b>S40045-01</b> (12) (13) MD977793 <b>D40045-01</b> (12)	<b>H40045-00</b> MD333279 82 Ø MLS 	<b>T40330-00</b> MD164738 (10x) 
1,8 4N13	85-110 kW (116-150 PS)	ASX ASX DI-D LANCER LANCER DI-D	05/10→	<b>S38323-00</b> (12) (13) 	<b>H40613-00</b> 1005B578 84,5 Ø 1,3 mm 1	
				<b>H40613-10</b> 1005B577 84,5 Ø 1,35 mm 2		
				<b>H40613-20</b> 1005B579 84,5 Ø 1,4 mm 3		
1,9 F8QT	66 kW (90 PS)	CARISMA TD	10/96-09/00	<b>D32119-00</b> (12) 	<b>H09585-00</b> 1,4 mm 2	<b>T09339-00</b> 
				<b>B30384-00</b> (13) 	<b>H19585-10</b> M345349 1,5 mm 1	
					<b>H29585-20</b> 81 Ø 1,6 mm 3	
1,9 F9Q F9Q2	75-85 kW (102-115 PS)	CARISMA DI-D SPACE STAR DI-D	09/00-06/06	<b>S32752-00</b> (12) (13) 	<b>H40379-00</b> 81 Ø 1,25 mm MLS 	<b>T09339-00</b> 
				<b>D32752-00</b> (12) 		
				<b>B32752-00</b> (13) 		
2,0 BSY	100-103 kW (136-140 PS)	GRANDIS DI-D OUTLANDER DI-D	09/05→	<b>D36710-00</b> (12) 	<b>H08124-00</b> 1,55 mm 1	<b>T08124-00</b> 
				<b>B36708-00</b> (13) (35) 	<b>H18124-10</b> 1,63 mm 2	
					<b>H28124-20</b> 82 Ø 1,7 mm 3	

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена

③⑤ contiene retén integrado / enthält integr. Wedi / including integrated oil seal / comprend bague d'étanchéité intégr. / contiene paraolio albero motore integrato / содержит встроенное уплотнение вала



<b>X83321-01</b> AS MD367806 	<b>N92012-01</b> MD184303 (16x) 	<b>X89787-01</b> 4x 	<b>X82253-01</b> MR323599 	<b>70-31414-10</b> 	<b>P77490-01</b> K ← MD168055 37x50x6 A SL RD MVQ <b>P77522-01</b> K → MD150161 85x103x8 A SL LD MVQ <b>P77585-01</b> N 2x MD372536 35x50x8 A SL RD NBR
<b>X83322-01</b> ES MD367805 	<b>N93157-00</b> MD184303 (8x) +1010A304 (8x) <b>P77786-00</b> ES 8x MD184303 <b>P77787-00</b> AS 8x 1010A304	<b>X83448-01</b> 1540A295 	<b>X83447-01</b> 1555A439 	<b>70-31414-10</b> 	<b>P77784-01</b> K ← 1052B061 70x85x6 A SL RD FPM <b>P77785-01</b> K → 1052A904 93x111x8 A SL LD FPM
<b>X08256-01</b> 	<b>N90300-00</b> <b>P76531-00</b> 8x	<b>X51482-01</b> (7) 	<b>X54032-01</b> 	<b>P76186-01</b> K ← 50x68x10 A RD FPM <b>P76353-01</b> K → 85x105x8 A SL LD FPM <b>P76039-01</b> N 25x42x8 A SL RD FPM	
<b>X53517-01</b> MW30621277 NBR 	<b>N91190-00</b> <b>P76532-00</b> 8x	<b>X52090-01</b> (7) 	<b>X54451-01</b> 	<b>P77069-01</b> K ← 42x54x5,8 A SL RD FPM <b>P76353-01</b> K → 85x105x8 A SL LD FPM <b>P76039-01</b> N 25x42x8 A SL RD FPM	
<b>X83030-01</b> NBR 	<b>N92990-00</b> <b>P76662-00</b> 16x	<b>X87466-01</b> 	<b>X81685-01</b> 	<b>70-31414-10</b> 	<b>P76096-11</b> K ← 35x48x10 A SL RD PTFE ACM <b>P77353-11</b> K → PTFE <b>P77181-01</b> N 2x 32x47x10 A SL RD PTFE ACM

AS lado de escape / Auslaßseite / exhaust side / côté échappement / lato scarico / сторона выпуска  
ES lado de admisión / Einlaßseite / intake side / côté admission / lato aspirazione / сторона впуска





MITSUBISHI						
Ltr.						
2,0 G63B	62-66 kW (84-90 PS) GALANT L 300 SPACE WAGON	06/86→	<b>S80894-00</b> <b>D80894-00</b>	<sup>12</sup> <sup>13</sup> <sup>12</sup>	<b>H80894-00</b> MD040533 86,5 Ø	
2,0 G63B Turbo	66-75 kW (90-102 PS) GALANT SPACE WAGON	03/85-04/91	<b>S80894-00</b> <b>D80894-00</b>	<sup>12</sup> <sup>13</sup> <sup>12</sup>	<b>H80894-00</b> MD040533 86,5 Ø	
2,0 4A20	107 kW (146 PS) ECLIPSE	12/95-04/99	<b>S40007-00</b> <b>D40007-00</b>	<sup>12</sup> <sup>13</sup> <sup>12</sup>	<b>H40007-00</b> 88,5 Ø MLS	
2,0 4D68 4D68 (SOHC) 4D68 T	50-66 kW (68-90 PS) GALANT GALANT TDI LANCER D SPACE RUNNER TD SPACE WAGON TD	06/92-10/04	<b>S37943-00</b> MD971654  <b>D37943-00</b> MD971653 	<sup>12</sup> <sup>13</sup> <sup>12</sup>	<b>H01043-00</b> MD301578 84 Ø 1,4 mm 1 <b>H11043-10</b> MD301579 84 Ø 1,45 mm 2 <b>H21043-20</b> MD301580 84 Ø 1,5 mm 3	<b>T40348-00</b> MD191474 (10x) 
2,0 4G63 4G63K	65-101 kW (88-137 PS) GALANT L 300 L 400 SAPPORO SPACE WAGON	08/80-03/01	<b>S40006-00</b> MD971623 <b>D40006-00</b>	<sup>12</sup> <sup>13</sup> <sup>12</sup>	<b>H40006-00</b> MD199174 86 Ø	
2,0 4G63	83-100 kW (113-136 PS) L 300 L 400 SPACE RUNNER SPACE WAGON SPACE WAGON GDI	10/92-12/04	<b>S80927-00</b> MD997475 <b>D80927-00</b> MD997471	<sup>12</sup> <sup>13</sup> <sup>12</sup>	<b>H80927-00</b> MD113173 86,5 Ø	
2,0 4G63	85-90 kW (115-122 PS) L 200 L 300 SPACE GEAR	07/94-12/07	<b>S40042-00</b> MD972933 <b>D40042-00</b> MD9723932	<sup>12</sup> <sup>13</sup> <sup>12</sup>	<b>H40042-00</b> MD346924 86 Ø 1,42 mm	



<b>X83193-01</b> MD041512 	<b>N93011-00</b> MD197467 (8x)	<b>X89634-01</b> MD040974 	<b>X82162-01</b> MD076481 	<b>X54883-01</b> MD040342 	<b>P76463-01</b> K ← 44x60x7 RD NBR <b>P77517-01</b> K → MD343564 80x96x9 A SL LD MVQ <b>P77585-01</b> N MD372536 35x50x8 A SL RD NBR
<b>X83193-01</b> MD041512 	<b>N93011-00</b> MD197467 (8x)	<b>X89634-01</b> MD040974 	<b>X82378-01</b> 	<b>X54883-01</b> MD040342 	<b>P77495-01</b> K ← MD050606 44x60x7 A SL RD MVQ <b>P77517-01</b> K → MD343564 80x96x9 A SL LD MVQ
<b>V37966-00</b> 	<b>N93012-00</b>	<b>X89701-01</b> 	<b>X82225-01</b> 	<b>X54904-01</b> 	<b>P77530-01</b> K → MD372251 91x111x9 A SL LD MVQ <b>P77596-01</b> N 18x30x9 A SL RD NBR
<b>V37943-00</b> 	<b>N93011-00</b> MD197467 (8x)	<b>X89700-01</b> 	<b>X82159-01</b> MD084230 	<b>70-31414-10</b> 	<b>P76463-01</b> K ← 44x60x7 RD NBR <b>P77522-01</b> K → MD150161 85x103x8 A SL LD MVQ <b>P77585-01</b> N MD372536 35x50x8 A SL RD NBR
<b>V37965-00</b> 	<b>N92012-01</b> MD184303 (16x)	<b>X89698-01</b> 	<b>X82224-01</b> MD181032 <b>X82321-01</b> 	<b>X54903-01</b> 	<b>P77495-01</b> K ← MD050606 44x60x7 A SL RD MVQ <b>P77522-01</b> K → MD150161 85x103x8 A SL LD MVQ <b>P77585-01</b> N MD372536 35x50x8 A SL RD NBR
<b>V37949-00</b> 	<b>N93000-01</b> MD115472 (16x)	<b>X89636-01</b> MD117729 	<b>X82161-01</b> MD124763 	<b>X54883-01</b> MD040342 	<b>P76463-01</b> K ← 44x60x7 RD NBR <b>P77585-01</b> N MD372536 35x50x8 A SL RD NBR
<b>V37979-00</b> 	<b>N92012-01</b> MD184303 (16x)	<b>X89731-01</b> MD193224 	<b>X82224-01</b> MD181032 		<b>P77495-01</b> K ← MD050606 44x60x7 A SL RD MVQ <b>P77522-01</b> K → MD150161 85x103x8 A SL LD MVQ <b>P77585-01</b> N MD372536 35x50x8 A SL RD NBR



MITSUBISHI

MITSUBISHI						
Ltr.						
2,0 4G63	106-110 kW (144-150 PS) ECLIPSE GALANT	11/87-11/95	<b>S80927-00</b> (12) (13) MD997475 <b>D80927-00</b> (12) MD997471	<b>H80927-00</b> MD113173 86,5 Ø		
2,0 4G63 (DOHC 16V) <b>[NEW]</b>	99 kW (135 PS) LANCER	09/03→	<b>S38799-00</b> (12) (13) MD979312 <b>D38799-00</b> (12) MD979311	<b>H40758-00</b> MD332034 86,5 Ø MLS		
2,0 6A12	110 kW (150 PS) GALANT V6	11/92-08/96	<b>S80981-00</b> (12) (13)  <b>D80981-00</b> (12)	<b>H80981-00</b> 2x MD198014 80 Ø	<b>T40330-00</b> MD164738 (10x) 	
2,3 4D55	50 kW (68 PS) L 300 D	04/83-10/86	<b>S80893-00</b> (12) (13) MD050092 <b>D80893-00</b> (12) MD050092	<b>H80893-10</b> MD050545 92,5 Ø	<b>T40331-00</b> MD040514 (18x) 	
2,3 4D55T	62 kW (84 PS) GALANT TD PAJERO TD	09/80-04/86	<b>S38257-00</b> (12) (13) MD974500 <b>D38257-00</b> (12) MD974499	<b>H40535-00</b> MD149577	<b>T40331-00</b> MD040514 (18x) 	
2,4 4G69 <b>[NEW]</b>	118-130 kW (160-177 PS) GALANT GDI GRANDIS OUTLANDER	05/03→	<b>S38797-00</b> (12) (13) MD979394  <b>D38798-00</b> (12) MD979393	<b>H40757-00</b> MN163381 88 Ø MLS		

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>V37949-00</b> 	<b>N93000-01</b> MD115472 (16x)	<b>X89636-01</b> MD117729 	<b>X82161-01</b> MD124763 	<b>X54883-01</b> MD040342 	<b>P76463-01 K</b> ← 44x60x7 RD NBR <b>P77517-01 K</b> → MD343564 80x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V38800-00</b> MD340535 +MD186785 (4x) 	<b>N95981-00</b> MD306079 (8x) +MD307343 (8x)	<b>X71005-01</b> 1540A019 	<b>X82224-01</b> MD181032 	<b>70-31414-10</b> 	<b>P77495-01 K</b> ← MD050606 44x60x7 A SL RD MVQ <b>P77868-01 K</b> → MD359158 A SL LD FPM <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>X83263-01</b> 2x MD174560 	<b>N92012-03</b> MD184303 (24x)	<b>X89696-01</b> 2x 	<b>X82222-01</b> 2x 	<b>70-31414-10</b> 	<b>P77490-01 K</b> ← MD168055 37x50x6 A SL RD MVQ <b>P77522-01 K</b> → MD150161 85x103x8 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37942-00</b> 	<b>N93011-00</b> MD197467 (8x)	<b>X89812-01</b> ⑦ MD050482 		<b>X54882-01</b> MD149392 	<b>P77495-01 K</b> ← MD050606 44x60x7 A SL RD MVQ <b>P77517-01 K</b> → MD343564 80x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37942-00</b> 	<b>N93011-00</b> MD197467 (8x)	<b>X89812-01</b> ⑦ MD050482 		<b>X54882-01</b> MD149392 	<b>P77495-01 K</b> ← MD050606 44x60x7 A SL RD MVQ <b>P77517-01 K</b> → MD343564 80x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>X71002-01</b> MN137117 	<b>N93208-00</b> MD184303 (16x) <b>P77786-00</b> MD184303	<b>X71003-01</b> MN171073 	<b>X71004-01</b> 1555A052 	<b>70-31414-10</b> 	<b>P77495-01 K</b> ← MD050606 44x60x7 A SL RD MVQ <b>P77868-01 K</b> → MD359158 A SL LD FPM <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR



MITSUBISHI

MITSUBISHI						
Ltr.						
2,5 4D56	51-55 kW (69-75 PS)	L 200 D L 300 D	11/86→	<b>S80893-00</b> (12) (13) MD050092 <b>D80893-00</b> (12) MD050092	<b>H80893-10</b> MD050545 92,5 Ø 	<b>T40331-00</b> MD040514 (18x) 
2,5 4D56 T 4D56 TD	62-98 kW (84-133 PS)	L200TD L300D L300TD L400TD PAJERO TD PAJERO TDiC SPACE GEAR TD	05/86→	<b>S37204-00</b> (12) (13) 1000A901 1 → 08/01  <b>S37942-00</b> (12) (13) MD978645 1 → 09/01 →  <b>D37204-00</b> (12) 1000A915 1 → 08/01  <b>D37942-00</b> (12) MD972999 1 → 09/01 → 	<b>H06820-10</b> 1005B425 92,5 Ø 1,45 mm 2 ■ 1 → 08/01 <b>H16820-20</b> 1005B426 92,5 Ø 1,5 mm 3 ■ 1 → 08/01 <b>H26820-30</b> 1005B427 92,5 Ø 1,55 mm 4 ■ 1 → 08/01 <b>H36820-40</b> 1005B428 92,5 Ø 1,6 mm 5 ■ 1 → 08/01  <b>H01086-00</b> MD377774 92 Ø 1,45 mm MLS 1 → 09/01 → <b>H11086-10</b> MD377775 92 Ø 1,5 mm 1 ■ MLS 1 → 09/01 → <b>H21086-20</b> MD377776 92 Ø 1,55 mm 2 ■ MLS 1 → 09/01 → 	<b>T40331-00</b> MD040514 (18x) 
2,5 6A13 6G73	118-125 kW (160-170 PS)	GALANT V6	11/92-10/04	<b>S40044-00</b> (12) (13) MD975563 <b>D40044-00</b> (12) MD975562	<b>H40044-00</b> 2x MD333227 82 Ø MLS 	

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



<b>V37942-00</b> 	<b>N93011-00</b> MD197467 (8x)	<b>X89812-01</b> (7) MD050482 	<b>X54882-01</b> MD149392 	<b>P77495-01 K</b> ← MD050606 44x60x7 A SL RD MVQ <b>P77517-01 K</b> → MD343564 80x96x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR	
<b>V37942-00</b> 	<b>N93011-00</b> MD197467 (8x)	<b>X89824-01</b> (7) MR188679 	<b>70-31414-10</b> 	<b>P77495-01 K</b> ← MD050606 44x60x7 A SL RD FPM <b>P77517-01 K</b> → MD343564 80x96x7,5 A SL LD FPM <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR	
<b>V37980-00</b> 2x MD173371 	<b>N92012-03</b> MD184303 (24x)	<b>X89735-01</b> 2x MD327788 	<b>X82259-01</b> 2x MR281718 	<b>70-31414-10</b> 	<b>P77490-01 K</b> ← MD168055 37x50x6 A SL RD MVQ <b>P77522-01 K</b> → MD150161 85x103x8 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR



MITSUBISHI

MITSUBISHI						
Ltr.						
2,6 G54B T/C 4G54	76-114 kW (103-155 PS)	PAJERO STARION	01/83-10/97	<b>S80928-00</b> (12) (13) MD997458 <b>D80928-00</b> (12) MD997457	<b>H80928-00</b> MD115646 93 Ø 	
2,8 4M40	69-71 kW (94-97 PS)			<b>S83264-00</b> (12) (13) ME994141 1 → 04/96   <b>S83264-01</b> (12) (13) ME994149 1 05/96 →   <b>D83264-00</b> (12) 1 → 04/96  <b>D83264-01</b> (12) 1 05/96 → 	<b>H01036-00</b> ME200751 96 Ø 1,3 mm 1 □ <b>H11036-10</b> ME200752 96 Ø 1,35 mm 2 □ <b>H21036-20</b> ME200753 96 Ø 1,4 mm 3 □ <b>H31036-30</b> ME200754 96 Ø 1,45 mm 4 □ 	<b>T40349-00</b> ME200426 (14x) +ME200848 (2x) +ME200427 (4x) 
2,8 4M40-A	69-71 kW (94-97 PS)	CANTER PAJERO D	11/93-12/99		<b>H01036-00</b> ME200751 96 Ø 1,3 mm 1 □ <b>H11036-10</b> ME200752 96 Ø 1,35 mm 2 □ <b>H21036-20</b> ME200753 96 Ø 1,4 mm 3 □ <b>H31036-30</b> ME200754 96 Ø 1,45 mm 4 □ 	<b>T40349-00</b> ME200426 (14x) +ME200848 (2x) +ME200427 (4x) 
2,8 4M40-2AT	85 kW (116 PS)	CANTER CANTER TDI	07/98 →		<b>H01036-00</b> ME200751 96 Ø 1,3 mm 1 □ <b>H11036-10</b> ME200752 96 Ø 1,35 mm 2 □ <b>H21036-20</b> ME200753 96 Ø 1,4 mm 3 □ <b>H31036-30</b> ME200754 96 Ø 1,45 mm 4 □ 	<b>T40349-00</b> ME200426 (14x) +ME200848 (2x) +ME200427 (4x) 



<b>V37941-00</b> 	<b>N93011-00</b> MD197467 (8x)	<b>X89633-01</b> MD024628 	<b>X82163-01</b> MD102683 	<b>X54882-01</b> MD149392 	<b>P77517-01 K →</b> MD343564 80x96x9 A SL LD MVQ
<b>V83264-00</b> ME200403 +ME011282 (2x) +ME200269 +ME200270 	<b>N76834-00</b> ME200524 (8x) <b>P76834-00</b> ME200524 8x	<b>X89697-01</b> ME200285 4x 	<b>X82236-01</b> ME202145 1 → 04/96  <b>X82223-01</b> ME201356 1 05/96 → 	<b>70-31414-10</b> 4x 	<b>P77500-01 K ←</b> ME200028 52x74x10/18,9 A SL NBR 1 → 04/96 <b>P77555-01 K ←</b> ME202850 50x74x11 1 05/96 → <b>P77532-01 K →</b> ME200012 92,5x114/120x10/16,5 A SL LD NBR 1 → 04/96 <b>P77556-01 K →</b> ME202851 94,5x114x12 1 05/96 →
<b>V83264-00</b> ME200403 +ME011282 (2x) +ME200269 +ME200270 	<b>N93011-00</b> MD197467 (8x)	<b>X89697-01</b> ME200285 4x 	<b>X82236-01</b> ME202145 4x 	<b>70-31414-10</b> 4x 	<b>P77500-01 K ←</b> ME200028 52x74x10/18,9 A SL NBR <b>P77532-01 K →</b> ME200012 92,5x114/120x10/16,5 A SL LD NBR
<b>V83264-00</b> ME200403 +ME011282 (2x) +ME200269 +ME200270 	<b>N93011-00</b> MD197467 (8x)	<b>X89697-01</b> ME200285 4x 	<b>X82236-01</b> ME202145 4x 	<b>70-31414-10</b> 4x 	<b>P77555-01 K ←</b> ME202850 50x74x11 <b>P77556-01 K →</b> ME202851 94,5x114x12



MITSUBISHI























MITSUBISHI						
Ltr.						
3,0 6G72	104 kW (141 PS) GALLOPER V6 PAJERO V6	11/88-12/03	<b>S80969-00</b> MD997496  <b>D80969-00</b> MD997435	<b>H80969-00</b> MD165614 92,5 Ø 	<b>T40356-00</b> MD065959 (8x) 	2x
3,0 6G72	110-130 kW (150-177 PS) PAJERO V6 SIGMA V6	12/90-10/96	<b>S80969-00</b> MD997496  <b>D80969-00</b> MD997435	<b>H80969-00</b> MD165614 92,5 Ø 	<b>T40356-00</b> MD065959 (8x) 	2x
3,0 6G72	136-151 kW (185-205 PS) DEBONAIR DIAMANTE ECLIPSE L 300 SIGMA V6 VERADA	09/89-03/05	<b>S40053-00</b> MD997670 <b>D40053-00</b> MD997669	<b>H40053-00</b> MD199239 92 Ø MLS 		2x
3,0 6G72	210 kW (286 PS) 3000 GT V6	06/92-08/99	<b>S40053-00</b> MD997670 <b>D40053-00</b> MD997669	<b>H40053-00</b> MD199239 92 Ø MLS 	<b>T40356-00</b> MD065959 (8x) 	2x
3,2 4M41	118-121 kW (160-165 PS) PAJERO DI-D	04/00-12/06	<b>S83320-00</b> ME993318  <b>D83320-00</b> 	<b>H01087-00</b> ME204037 99,5 Ø 0,5 mm MLS <b>H11087-10</b> ME204038 99,5 Ø 0,55 mm MLS <b>H21087-20</b> ME204039 99,5 Ø 0,6 mm MLS <b>H31087-30</b> ME204040 99,5 Ø 0,65 mm MLS 		1 ■ 2 ■ 3 ■ 4 ■



<b>X83248-01</b> MD133671 	<b>N93011-01</b> MD197467 (12x)		<b>X82194-01</b> MD134703 	<b>70-31414-10</b> 	<b>P77490-01 K ←</b> MD168055 37x50x6 A SL RD MVQ <b>P77530-01 K →</b> MD372251 91x111x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>X83248-01</b> MD133671 	<b>N93011-01</b> MD197467 (12x)		<b>X82194-01</b> MD134703 	<b>70-31414-10</b> 	<b>P77530-01 K →</b> MD372251 91x111x9 A SL LD MVQ <b>P77585-01 N</b> MD372536 35x50x8 A SL RD NBR
<b>V37984-00</b> MD186786 +MD186787 (3x) 	<b>N93037-00</b> MD306079 (12x) +MD307343 (12x)	<b>X89743-01</b> MD164701 	<b>X82266-01</b> MD168115 	<b>70-31414-10</b> 	<b>P77490-01 K ←</b> MD168055 37x50x6 A SL RD MVQ <b>P77530-01 K →</b> MD372251 91x111x9 A SL LD MVQ <b>P77612-01 N</b> MD177097 30x42x7 A SL MVQ
<b>V37984-00</b> MD186786 +MD186787 (3x) 	<b>N93037-00</b> MD306079 (12x) +MD307343 (12x)	<b>X89743-01</b> MD164701 	<b>X82266-01</b> MD168115 	<b>70-31414-10</b> 	<b>P77490-01 K ←</b> MD168055 37x50x6 A SL RD MVQ <b>P77530-01 K →</b> MD372251 91x111x9 A SL LD MVQ <b>P77612-01 N</b> MD177097 30x42x7 A SL MVQ
<b>X83320-01</b> ME192209 	<b>N93000-01</b> MD115472 (16x)	<b>X89786-01</b> ME203212 	<b>M37910-00</b> ME203114 (4x) 	<b>X54916-01</b> ME201756 	<b>P77555-01 K ←</b> ME202850 50x74x11 <b>P77564-01 K →</b> ME203250 90,5x114x12



<b>MITSUBISHI</b>							
Ltr.	3,3 4D30	64 kW (87 PS)			<b>D80929-00</b> ME999278 HS <sup>(12)</sup>	<b>H80929-00</b> ME011045 102,7 Ø MLS 	
	3,3 4D31T	86 kW (117 PS) CANTER	07/86→		<b>S80929-01</b> ME999663 <sup>(12)</sup> <b>D80929-01</b> ME999663 HS <sup>(12)</sup>	<b>H80929-00</b> ME011045 102,7 Ø MLS 	

					
<b>X83214-01</b> ME011417 	<b>N93022-00</b> ME215092 (8x)		<b>X82377-01</b> ME013536 4x 	<b>X54884-01</b> ME014009 	
<b>X83215-01</b> ME011279 	<b>N93022-00</b> ME215092 (8x)		<b>X82377-01</b> ME013536 4x 	<b>X54884-01</b> ME014009 	

MITSUBISHI

