



HONDA

HONDA

 Code 

O-9

20T2N 662

4EE-2 654

A

A20A1 656

A20A2 656

A20A3 656

A20A4 656

B

B16A1 648

B18C4 654

B18C6 654

B20A1 658

B20A2 658

B20A5 658

B20A7 658

B20A8 658

B20A9 658

B20B 658

B20B3 658

B20Z1 658

C

C25A1 668

C25A2 668

C27A1 668

D

D13B1 642

D13B2 642

D13B7 642



D14A3 644

D14A4 644

D14A7 644

D14A8 644

D14Z1 644

 Code 

D14Z5 644

D14Z6 644

D15A1 644

D15B2 646

D15B7 646

D15Z1 646

D15Z3 646

D16A6 648

D16A7 648

D16A8 648

D16A9 648

D16V1 650

D16W5 650

D16Y7 650

D16Z2 650

D16Z5 648

D16Z6 650

D16Z7 650

D16Z9 650

D17A2 652

D17A5 652

D17A8 654

E

ECA1 640

EN1 642

EN2 642

EN4 642

ER1 640

ER2 640

ER4 640

ET1 654

ET2 654



ET3 654

ET4 654

EV2 642

EW2 646

EW3 648

 Code 

EW4 648

EY 652

EZ 652

F

F18B2 656

F20A2 658

F20A4 658

F20A6 658

F20A7 658

F20A8 658

F20B3 658

F20B5 660

F20B7 660

F20C1 660

F20C VTEC 660

F20Z1 660

F20Z2 662

F20Z3 658

F22A3 662

F22A7 662

F22A8 662

F22B5 664

F22B8 664

F23A1 666

F23A3 666

F23A5 666

F23A6 666

F23A7 666

F23A8 666

F23Z5 668



H

H23A2 668

H23A3 668

J

J30A1 668

 Code 

K

K20A1 662

K24A 668

L

L12A1 640

L12A2 640

L12A3 640

L12B1 640

L13A1 642

L13A3 642

L13A5 642

L13A7 642

L13A8 642

L13Z1 644

L15A1 648

L15A2 648

L15A3 648

L15A7 648

N

N22A1 664

N22A2 664

R

R18A1 656

R18A2 656

R20A1 662

R20A2 662

R20A3 662

X

XUD7T 656



Z

ZA2 640

ZC1 652

 Code 

 Code 

 Code 

 Code 

HONDA						
Ltr.						
1,0 ECA1	50-56 kW (68-76 PS) INSIGHT INSIGHT VTEC	04/00-12/06	D40097-00 06110-PHM-000 B37934-00 06111-PHM-000	⑫	⑬	H40097-00 12251-PHM-004 73 Ø MLS
1,2 ER1 ER2 ER4	33-41 kW (45-56 PS) CITY JAZZ	11/80-10/86	S37226-00 061A1-PE8-000 +061B1-PC0-020 D37226-00 061A1-PE8-000	⑫ ⑬		H80905-00 12251-PC0-010 61,9 Ø
1,2 L12A1	57-58 kW (78-79 PS) CIVIC JAZZ	04/01-07/08	D40511-00 06110-PWA-030 B59319-00 06111-PWA-010 +06114-PWA-000	⑫	⑬	H40511-00 12251-PWA-J01 MLS
1,2 L12A2 L12A3	58-61 kW (79-83 PS) CITY	05/03→	D40512-00 06110-REA-Z00 B59319-00 06111-PWA-010 +06114-PWA-000	⑫	⑬	H40512-00 12251-REA-Z01 MLS
1,2 L12B1	66 kW (90 PS) JAZZ	07/08→	D40603-00 06110-RB0-010 B59319-00 06111-PWA-010 +06114-PWA-000	⑫ ⑬	⑭	H40603-00 12251-RB0-004 0,65 mm MLS
1,2 ZA2	40 kW (54 PS) CIVIC	01/84-10/87	D80902-01 061A1-PE3-020 B54868-00 061B1-PE0-010	⑫	⑬	H80902-10 12251-PE3-014 74,5 Ø

⑫ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена

⑬ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус выпускного коллектора



X83324-01 12341-PHM-000 	N93047-01 12210-PZ004 (6x) +12211-PZ1-004 (6x)	X89790-01 17106-PHM-006 3x 	X82305-01 18115-PHM-004 	E37934-00 11251-PHM-000 +11252-PHM-000 	P76115-00 K ← 91212-PWA-003 40x55x8 A SL RD MVQ P77565-01 K → 91214-PHM-003 65x88x10 A SL LD
X83200-01 12341-PC1-010 		X89841-01 17146-PHM-004 ⑩ 	X82433-01 18115-PC0-014 ⑦ 	X54871-01 11251-PC0-014 	P77585-01 K ← 91213-PH1-003 35x50x8 A SL RD NBR P77510-01 K → 91214-634-004 74x98x12 A SL RD MVQ P77600-01 N 91203-PG6-003 27x43x9 A SL LD NBR
V38233-00 12341-PWA-000 	N93139-00 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	M38234-00 17105-PWA-007 (4x) 	X59318-01 18115-PWA-003 	X59319-01 11252-PWA-000 	P76115-00 K ← 91212-PWA-003 40x55x8 A SL RD MVQ P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
V38233-00 12341-PWA-000 	N93139-00 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	M38234-00 17105-PWA-007 (4x) 	X59318-01 18115-PWA-003 	X59319-01 11252-PWA-000 	P76115-00 K ← 91212-PWA-003 40x55x8 A SL RD MVQ P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
X83414-01 12341-RB0-003 ACM 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X83422-01 17105-RB0-004 	X83423-01 18115-RB0-007 	X59319-01 11252-PWA-000 	P76115-00 K ← 91212-PWA-003 40x55x8 A SL RD MVQ P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
X83197-01 12341-PE0-000 		M82547-00 17115-RB0-007 (4x) ⑩ 	X82146-01 18110-PE0-010 2x 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR

⑩ con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



HONDA						
Ltr.						
1,3 D13B1 D13B2	55 kW (75 PS) CIVIC	10/87-11/95	S80906-00 ⑫ ⑬ 061A1-PM3-000 +061B14-PM3-000 D80906-00 ⑫ 061A1-PM3-000	H80906-00 12251-PM3-003 75,5 Ø 		
1,3 D13B7	48 kW (65 PS) LOGO	03/99-03/02	D40101-00 ⑫ 06110-P7A-G00 B54918-00 ⑬ 06111-P7A-G00	H40101-00 12251-P7A-G01 76 Ø 0,65 mm MLS 		
1,3 EN1 EN2 EN4	33-52 kW (45-71 PS) CIVIC	09/79-12/84	D80899-00 ⑫ 061A1-PA1-026 B54868-00 ⑬ 061B1-PE0-010	H80899-10 12251-642-020 74 Ø 		
1,3 EV2	52 kW (71 PS) CIVIC CRX	08/83-12/87	D80902-01 ⑫ 061A1-PE3-020 B54868-00 ⑬ 061B1-PE0-010	H80902-10 12251-PE3-014 74,5 Ø 		
1,3 L13A1 L13A7 L13A8	61-85 kW (83-116 PS) CITY CIVIC FIT JAZZ JAZZ DSI	09/01→	D40511-00 ⑫ 06110-PWA-030 B59319-00 ⑬ 06111-PWA-010 +06114-PWA-000	H40511-00 12251-PWA-J01 MLS 	T40512-00 90008-PWA-003 (10x) 	
1,3 L13A3 L13A5	60-65 kW (82-88 PS) CITY	10/05→	D40512-00 ⑫ 06110-REA-Z00 B59319-00 ⑬ 06111-PWA-010 +06114-PWA-000	H40512-00 12251-REA-Z01 MLS 	T40512-00 90008-PWA-003 (10x) 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



X83204-01 12341-PM6-010 	N93046-00 12210-PT2-004 (8x) +12211-PT2-004 (8x)	X89616-01 17105-PM3-004 	X82144-01 18115-PM3-003 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V83228-00 12030-P2A-000 		X89793-01 17105-P7A-004 	X82308-01 18115-PEJ-004 	X54919-01 11251-P1J-E00 	P77563-01 K ← 91212-P7A-004 31x46x7 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
X83196-01 12341-PA1-000 		X89968-01 2x 17105-634-000 	X82141-01 4x 18110-PA1-000 	X54868-01 11251-PE0-020 	P77585-01 K ← 91213-PH1-003 35x50x8 A SL RD NBR P77510-01 K → 91214-634-004 74x98x12 A SL RD MVQ P77600-01 N 91203-PG6-003 27x43x9 A SL LD NBR
X83197-01 12341-PE0-000 		X89620-01 17105-PE1-650 	X82146-01 2x 18110-PE0-010 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V38233-00 12341-PWA-000 	N93139-00 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	M38234-00 17105-PWA-007 (4x) X59320-01 ⑩ 17146-PWA-004 	X59318-01 18115-PWA-003 	X59319-01 11252-PWA-000 70-31414-10 	P76115-00 K ← 91212-PWA-003 40x55x8 A SL RD MVQ P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
V38233-00 12341-PWA-000 	N93139-00 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	M38234-00 17105-PWA-007 (4x) X59320-01 ⑩ 17146-PWA-004 	X59318-01 18115-PWA-003 	X59319-01 11252-PWA-000 70-31414-10 	P76115-00 K ← 91212-PWA-003 40x55x8 A SL RD MVQ P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR



HONDA						
Ltr.						
1,4 D14A3 D14A4	55-66 kW (75-90 PS)	CIVIC	11/95-02/01	D40095-00 06110-P2A-030 ¹²	H40095-00 12251-P2J-004 76 Ø 0,7 mm MLS 	
1,4 D14A7 D14A8	55-66 kW (75-90 PS)	CIVIC CONCERTO	08/89-02/01	D40095-01 06110-P1J-E00 ¹² B54919-01 06111-P2A-010 ¹³	H40095-00 12251-P2J-004 76 Ø 0,7 mm MLS 	
1,4 D14Z1	55 kW (75 PS)	CIVIC	11/95-02/01	D40095-00 06110-P2A-030 ¹²	H40095-00 12251-P2J-004 76 Ø 0,7 mm MLS 	
1,4 D14Z5 D14Z6	55-66 kW (75-90 PS)	CIVIC	12/00-09/05	D40096-02 06110-PSM-E00 ¹² B54919-00 06111-PSG-Y10 ¹³	H40096-00 12251-PLC-003 76 Ø 0,73 mm MLS 	
1,4 L13Z1 [NEW]	73-74 kW (99-101 PS)	CITY JAZZ	07/08→	D40603-00 06110-RB0-010 ¹² ¹⁹ B59319-00 06111-PWA-010 ¹³ +06114-PWA-000	H40603-00 12251-RB0-004 0,65 mm MLS 	T40512-00 90008-PWA-003 (10x)
1,5 D15A1	63 kW (86 PS)	INTEGRA	10/85-08/89	D80902-01 061A1-PE3-020 ¹² B54868-00 061B1-PE0-010 ¹³	H80902-10 12251-PE3-014 74,5 Ø 	

¹² junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



V83228-00 12030-P2A-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	X89783-01 17105-P2A-014 	X82302-01 18115-P2A-004 	X54919-01 11251-P1J-E00 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V83228-00 12030-P2A-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	M38276-00 17105-P1J-E01 (3x) +17106-P1J-E01 (1x) 	X82302-01 18115-P2A-004 	X54919-01 11251-P1J-E00 	P77736-01 K ← 91212-P01-003 31x46x7 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V83228-00 12030-P2A-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	X89783-01 17105-P2A-014 	X82302-01 18115-P2A-004 	X54919-01 11251-P1J-E00 	P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V38003-00 123030-PLC-010 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	X89794-01 17105-PLA-G01 4x 	X82304-01 18115-PLC-J01 	X54919-01 11251-P1J-E00 	P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
X83414-01 12341-RB0-003 ACM 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	X83422-01 17105-RB0-004 	X83423-01 18115-RB0-007 	X59319-01 11252-PWA-000 	P76115-00 K ← 91212-PWA-003 40x55x8 A SL RD MVQ P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
X83197-01 12341-PE0-000 		X89620-01 17105-PE1-650 	X82146-01 18110-PE0-010 2x 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR

¹⁹ con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



HONDA						
Ltr.						
1,5 D15B2	61-74 kW (83-101 PS)	CIVIC CONCERTO	10/87-12/95	S80906-01 ⑫ ⑬ 061A1-PM6-000 +061B1-PM3-000 D80906-01 ⑫ 061A1-PM6-000	H80906-00 12251-PM3-003 75,5 Ø 	
1,5 D15B7	74-77 kW (101-105 PS)	CITY CIVIC CRX	01/94-09/03	S80965-00 ⑫ ⑬ 06110-P03-000 +06111-P07-000 D80965-00 ⑫ 06110-P03-000	H80965-00 12251-PM5-S02 75,5 Ø 	
1,5 D15Z1	69-88 kW (94-120 PS)	CIVIC	10/91-11/95	S80967-00 ⑫ ⑬ 06110-P08-000 +06111-P08-000 D80967-00 ⑫ 06110-P08-000	H80967-00 12251-P08-004 75,8 Ø MLS 	
1,5 D15Z3	66 kW (90 PS)	CIVIC CIVIC VTEC-E	09/94-01/97	D40095-00 ⑫ 06110-P2A-030	H40095-00 12251-P2J-004 76 Ø 0,7 mm MLS 	
1,5 EW2	63 kW (86 PS)	CIVIC	10/83-10/87	D80902-01 ⑫ 061A1-PE3-020 B54868-00 ⑬ 061B1-PE0-010	H80902-10 12251-PE3-014 74,5 Ø 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



X83204-01 12341-PM6-010 	N93046-00 12210-PT2-004 (8x) +12211-PT2-004 (8x)	X89617-01 17105-PG6-010 	X82144-01 18115-PM3-003 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V37946-00 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89621-01 17105-P00-T02 	X82147-01 18115-P00-004 X82318-01 △ 18212-SA0-003 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
X83228-01 12341-P08-000 	N93046-00 12210-PT2-004 (8x) +12211-PT2-004 (8x)	X89642-01 17105-P07-004 X89826-01 ⑩ 17105-P08-004 	X82147-01 18115-P00-004 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V83228-00 12030-P2A-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89783-01 17105-P2A-014 	X82302-01 18115-P2A-004 	X54919-01 11251-P1J-E00 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N ← 91213-PE1-721 29x45x8 A SL LD NBR
X83197-01 12341-PE0-000 	N93023-00 12211-PE0-004 (12x)	X89620-01 17105-PE1-650 	X82146-01 18110-PE0-010 2x 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR



HONDA						
Ltr.						
1,5 EW3 EW4	66-74 kW (90-101 PS)	CIVIC CRX	10/83-10/87	D80902-00 ⑫ 061A1-PE7-020	H80902-10 12251-PE3-014 74,5 Ø	
1,5 L15A1	70-79 kW (95-107 PS)	CITY	09/04→	D40605-00 ⑫ ⑬ 06110-REB-Z01 B59319-00 ⑬ 06111-PWA-010 +06114-PWA-000	H40605-00 12251-REB-Z01 0,85 mm MLS	T40512-00 90008-PWA-003 (10x)
1,5 L15A2 L15A3	81-88 kW (110-120 PS)	JAZZ	07/08→	D40512-00 ⑫ 06110-REA-Z00 B59319-00 ⑬ 06111-PWA-010 +06114-PWA-000	H40512-00 12251-REA-Z01 MLS	T40512-00 90008-PWA-003 (10x)
1,5 L15A7	88 kW (120 PS)	CITY JAZZ	07/08→	D40603-00 ⑫ ⑬ 06110-RB0-010 B59319-00 ⑬ 06111-PWA-010 +06114-PWA-000	H40603-00 12251-RB0-004 0,65 mm MLS	T40512-00 90008-PWA-003 (10x)
1,6 B16A1	110 kW (150 PS)	CIVIC VTEC CRX VTEC	10/89-02/92	D40056-00 ⑫ 061A1-PR3-305	H40056-00 12251-P30-014 81,5 Ø 0,6 mm MLS	
1,6 D16A6 D16A7	79-96 kW (107-130 PS)	CIVIC CRX	09/87-10/95	S80965-00 ⑫ ⑬ 06110-P03-000 +06111-P07-000 D80965-00 ⑫ 06110-P03-000	H80965-00 12251-PM5-S02 75,5 Ø	
1,6 D16A8 D16A9 D16Z5	90-96 kW (122-131 PS)	CIVIC CONCERTO CRX	09/87-03/95	S80968-00 ⑫ ⑬ 061A1-PM7-G00 +061B1-PM7-000 D80968-00 ⑫ 061A1-PM7-G00	H80968-00 12251-PM7-003 75,5 Ø	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



X83199-01 12341-PE2-003 					
X89620-01 17105-PE1-650 		X82146-01 18110-PE0-010 2x 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR	
V83416-00 12030-PWC-000 ACM 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	M38234-00 17105-PWA-007 (4x) X59320-01 ⑩ 17146-PWA-004 	X59318-01 18115-PWA-003 	X59319-01 11252-PWA-000 70-31414-10 	P76115-00 K ← 91212-PWA-003 40x55x8 A SL RD MVQ P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
V38233-00 12341-PWA-000 	N93139-00 12210-PZ1-003 (4x) +12211-PZ1-003 (4x)	M38234-00 17105-PWA-007 (4x) X59320-01 ⑩ 17146-PWA-004 	X59318-01 18115-PWA-003 	X59319-01 11252-PWA-000 70-31414-10 	P76115-00 K ← 91212-PWA-003 40x55x8 A SL RD MVQ P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
X83414-01 12341-RB0-003 ACM 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X83422-01 17105-RB0-004 M82547-00 ⑩ 17115-RB0-007 (4x) 	X83423-01 18115-RB0-007 	X59319-01 11252-PWA-000 70-31414-10 	P76115-00 K ← 91212-PWA-003 40x55x8 A SL RD MVQ P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
V37993-00 12030-PR3-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89765-01 17105-P30-004 	X82284-01 18115-P30-003 		P77600-01 N 2x 91203-PG6-003 27x43x9 A SL LD NBR
V37946-00 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89621-01 17105-P00-T02 	X82144-01 18115-PM3-003 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
X83229-01 12341-PM7-000 	N93050-00 12210-PT2-004 (8x) +12211-PT2-004 (8x)		X82144-01 18115-PM3-003 	X54868-01 11251-PE0-020 	P77600-01 N 91203-PG6-003 27x43x9 A SL LD NBR

⑬ con junta de culata MLS / mit Mehrlagen-Zylinderkopfdichtung / with multilayer cylinder head gasket / avec joint de culasse multifeuilles / con guarnizione testata multistrato / с многослойной прокладкой головки блока цилиндров



HONDA						
Ltr.						
1,6 D16V1	02/01-12/05	81 kW (110 PS)	CIVIC	D40096-02 ⑫ 06110-PSM-E00 B37209-00 ⑬ 06111-PMM-A01	H40096-00 12251-PLC-003 76 Ø 0,73 mm MLS 	
1,6 D16W5	10/99→	91 kW (124 PS)	HR-V	D40095-00 ⑫ 06110-P2A-030 ① 01/03→	H40095-00 12251-P2J-004 76 Ø 0,7 mm MLS 	
1,6 D16Y7	01/94-03/00	77 kW (105 PS)	CIVIC	D40095-00 ⑫ 06110-P2A-030	H40095-00 12251-P2J-004 76 Ø 0,7 mm MLS 	
1,6 D16Z2	10/87-12/97	78-82 kW (106-112 PS)	CIVIC CONCERTO DOMANI	D80906-01 ⑫ 061A1-PM6-000	H80906-00 12251-PM3-003 75,5 Ø 	
1,6 D16Z6 D16Z7 D16Z9	10/91-12/98	92-96 kW (125-131 PS)	CIVIC CIVIC VTEC CRX	S80967-00 ⑫ ⑬ 06110-P08-000 +06111-P08-000 D80967-00 ⑫ 06110-P08-000	H80967-00 12251-P08-004 75,8 Ø MLS 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission /
guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



V38003-00 123030-PLC-010 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	X89794-01 4x 17105-PLA-G01 X89843-01 ⑩ 17055-PLD-004 	X82304-01 18115-PLC-J01 	70-31414-10 	P77731-01 K ← 91212-PLC-003 38x50x7 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V83228-00 12030-P2A-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89783-01 17105-P2A-014 	X82302-01 18115-P2A-004 		P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V83228-00 12030-P2A-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89783-01 17105-P2A-014 	X82302-01 18115-P2A-004 	X54919-01 11251-P1J-E00 	P77736-01 K ← 91212-P01-003 31x46x7 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N ← 91213-PE1-721 29x45x8 A SL LD NBR
X83204-01 12341-PM6-010 	N93046-00 12210-PT2-004 (8x) +12211-PT2-004 (8x)	X89621-01 17105-P00-T02 	X82144-01 18115-PM3-003 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V83228-00 12030-P2A-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89642-01 17105-P07-004 X89826-01 ⑩ 17105-P08-004 	X82147-01 18115-P00-004 	X54868-01 11251-PE0-020 	P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR



HONDA						
Ltr.						
1,6 EY	65 kW (88 PS)	ACCORD	11/85-12/89	D80903-01 ⑫ 061A1-PC7-660 B54872-00 ⑬ 061B1-PD2-000	H80903-10 12251-PD6-013 81 Ø 	
1,6 EZ	65 kW (88 PS)	ACCORD	09/83-10/85	S80903-00 ⑫ ⑬ 061A1-PC7-660 +061B1-PC7-660 D80903-01 ⑫ 061A1-PC7-660 B54872-00 ⑬ 061B1-PD2-000	H80903-10 12251-PD6-013 81 Ø 	
1,6 ZC1	92 kW (125 PS)	CRX	03/86-10/87	D40648-00 ⑫ 061A1-PJ1-000	H40648-00 12251-PG6-003 75,5 Ø 	
1,7 D17A2	92 kW (125 PS)	EDIX FR-V STREAM	05/01→	D40096-01 ⑫ 06110-RJH-000 B37209-00 ⑬ 06111-PMM-A01	H40096-00 12251-PLC-003 76 Ø 0,73 mm MLS 	
1,7 D17A5	92 kW (125 PS)	CIVIC VTEC	05/01-12/05	D40096-00 ⑫ 06110-PLL-Y01 B54919-00 ⑬ 06111-PSG-Y10	H40096-00 12251-PLC-003 76 Ø 0,73 mm MLS 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



X83205-01 12341-PH4-000 		X89656-01 17105-PD2-000 	X82187-01 18115-PD2-000 	X54872-01 11251-PC6-010 	P77487-01 K ← 91212-PC6-003 35x54x8 A SL LD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
X83205-01 12341-PH4-000 		X89656-01 17105-PD2-000 	X82187-01 18115-PD2-000 	X54872-01 11251-PC6-010 	P77487-01 K ← 91212-PC6-003 35x54x8 A SL LD MVQ P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
X83229-01 12341-PM7-000 	N93050-00 12210-PT2-004 (8x) +12211-PT2-004 (8x)	X89617-01 17105-PG6-010 	X82144-01 18115-PM3-003 		P77671-01 K ← 91212-PD6-A01 31x46x8 A SL LD NBR P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77600-01 N 91203-PG6-003 27x43x9 A SL LD NBR
V38003-00 123030-PLC-010 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89789-01 4x 17105-PMR-A01 	X82304-01 18115-PLC-J01 	70-31414-10 	P77731-01 K ← 91212-PLC-003 38x50x7 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V38003-00 123030-PLC-010 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89784-01 17055-PLC-004 	X82304-01 18115-PLC-J01 	X54919-01 11251-P1J-E00 	P77731-01 K ← 91212-PLC-003 38x50x7 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR



HONDA						
Ltr.						
1,7	D17A8	88 kW (120 PS) CIVIC	05/01-12/05	D40096-00 ⑫ 06110-PLL-Y01 B37209-00 ⑬ 06111-PMM-A01	H40096-00 12251-PLC-003 76 Ø 0,73 mm MLS 	
1,7	4EE-2	74 kW (100 PS) CIVIC CTDi	01/02-09/05	D37122-00 ⑫ B37122-00 ⑬	H08698-00 12251-PLZ-D00 1,45 mm 1 MLS H18698-10 12251-PLZ-D10 1,5 mm 2 MLS H28698-20 12251-PLZ-D20 80 Ø 1,55 mm 3 MLS 	T07916-00
1,8	B18C4 B18C6	124-140 kW (169-190 PS) CIVIC INTEGRA Type-R	01/97-10/01		H40056-00 12251-P30-014 81,5 Ø 0,6 mm MLS 	
1,8	ET1	74 kW (101 PS) ACCORD	09/83-10/85	S80903-00 ⑫ ⑬ 061A1-PC7-660 +061B1-PC7-660 D80903-01 ⑫ 061A1-PC7-660 B54872-00 ⑬ 061B1-PD2-000	H80903-10 12251-PD6-013 81 Ø 	
1,8	ET2 ET3 ET4	74-77 kW (101-105 PS) PRELUDE	11/83-04/87	S80903-00 ⑫ ⑬ 061A1-PC7-660 +061B1-PC7-660 D80903-01 ⑫ 061A1-PC7-660	H80903-10 12251-PD6-013 81 Ø 	



V38003-00 123030-PLC-010 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89784-01 17055-PLC-004 X89789-01 4x 17105-PMR-A01 	X82304-01 18115-PLC-J01 	70-31414-10 	P77731-01 K ← 91212-PLC-003 38x50x7 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
X83101-01 12341-PLZ-D00 	N92990-00 12211-PLZ-D00 (16x) P76662-00 16x 12211-PLZ-D00	X89160-01 17105-PLZ-D00 	X81516-01 18115-PLZ-D00 	70-31414-10 	P77427-01 K ← 91220-PLZ-D00 40x52x6 A SL RD FPM P76373-01 K → 91220-PLZ-D10 87x100x8 A SL LD ACM P76130-01 N 2x 91214-PLZ-D00 38x50x8 A SL RD FPM
V37993-00 12030-PR3-000 			X82284-01 18115-P30-003 		
X83205-01 12341-PH4-000 	N93007-00 12210-PC1-003 (4x) +12211-PE0-004 (8x)	X89656-01 17105-PD2-000 	X82187-01 18115-PD2-000 X82188-01 2x 18116-PD2-000 	X54872-01 11251-PC6-010 	P77487-01 K ← 91212-PC6-003 35x54x8 A SL LD MVQ P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
X83205-01 12341-PH4-000 	N93007-00 12210-PC1-003 (4x) +12211-PE0-004 (8x)	X89658-01 17105-PC7-000 	X82187-01 18115-PD2-000 X82188-01 2x 18116-PD2-000 	X54872-01 11251-PC6-010 	P77487-01 K ← 91212-PC6-003 35x54x8 A SL LD MVQ P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR



HONDA

HONDA						
Ltr.						
1,8 F18B2	100 kW (136 PS) ACCORD	10/98-12/02	D40098-01 ⑫ 06110-PDA-E00 B37212-00 ⑬ 06111-PAA-A01	H40098-00 12251-POA-004 86 Ø 0,7 mm MLS 	T40100-00 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	
1,8 R18A1 R18A2	103 kW (140 PS) CIVIC CROSSROAD FR-V STREAM VTEC	09/05→	D38243-00 ⑫ 06110-RNA-000 +06114-RNA-010	H40531-00 12251-RNA-A02 MLS 	T40531-00 90005-RNA-A01 (10x) 	
1,8 XUD7T	58-65 kW (79-88 PS) CITY D CONCERTO TD	08/94-11/99	S31587-00 ⑫ ⑬ D31587-00 ⑫ B30527-00 ⑬	H02299-00 1,6 mm 2 H12299-10 82 Ø 1,75 mm 3	T08280-00 	
2,0 A20A1 A20A2 A20A3	75-85 kW (102-116 PS) ACCORD	11/85-12/89	D80907-00 ⑫ 061A1-PJO-000 ① →12/87 D80907-01 ⑫ 061A1-PJO-A00 ① 01/88→	H80907-00 12251-PH4-003 86 Ø 		
2,0 A20A4	90 kW (122 PS) ACCORD	11/85-12/87	D80907-00 ⑫ 061A1-PJO-000	H80907-00 12251-PH4-003 86 Ø 		

⑫ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



V38006-00 12030-POA-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X59451-01 17105-POA-A02 	X82512-01 18115-PAA-L21 	70-31414-10 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PT0-003 28x42x8 A SL LD MVQ
X59333-01 12341-RNA-A01 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	M38245-00 17105-RNA-A01 (4x) +17106-RNA-A01 (1x) M38260-00 ⑩ 17103-RNA-A01 (2x) +17104-RNA-A01 (4x) 	X59334-01 18115-RNA-004 	70-31414-10 	P77720-01 K ← 91212-RNA-A01 43x58x7 A SL RD P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
X07796-01 	N90300-00 P76531-00 8x	X03013-01 X51239-01 ⑦	X04848-01 2x NBR X07793-01 		P76151-01 K ← 42x62x7 A RD FPM P76386-01 K → 90x110x7 A SL LD FPM P76099-11 N 2x 35x50x8 A SL WD FPM
X83205-01 12341-PH4-000 	N93007-00 12210-PC1-003 (4x) +12211-PE0-004 (8x)	X89618-01 17105-PH3-000 	X82187-01 18115-PD2-000 X82188-01 2x 18116-PD2-000 X82318-01 18212-SAO-003 ① →12/87	X54872-01 11251-PC6-010 	P77487-01 K ← 91212-PC6-003 35x54x8 A SL LD MVQ ① 01/88→ P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
X83205-01 12341-PH4-000 	N93007-00 12210-PC1-003 (4x) +12211-PE0-004 (8x)	X89618-01 17105-PH3-000 	X82187-01 18115-PD2-000 X82188-01 2x 18116-PD2-000 X82318-01 18212-SAO-003	X54872-01 11251-PC6-010 	P77487-01 K ← 91212-PC6-003 35x54x8 A SL LD MVQ P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус впускного коллектора



HONDA						
Ltr.						
2,0 B20A1 B20A2 B20A8	98-101 kW (133-137 PS)	ACCORD PRELUDE	04/86-12/89	D80908-00 ⑫ 061A1-PH3-000	H80908-00 12251-PH3-023 82,5 Ø 	
2,0 B20A5 B20A7 B20A9	101-110 kW (137-150 PS)	PRELUDE	04/87-01/92	D80909-00 ⑫ 061A1-PK2-660	H80909-00 12251-PK1-662 82 Ø 	
2,0 B20B B20B3 B20Z1	94-108 kW (128-147 PS)	CR-V	10/95→	D38244-00 ⑫ 06110-P3F-902	H40532-00 12251-P8R-004 MLS 	
2,0 F20A2 F20A4 F20A6 F20A7 F20A8 F20Z3	66-98 kW (90-133 PS)	ACCORD PRELUDE	01/90-10/00	S80970-00 ⑫ ⑬ 061A1-PT3-000 +061B1-PT3-000 D80970-00 ⑫ 061A1-PT3-000	H80970-00 12251-PT0-J02 86 Ø MLS 	
2,0 F20B3	100 kW (136 PS)	ACCORD	09/93-02/98	D40098-00 ⑫ 06110-P0D-030 B54917-00 ⑬ 06111-PT1-010	H40098-00 12251-P0A-004 86 Ø 0,7 mm MLS 	T40098-00 90005-PT0-003 (9x) +90006-PT0-003 (1x)



V37945-00 12341-PK2-000 +12342-PG6-000 (4x) 	V37945-00 12341-PK2-000 +12342-PG6-000 (4x) 	X89618-01 17105-PH3-000 	X82145-01 18115-PK2-000 	X54873-01 11251-PH3-000 	P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77600-01 N 91203-PG6-003 27x43x9 A SL LD NBR
V37945-00 12341-PK2-000 +12342-PG6-000 (4x) 	V38244-00 12030-PR4-000 	X89659-01 17105-PK3-A00 	X82145-01 18115-PK2-000 X82319-01 2x 18212-SB2-961 	X54874-01 11251-PK1-010 	P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77604-01 N 91213-PE1-721 29x45x8 A SL LD NBR
V38244-00 12030-PR4-000 	N93050-00 12210-PT2-004 (8x) +12211-PT2-004 (8x) 	X59335-01 17105-PHK-004 	X82190-01 18115-PR3-003 	X54897-01 11251-PR3-000 	P77733-01 K ← 91212-PR3-003 38x50x7,4 A SL LD FPM P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77600-01 N 91203-PG6-003 27x43x9 A SL LD NBR
V38004-00 12030-PT0-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	X89657-01 17105-PT2-004 	X82310-01 18115-PT0-004 	X54896-01 11251-PT0-000 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PT0-003 28x42x8 A SL LD MVQ
V38004-00 12030-PT0-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x) 	X89791-01 17105-P0A-004 	X82306-01 18115-P0A-003 	X54896-01 11251-PT0-000 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77735-01 K ← 91233-PT0-003 27x40x8 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PT0-003 28x42x8 A SL LD MVQ



HONDA						
Ltr.						
2,0 F20B5	108 kW (147 PS) ACCORD	02/98-06/03	D40098-02 ⑫ 06110-PAD-G00 B37212-00 ⑬ 06111-PAA-A01	H40098-00 12251-POA-004 86 Ø 0,7 mm MLS 	T40100-00 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	
2,0 F20B7	107-108 kW (145-147 PS) ACCORD	02/98-06/03	D40098-02 ⑫ 06110-PAD-G00 B37212-00 ⑬ 06111-PAA-A01	H40098-00 12251-POA-004 86 Ø 0,7 mm MLS 	T40100-00 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	
2,0 F20C VTEC	177 kW (240 PS) S2000	06/99→	D40094-00 ⑫ 06110-PCX-020 B77561-00 ⑬ 06111-PCX-020 	H40094-00 12251-PCX-004 88 Ø 0,65 mm MLS 		
2,0 F20C1	170 kW (231 PS) S 2000 VTEC	03/99-10/03	D40094-00 ⑫ 06110-PCX-020 B77561-00 ⑬ 06111-PCX-020 	H40094-00 12251-PCX-004 88 Ø 0,65 mm MLS 	T40100-01 90005-PCX-003 (10x) 	
2,0 F20Z1	96 kW (131 PS) ACCORD	03/93-10/98	D80970-01 ⑫ 06110-PT5-020 B54917-00 ⑬ 06111-PT1-010	H80970-00 12251-PT0-J02 86 Ø MLS 		



V38006-00 12030-POA-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	M37919-00 17105-PAA-A01 	X82306-01 18115-POA-003 	70-31414-10 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77735-01 K ← 91233-PT0-003 27x40x8 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PT0-003 28x42x8 A SL LD MVQ
V38006-00 12030-POA-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89792-01 17105-PAA-L01 	X82306-01 18115-POA-003 	70-31414-10 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77735-01 K ← 91233-PT0-003 27x40x8 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PT0-003 28x42x8 A SL LD MVQ
V38002-00 12040-PCX-305 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89782-01 17105-PCX-004 	X82301-01 18115-PCX-004 	70-31414-10 	P77562-01 K ← 91212-PCX-003 43x58x8 A SL RD FPM P77561-01 K → 91214-PCX-003 80x98x10 A SL LD MVQ
V38002-00 12040-PCX-305 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89782-01 17105-PCX-004 	X82301-01 18115-PCX-004 	70-31414-10 	P77562-01 K ← 91212-PCX-003 43x58x8 A SL RD FPM P77561-01 K → 91214-PCX-003 80x98x10 A SL LD MVQ
V38004-00 12030-PT0-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89657-01 17105-PT2-004 	X82310-01 18115-PT0-004 	X54896-01 11251-PT0-000 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77735-01 K ← 91233-PT0-003 27x40x8 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PT0-003 28x42x8 A SL LD MVQ



HONDA						
Ltr.						
2,0 F20Z2	85 kW (116 PS)	ACCORD	03/93-01/96	D80970-01 ⑫ 06110-PT5-020 B54917-00 ⑬ 06111-PT1-010	H80970-00 12251-PT0-J02 86 Ø MLS 	T40098-00 90005-PT0-003 (9x) +90006-PT0-003 (1x)
2,0 K20A1	115 kW (156 PS)	STREAM	05/01→	D40104-00 ⑫ 06110-PNA-020 B77567-00 ⑬ 06114-RBA-020 	H40104-00 12251-PNA-004 86,5 Ø 0,6 mm MLS 	T40104-00 90005-PNA-003 (10x)
2,0 R20A1 R20A2 R20A3	110-115 kW (150-156 PS)	ACCORD CR-V STEPWAGON	01/07→	D38243-00 ⑫ 06110-RNA-000 +06114-RNA-010 	H40531-00 12251-RNA-A02 MLS 	T40531-00 90005-RNA-A01 (10x)
2,0 20T2N	74-77 kW (101-105 PS)	ACCORD TDi CIVIC D CIVIC TDIC	04/96-12/02	S36055-00 ⑫ ⑬ D36055-00 ⑫ 	H03732-00 1,05 mm 1 MLS H13732-10 1,2 mm 2 MLS H23732-20 85,5 Ø 1,35 mm 3 	
2,2 F22A3 F22A7 F22A8	108-110 kW (147-150 PS)	ACCORD ASCOT	01/90-10/96	S80970-00 ⑫ ⑬ 061A1-PT3-000 +061B1-PT3-000 D80970-00 ⑫ 061A1-PT3-000	H80970-00 12251-PT0-J02 86 Ø MLS 	

⑦ junta para múltiple de admisión/de escape / Dichtung Ansaug-/Abgaskrümmer / intake/exhaust manifold gasket / joint collecteur d'admission/d'échappement / guarnizione collettore di aspirazione/di scarico / прокладка всасывающего/выпускного колена



V38004-00 12030-PT0-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89795-01 17105-PT2-014 	X82310-01 18115-PT0-004 	X54896-01 11251-PT0-000 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77735-01 K ← 91233-PT0-003 27x40x8 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PT0-003 28x42x8 A SL LD MVQ
V38008-00 12030-PNC-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89796-01 17105-PNA-J01 X89845-01 ⑩ 17055-PNA-004 	X82312-01 18115-PNA-004 ① →12/03 X82311-01 18115-PRB-A01 ① 01/04→ 	70-31414-10 	P77567-01 K ← 91212-RBD-E01 43x58x7 A SL RD ACM P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
X59333-01 12341-RNA-A01 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	M38245-00 17105-RNA-A01 (4x) +17106-RNA-A01 (1x) M38260-00 ⑩ 17103-RNA-A01 (2x) +17104-RNA-A01 (4x) 	X59334-01 18115-RNA-004 	70-31414-10 	P77720-01 K ← 91212-RNA-A01 43x58x7 A SL RD P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
X53700-01 	N90170-00	X52283-01 ⑦ 	X54457-01 NBR 	P77126-01 K ← 35x45x7 A SL RD FPM P77397-01 K → FPM	
V38004-00 12030-PT0-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89657-01 17105-PT2-004 	X82189-01 18115-PT3-A21 	X54896-01 11251-PT0-000 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PT0-003 28x42x8 A SL LD MVQ

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiamento collettore aspirazione / прокладка, корпус выпускного коллектора



HONDA						
Ltr.						
2,2 F22B5 F22B8	110 kW (150 PS) ACCORD SHUTTLE	09/93-02/98	D40098-00 ⑫ 06110-P0D-030 B54917-00 ⑬ 06111-PT1-010	H40098-00 12251-P0A-004 86 Ø 0,7 mm MLS 	T40098-00 90005-PT0-003 (9x) +90006-PT0-003 (1x)	
2,2 N22A1	103 kW (140 PS) ACCORD CTDi FR-V CTDi	01/04→	D38009-00 ⑫ →12/05 B77568-00 ⑬ 06111-RBD-E01	H01097-00 12251-RBD-E01 86 Ø 1,3 mm 1 MLS H01097-10 12252-RBD-E01 86 Ø 1,35 mm 2 MLS H01097-20 12253-RBD-E01 86 Ø 1,4 mm 0 MLS H11097-30 12254-RBD-E01 86 Ø 1,45 mm 3 MLS H11097-40 12255-RBD-E01 86 Ø 1,5 mm 4 MLS 		
2,2 N22A2	103 kW (140 PS) CIVIC CR-V CTDi	02/05→	B77568-00 ⑬ 06111-RBD-E01	H01097-00 12251-RBD-E01 86 Ø 1,3 mm 1 MLS H01097-10 12252-RBD-E01 86 Ø 1,35 mm 2 MLS H01097-20 12253-RBD-E01 86 Ø 1,4 mm 0 MLS H11097-30 12254-RBD-E01 86 Ø 1,45 mm 3 MLS H11097-40 12255-RBD-E01 86 Ø 1,5 mm 4 MLS 		

V38004-00 12030-PT0-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89791-01 17105-P0A-004 	X82306-01 18115-P0A-003 	X54896-01 11251-PT0-000 	P77602-01 N 91213-PT0-003 28x42x8 A SL LD MVQ
V38009-00 12030-RBD-E01 →12/05 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89797-01 17105-RBD-E01 	X82313-01 18115-RBD-E01 	70-31414-10 	P77567-01 K ← 91212-RBD-E01 43x58x7 A SL RD ACM P77568-01 K → 91214-RBD-E01 87x104x10 A SL LD MVQ
	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89797-01 17105-RBD-E01 	X82313-01 18115-RBD-E01 	70-31414-10 	P77567-01 K ← 91212-RBD-E01 43x58x7 A SL RD ACM P77568-01 K → 91214-RBD-E01 87x104x10 A SL LD MVQ



HONDA						
Ltr.						
2,3 F23A1	110 kW (150 PS) ACCORD	03/97-01/99	D40100-02 ⑫ 06110-PAB-A00 B37212-00 ⑬ 06111-PAA-A01	H40100-00 12251-PAA-A02 87 Ø 0,72 mm MLS 	T40100-00 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	
2,3 F23A1	113 kW (154 PS) ACCORD	01/01-06/03	D40100-02 ⑫ 06110-PAB-A00 B37212-00 ⑬ 06111-PAA-A01	H40100-00 12251-PAA-A02 87 Ø 0,72 mm MLS 	T40100-00 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	
2,3 F23A3 F23A6 F23A7 F23A8	110-118 kW (150-160 PS) ACCORD ACCORD VTI ODYSSEY SHUTTLE	10/97→	D40100-02 ⑫ 06110-PAB-A00 B37212-00 ⑬ 06111-PAA-A01	H40100-00 12251-PAA-A02 87 Ø 0,72 mm MLS 	T40100-00 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	
2,3 F23A5	100 kW (136 PS)		B37212-00 ⑬ 06111-PAA-A01	H40098-00 12251-POA-004 86 Ø 0,7 mm MLS 	T40100-00 90005-PAA-A01 (9x) +90006-PAA-A01 (1x) 	



V38006-00 12030-POA-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	M37919-00 17105-PAA-A01 →12/97 X89792-01 17105-PAA-L01 →01/98→ 	X82306-01 18115-POA-003 	70-31414-10 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77735-01 K ← 91233-PTO-003 27x40x8 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PTO-003 28x42x8 A SL LD MVQ
V38006-00 12030-POA-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X89792-01 17105-PAA-L01 	X82306-01 18115-POA-003 	70-31414-10 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77735-01 K ← 91233-PTO-003 27x40x8 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PTO-003 28x42x8 A SL LD MVQ
V38006-00 12030-POA-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	M37919-00 17105-PAA-A01 	X82306-01 18115-POA-003 	70-31414-10 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77735-01 K ← 91233-PTO-003 27x40x8 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PTO-003 28x42x8 A SL LD MVQ
V38006-00 12030-POA-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	M37919-00 17105-PAA-A01 	X82306-01 18115-POA-003 	70-31414-10 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77735-01 K ← 91233-PTO-003 27x40x8 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PTO-003 28x42x8 A SL LD MVQ



HONDA						
Ltr.						
2,3 F23Z5	11/00-06/03	113 kW (154 PS) ACCORD	1	D40100-02 ⑫ 06110-PAB-A00 B37212-00 ⑬ 06111-PAA-A01	H40100-00 12251-PAA-A02 87 Ø 0,72 mm MLS 	T40100-00 90005-PAA-A01 (9x) +90006-PAA-A01 (1x)
2,3 H23A2 H23A3	02/92-09/96	116-118 kW (158-160 PS) ACCORD PRELUDE		D40102-00 ⑫ 06110-P14-010 B54912-00 ⑬ 06111-P14-030	H40102-00 12251-P14-A02 88 Ø 0,68 mm MLS 	
2,4 K24A	02/03→	124-140 kW (168-190 PS) ACCORD CR-V ODYSSEY		D40103-00 ⑫ 06110-RBA-E01 B77567-00 ⑬ 06114-RBA-020 	H40103-00 12251-RAC-004 87 Ø 0,68 mm MLS 	
2,5 C25A1 C25A2	01/86-06/88	110-127 kW (150-173 PS) LEGEND V6		S80910-00 ⑫ ⑬ 061A1-PH7-660 +061B1-PH7-660 D80910-00 ⑫ 061A1-PH7-660	H80910-00 2x 12251-PH7-004 85 Ø 	
2,7 C27A1	10/87-12/90	124 kW (169 PS) LEGEND V6		S80911-00 ⑫ ⑬ 061A1-PL2-000 +061B1-PH7-000 D80911-00 ⑫ 061A1-PL2-000	H80911-00 2x 12251-PL2-003 88 Ø 	
3,0 J30A1	02/98-06/03	147 kW (200 PS) ACCORD VTEC ACCORD V6 24v		D40099-00 ⑫ R 06120-P8A-A13 D40099-01 ⑫ L 06110-P8A-A21 B77561-01 ⑬ 06111-P8A-A01	H40099-00 2x 12251-P8A-A01 87 Ø 0,7 mm MLS 	

⑩ junta, carcasa de colector de admisión / Dichtung Ansaugkrümmergehäuse / gasket, intake manifold housing / joint d'étanchéité, carter de collecteur d'admission / guarnizione, alloggiam. collettore aspirazione / прокладка, корпус впускного коллектора



V38006-00 12030-P0A-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	X59451-01 17105-P0A-A02 	X82306-01 18115-P0A-003 	70-31414-10 	P77594-01 K ← 91212-PAA-A02 40x52x7,1 A SL LD MVQ P77735-01 K ← 91233-PT0-003 27x40x8 A SL LD P77672-01 K → 91214-PH1-004 80x100x10 A SL RD MVQ P77602-01 N 91213-PT0-003 28x42x8 A SL LD MVQ
V38007-00 12030-PT2-000 	N93050-00 12210-PT2-004 (8x) +12211-PT2-004 (8x)	X89795-01 17105-PT2-014 X89844-01 ⑩ 17121-PT2-003 	X82310-01 18115-PT0-004 	X54912-01 11251-P0A-000 	P77602-01 N 2x 91213-PT0-003 28x42x8 A SL LD MVQ
V38008-00 12030-PNC-000 	N93047-00 12210-PZ1-004 (8x) +12211-PZ1-004 (8x)	M37920-00 17115-RAA-A01 	X82311-01 18115-PRB-A01 	70-31414-10 	P77567-01 K ← 91212-RBD-E01 43x58x7 A SL RD ACM P77526-01 K → 91214-PWA-003 80x98x10 A SL LD NBR
X83206-01 2x 12341-PH7-000 	N93007-02 12210-PD2-004 (12x) +12211-PH7-004 (12x)	X89619-01 2x 18115-PH7-003 	X82386-01 2x 17105-PH7-003 X82318-01 18212-SA0-003 	X54932-01 11251-PH7-000 	P77585-01 N 2x 91213-PH1-003 35x50x8 A SL RD NBR
X83206-01 2x 12341-PH7-000 	N93007-02 12210-PD2-004 (12x) +12211-PH7-004 (12x)	X89619-01 2x 18115-PH7-003 	X82386-01 2x 17105-PH7-003 	X54932-01 11251-PH7-000 	P77585-01 N 91213-PH1-003 35x50x8 A SL RD NBR
V38005-00 2x 12030-P8A-A00 	N93047-02 12210-PZ1-A01 (12x) +12211-PZ1-004 (12x)	M37917-00 R 17065-P8A-A01 M37918-00 L 17055-P8A-A01 X89842-01 ⑩ 17105-P8A-A01 	X82307-01 2x 18115-P8A-A01 	70-31414-10 	P77621-01 N 2x 91213-P8A-A01 39x53x8

